News Channel Update

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Recall Campaign Launch Notification		
Check Sliding Roof Bonding		
MY01-11 C-Class, CLK-Class, E-Class and CLS-	DATE: January 20, 2023	
Class		
(203, 209, 211 and 219 platform)		

IMPORTANT RECALL CAMPAIGN UPDATE

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



Recall Cam	paign Laund	ch Notification	January 20, 2023			
Campaign No. :	NHTSA ID	Campaign Desc. :				
2023010004 2023010005 2023010006	22V954	22P7891007 22P7891008 22P7891009	Check Sliding Roof Bonding			
platform), CLK-Class (209 platform), E-Class	s (211 platform) and CLS-Class	conding on <u>123,696</u> Model Year ("MY") 2001-2011 C-Class (203 (219 platform) vehicles. The recall campaign will be visible on the fected VINs were flagged in VMI as "OPEN" on January 20, 2023.			
	Background					
Issue		on certain Model Year ("MY") Class (211 platform) and Cl sunroof panel and the sliding of the bond might deteriorate of the bond would not be gual vehicle cannot be ruled out. I other road users. When the ac detached panel or excessive versions.	the manufacturer of Mercedes-Benz vehicles, has determined that 2001 – 2011 C-Class (203 platform), CLK-Class (209 platform), E-S-Class (219 platform) vehicles, the bonding between the glass roof frame might not meet specifications. In this case, the adhesion gradually over time. Therefore, the specified durability requirements ranteed. As a consequence, a separation of the glass panel from the his could increase the risk of a potential accident and/or injury for thesion begins to deteriorate, the customer might observe a partially wind noises in the area of the sunroof while driving.			
What We're Doing		MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will check the glass panel bonding on the affected vehicles and replace the sliding roof, if necessary				
Parts		The remedy is available and	I can be performed.			
		Vehicles Aff	ected			
Vehicle Model Year(s)		2001-2011				
Vehicle Model		C-Class, CLK-Class, E-Class a				
		Vehicle Popu	lations			
Total Recall Population	1	123,696				
Total Vehicles in Dealer Inventory 0		0				
notification until th Instruction	ne vehicle has been ons will be available ator vehicles may co	repaired. Once the remedy is in Star TekInfo. Once the repontinue to be driven, but mus	r lease any new vehicles in dealer inventory covered by this available, the vehicles will be flagged as "OPEN" and Work air is complete the vehicle may be sold or leased. St not be retailed until repaired. As a matter of normal service hich might be applicable to the vehicle(s).			
Additionally, given th	is notice, it is a viol	ation of Federal Law for renta until the vehicle has b	al car companies to rent vehicles covered by this notification een repaired.			
Next Steps/Notes						
Customer Notification	Timeline	Customer letters will be ma	ailed on February 3, 2023.			
AOMS/SOMS		AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.				
Rental Fleet Partners			eles in your fleet. Please contact your respective MBUSA fleet information and next steps. For repairs, please contact your			



While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Recall Campaign Bulletin



Campaign No. 2023010004, January 2023

Recall Campaign Bulletin

Recall Campaign Bulletin

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model C-Class (203 platform)

Model Year 2006

Check Sliding Roof Bonding

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2001 – 2011 C-Class (203 platform), CLK-Class (209 platform), E-Class (211 platform) and CLS-Class (219 platform) vehicles, the bonding between the glass sunroof panel and the sliding roof frame might not meet specifications. In this case, the adhesion of the bond might deteriorate gradually over time. Therefore, the specified durability requirements of the bond would not be guaranteed. As a consequence, a separation of the glass panel from the vehicle cannot be ruled out. This could increase the risk of a potential accident and/or injury for other road users. When the adhesion begins to deteriorate, the customer might observe a partially detached panel or excessive wind noises in the area of the sunroof while driving.

Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 4 vehicles are affected.

Order No. P-RC-2023010004

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Check panoramic sliding sunroof and replace, if necessary

Attention, danger: Wear safety glasses and stay clear of the area above the suction cup tool (head/face) during the check.



Figure 1




Figure 2 (Test sequence 1, 2, 3, 4 - arrow indicates direction of travel)

i If the panoramic sliding sunroof panel is detached from the padding of the sliding sunroof/ tilting roof frame at one of the test points (see Figure 3), replace the sliding sunroof panel.



Figure 3, not OK (shown here on a sliding sunroof)

- a. If the panoramic sliding sunroof panel is detached from the padding: Perform work procedure.
- b. If the panoramic sliding sunroof panel is not detached from the padding: Perform operation step 4 and end the measure.
- 4. Perform function test of panoramic sliding sunroof.
 - To do so, open and close panoramic sliding sunroof (tilt and slide positions).

Work Procedure

1. Replace panoramic sliding sunroof panel (AR77.21-P-0500PB)

Primary Parts Information

Qty.	Part Name	Part Number
As required (1)	Panoramic sliding sunroof panel model 203	A 203 780 01 21
As required (1)	Screws (repair kit)	A 203 780 02 16

Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

iNote: The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
	12-1589	Check panoramic sliding sunroof	8.0
78 910 07	12-1590	Replace panoramic sliding sunroof (after check) Includes: Perform teach-in run for automatic reversing function on panoramic sliding sunroof (XENTRY connected)	1.6

Note: Always check ASRA for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.

Special tools

Qty.	Part Name	Part Number
1	Tool kit	W 000 588 01 99 00