

# IMPORTANT SAFETY RECALL NOTICE

This notice applies to your vehicle



10101 Science Drive  
Sturtevant, Wisconsin 53177  
USA

[www.brp.com](http://www.brp.com)

**September 29, 2022**

## **Re: Front Sprocket Wear - Potential Loss of Propulsion**

Dear BRP Customer,

Following the previous notice issued in May 2022, this updated notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. BRP has decided that a defect related to motor vehicle safety exists in the following vehicles. As a result, BRP is conducting a safety recall.

**Our records show that you own a potentially affected vehicle.**

### **What is the potential problem?**

The front sprocket may be defective and may be subject to premature wear. Over time, the vehicle could lose propulsion. If the vehicle loses propulsion, there is an increased risk of a crash.

### **Which models are involved?**

Certain 2015 to 2019 Can-Am® Spyder RT and F3 vehicles

### **What should you do?**

- The final repair is to replace the front sprocket and the sprocket screw. The replacement procedure should take less than an hour.
- Due to supply chain limitations, the parts for the final repair will gradually be available in a very limited quantity over an extended time period beginning October 31.
- Contact your authorized BRP Can-Am dealer and schedule an appointment to have the safety recall performed on your vehicle.
- BRP will continue to offer an interim repair procedure. The procedure acts as a temporary solution until the parts for the final repair are available in sufficient quantity. The procedure is available at your dealer now and should take less than an hour.
- BRP will repair your vehicle at no cost.
- The wear occurs over usage time and varies between vehicles. In case of a loss of propulsion, you will maintain steering and braking functions, but you will not be able to maintain your speed. Please have your sprocket and sprocket screw replaced by your dealer, and, if you continue to ride your vehicle before the final repair, we recommend that you go to your dealer for the interim repair procedure.

- If you leased this vehicle:
  - Send a copy of this letter to the lessee within ten working days after the day you received this letter.
  - Do the same with any future letters about this safety recall.

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590, call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153) or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 22V352.

If you previously had to replace the front sprocket for this issue and BRP did not cover the cost of the repair, please contact us for reimbursement. However, your vehicle will still need to have the safety recall repair performed.

**What to do if you feel you have received this notice by mistake:**

This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information regarding your name or address are incorrect, please contact BRP at your earliest convenience.

Your safety and continued satisfaction with our products are a priority for us. We apologize for any inconvenience this may cause you and remain committed to facilitating the process as much as we can.

Thank you for your immediate attention to this matter.

Sincerely,

***BRP Customer Services Department***

**If you have questions or need assistance, or to find the nearest authorized BRP dealer:**

- Visit [www.brp.com](http://www.brp.com)
- Or call: 1-888-272-9222  
8:00 AM to 8:00 PM Eastern time 7 days a week.