



VOLUNTARY RECALL CAMPAIGN

Classification: EL22-014	Reference: NTB22-086	Date: September 28, 2022
-----------------------------	-------------------------	-----------------------------

VOLUNTARY SAFETY RECALL CAMPAIGN 2017 ROGUE; WIRE HARNESS INSPECTION

CAMPAIGN ID #: PC918
APPLIED VEHICLES: 2017 Rogue (T32)

**Check Service COMM or Dealer Business Systems (DBS)
National Service History to confirm campaign eligibility.**

INTRODUCTION

Nissan is conducting this voluntary safety recall campaign on certain specific model year 2017 Rogue vehicles, to inspect the body wire harness. This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER


Nissan has assigned identification number PC918 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

INSPECTION OVERVIEW



SERVICE PROCEDURE

Inspection

1. Remove the driver (LH) side inner front kicking plate.
 - Refer to the ESM: **BODY INTERIOR > INTERIOR > REMOVAL AND INSTALLATION > BODY SIDE TRIM > KICKING PLATE**
2. Remove the driver (LH) side dash side finisher.
 - Refer to the ESM: **BODY INTERIOR > INTERIOR > REMOVAL AND INSTALLATION > BODY SIDE TRIM > DASH SIDE FINISHER**

IMPORTANT: Do NOT disconnect the M74/B42 wire harness connector.

3. While leaving the M74/B42 wire harness connectors connected, disengage the connectors from the connector bracket by pulling in the direction shown (Figure 1).




Figure 1

4. Carefully pull the wire harness away from the body and inspect the B42 wire harness connector branch for tape that runs the full length of the wire harness branch.
 - If the tape does NOT run the full length of the wire harness branch, as shown in Figure 2, no further action is needed. Skip to step 6 on page 5 for reassembly.
 - If tape is present and runs the full length from the connector to the body wire harness, as shown in Figure 3, continue to step 5.
 - One strip of tape on the wire harness branch is OK.
 - Foam on the M74/B42 wire harness connectors is OK.



Figure 2



Figure 3

5. If tape is present on the length of the wire harness branch, as shown in Figure 3, take a clear photo and send it in an email to FQA_Inspection_support@nissan-usa.com with the following information:
 - Email Subject PC918 2017 Rogue Wire Harness
 - Dealer Code
 - VIN
 - Contact Name
 - Contact Email Address
 - Contact Phone Number

NOTE: The email and photo will serve as notification to Nissan in the event an NG condition is found. No further action is required in this case and the vehicle can be returned to the customer.

6. While leaving the M74/B42 wire harness connectors connected, engage the connectors into the connector bracket by pushing in the direction shown (Figure 4).




Figure 4

7. Reinstall the driver side dash side finisher.
 - Refer to the ESM: **BODY INTERIOR > INTERIOR > REMOVAL AND INSTALLATION > BODY SIDE TRIM > DASH SIDE FINISHER**
8. Reinstall the driver (LH) side inner front kicking plate.
 - Refer to the ESM: **BODY INTERIOR > INTERIOR > REMOVAL AND INSTALLATION > BODY SIDE TRIM > KICKING PLATE**

CLAIMS INFORMATION

Submit a “CM” line claim using the following claims coding:

CAMPAIGN (“CM”) ID	DESCRIPTION	OP CODE	FRT
PC918	Inspect wire harness branch (OK Condition)	PC9180	0.2
	Inspect wire harness branch (NG Condition, email photo)	PC9181	0.3

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
September 28, 2022	NTB22-086	Original bulletin published