



# RECALL CAMPAIGN BULLETIN

Classification:	Reference:	Date:
BT22-004	NTB22-013	February 24, 2022

## VOLUNTARY SAFETY RECALL CAMPAIGN 2022 PATHFINDER; 2<sup>ND</sup> ROW SEAT TRACK MOUNTING BOLT

**CAMPAIGN ID #:** PC867  
**APPLIED VEHICLES:** 2022 Pathfinder (R53)

**Check Service COMM or Dealer Business Systems (DBS)  
National Service History to confirm campaign eligibility.**

### INTRODUCTION

Nissan is conducting this voluntary safety recall campaign, on certain specific model year 2022 Pathfinder vehicles, to inspect and, if necessary, install up to 4 seat track mounting bolts to the 2<sup>nd</sup> row seat tracks. This service will be performed at no charge to the customer for parts or labor.

### IDENTIFICATION NUMBER

Nissan has assigned identification number PC867 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

### DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## SERVICE PROCEDURE

1. Open the rear passenger (RH) side door.
2. Depress the walk inside switch (Figure 1) and allow the 2<sup>nd</sup> row seat to move forward (Figure 2).

**NOTE:** Figure 1 and Figure 2 show a vehicle equipped with 2<sup>nd</sup> row captain's chairs. Vehicles equipped with 2<sup>nd</sup> row bench seats are similar.




Figure 1



Figure 2

3. Perform steps 1 and 2 for the driver (LH) side 2<sup>nd</sup> row seat.
4. Inspect the seat tracks behind the 2<sup>nd</sup> row seats (Figure 3).




Figure 3

5. Inspect for the presence of the four (4) seat track mounting bolts [one (1) mounting bolt per seat track, two (2) mounting bolts per seat], as shown in Figure 4.
- If **all** seat track mounting bolts are present (Figure 4), skip to step 7.
  - If any of the seat track mounting bolts are missing (Figure 5), continue to step 6 for bolt installation.




Figure 4




Figure 5

6. Install new bolt(s) from the **PARTS INFORMATION** table on page 4.
- Torque the new bolt to 45 N•m (4.5 kg-m, **33 ft-lb**).
7. Return both seats to their original positions.
8. Close both rear doors.

## PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
BOLT (1)	88921-6TA2A	4 (As Needed)

(1) Only order actual quantity of bolts needed for the repair.

## CLAIMS INFORMATION

Submit a “CM” line claim using the following claims coding:

CAMPAIGN (“CM”) ID	DESCRIPTION	OP CODE	FRT
PC867	Inspect 2 <sup>nd</sup> Row Seat Frame Mounting Bolts and, If Necessary, Install up to 4 New Bolts	PC8670	0.2

## AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
February 24, 2022	NTB22-013	Original bulletin published

