

# Newmar Corporation

PO Box 30  
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

**RSB 590**  
**November 01, 2022**

**NHTSA #22V 748**  
**TC #2022-569**

## RECALL SERVICE BULLETIN

### AFFECTED MODELS

2023 :: Dutch Star

### DESCRIPTION

The dash interferes with full extension of the brake pedal assembly.

### ISSUE

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner and Spartan Chassis.

On certain Newmar motorhomes, when the adjustable brake pedal is fully extended towards the driver, it may contact the dash panel. This can cause the brakes to partially be applied. Continuing to drive with the brakes partially applied may cause the brakes to overheat and cause a brake failure.

### UNITS AFFECTED

Please refer to the attached population list for affected units and VINs.

### CORRECTIVE ACTION

Follow the attached work instructions to trim the plastic dash panel.

### PARTS NEEDED

Item Description	Quantity	Newmar Part #
<b>SEAL FOAM SCRNR DR</b>	1 ft.	03650

FLAT RATE CODE: 22V 748

LABOR TIME: .5 hr.

### DEALER ACTION

Contact your Newmar Service Account Manager to obtain authorization and order part(s).

### CUSTOMER ACTION

Contact the Newmar brand specialist immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

**IMPORTANT:** Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.