







v: 5.0

## **Recall Service Bulletin**

RSB22-330-001

DATE: 11-3-22

This Recall service bulletin applies to 2015 through 2019 MM and K2, **APPLIES TO:** 

motor home chassis built between February 12, 2014 and December 11,

2017.

NHTSA/TC Id: 22V-776

**CONDITION:** Motor home chassis were manufactured with service brake supply

reservoirs that do not meet the 12x combined volume as defined by

**FMVSS 121.** 

Install larger capacity air reservoir **CORRECTION:** 

**LABOR ALLOCATION:** 3 hr

E3 **CLASSIFICATION:** 

**PARTS NEEDED:** 

Expires 11/2027

Description Part Number QTY

S- 2628-001 Kit-Service, Addl Air Tank Volume

Kit # S-2628-001 Contains:

| <u>QTY</u> | <u>Part Number</u> | <u>Description</u>           |
|------------|--------------------|------------------------------|
| 2          | 4403-MM5-001       | Support-Air Tank to Frame    |
| 4          | 0100-MM5-002       | Support-Air Reservoir        |
| 1          | 0219-MM5           | Air Tank 1200 Cu In          |
| 1          | 2035-MM5-031       | Lanyard-Air Res Drain Valve  |
| 1          | 0716-MM5-J05       | Bushing 8-4                  |
| 1          | 3092-MM5-A07       | Elbow 90° 6-8                |
| 1          | 3092-MM5-A02       | Elbow 90° 4-4                |
| 2          | 3092-MM5-B12       | Elbow 45° 10-8               |
| 2          | 06160650H8Y        | Bolt 3/8-16x6.50 Hex Gr8 Yel |
| 2          | 0616FLN8Y          | Nut 3/8-16 Flg Lk Gr8 Yel    |
| 2          | 06FWSAE8Y          | Washer Flat 3/8 SAE Gr8      |
| 4          | 06160125FH8Y       | Bolt 3/8-16x1.25 Hex Gr8 Yel |
| 4          | 08130150FH8Y       | Bolt 1/2-13x1.50 Flg Gr8     |
| 4          | 0813FLN8Y          | Nut 1/2-13 Flg Lk            |
| 1          | 4414-MM5           | Plumbing Diagram             |
| 1          | RSB22-330-001      | Recall Instructions          |

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.









# **Recall Service Bulletin**

RSB22-330-001

#### **GENERAL INSTRUCTIONS:**

Thoroughly review entire service bulletin before starting work. If there are questions or concerns with steps defined in this service bulletin, contact Spartan RV Chassis Customer & Product Support Group.

All applicable industry safety standards must be followed when performing work identified in this procedure.

#### **STEP-BY-STEP INSTRUCTIONS:**

- 1. Properly support chassis to gain access to work underneath.
- 2. Locate air tanks and drain all air from tanks.
- 3. Locate the wet tank located on cross member. Refer to Figure 1




Figure 1.0

- 4. Disconnect air lines from air tank.
- 5. Remove wet tank from the cross member.
- 6. Remove and retain the moisture ejector for re-use. Refer to Figure 2 Item 11
- 7. Disconnect lanyard from drain valve and discard lanyard.
- 8. Properly dispose of air tank.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.









## **Recall Service Bulletin**

RSB22-330-001

- 9. Assemble the replacement wet tank using air tank 0219-MM5 (Item 2). Refer to Figure 2.
- 10. To install fittings and drain valve apply pipe sealer with Teflon or equivalent to pipe threads only and tighten 2-3 turns from finger tight.
- 11. Install 3092-MM5-B12 (Item 5) in the end ports of the air tank. Refer to Figure 2.
- 12. Install 3092-MM5-A07 (Item 10) in top port of the air tank. Refer to Figure 2.
- 13. Install 0716-MM5-J05 (Item 3) and 3092-MM5-A02 (Item 4) in remaining top port of the air tank. Refer to Figure 2.
- 14. Install Moisture Ejector (Item 11) retained in step 6 into bottom port of the air tank. The moisture ejector must be mounted with the manual drain oriented perpendicular to the frame rail. Refer to Figure 2.
- 15. Attach new lanyard 2035-MM5-031 to manual drain valve.
- 16. Install 0100-MM5-002 (Item 1) on the air tank using 06160650H8Y (Item 7), 06FWSAE8Y (Item 9) and 0616FLN8Y (Item 8). Refer to Figure 2.




Figure 2.0

17. Drill 4 holes in the right frame rail between the last two cross members on the chassis. Refer to Figure 3 for location of the holes.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

Expires 11/2027



Expires 11/2027







# **Recall Service Bulletin**

RSB22-330-001




Figure 3.0

18. Install 4403-MM5-001 (Item 1) on frame rail using 08130150FH8Y (Item 2) and 0813FLN8Y (Item 3). Refer to figure 4




Figure 4.0

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.









# **Recall Service Bulletin**

RSB22-330-001

19. Install air tank assembly to mounting brackets on frame rail using 06160125FH8Y and then tighten the 06160650FH8Y. Refer to Figure 5.




Figure 5.0

- 20. Connect 5/8" black air line from air dryer port 21 to air tank. Refer to Figure 5.
- 21. Connect 1/4" yellow air line from governor reservoir port to air tank. Refer to Figure 5
- 22. Connect 5/8" black air line from air tank to primary air tank. Refer to Figure 5.
- 23. Connect 3/8" black air line from shop air connection to air tanks Refer to Figure 5.
- 24. Route Drain Lanyard from moisture ejector to existing 0.63" diameter hole forward of the last cross member.
- 25. Check installed air lines per plumbing diagram 4414-MM5. Fill air system and check for leaks, resolve any issues, tie wrap all loose airlines and cables to existing cable runs.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.