

April 17, 2023

Mr. Kevin White Global Quality Systems Meritor, Inc. 2135 West Maple Troy, MI 48084

Subject: Steer Axle Fasteners May Come Loose

Dear Mr. White:

This letter serves to acknowledge Meritor, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: MERITOR/FRONT DRIVE STEER AXLE/9999

Mfr's Report Date: April 11, 2023

NHTSA Campaign Number: 23E-031

Components: STEERING:CRITICAL FASTENERS

Potential Number of Units Affected: 65

Problem Description:

Meritor, Inc. (Meritor) is recalling certain front drive steer axles, models MFS and FF, with part numbers MFS20133ANK66, MFS20133ANK86, and FF961LX296. The front-drive steer axle fasteners may loosen, resulting in a complete separation of the axle assembly joints.

Consequence:

Steer axle assembly separation can result in a loss of vehicle control, increasing the risk of a crash.

Remedy:

Meritor will work with the affected manufacturers to inspect and replace the pro-torque nut keeper on the steer axle assembly, free of charge. Owners may contact Meritor customer service at 1-866-668-7221.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107MR 23E-031

Please ensure the following requirements are met:

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Meritor, Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alae Andry

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

