

Part 573 Safety Recall Report

23V-066

Manufacturer Name : Navistar, Inc.**Submission Date :** MAR 09, 2023**NHTSA Recall No. :** 23V-066**Manufacturer Recall No. :** 23502**Manufacturer Information :**

Manufacturer Name : Navistar, Inc.

Address : 2701 Navistar Drive
Lisle IL 60532

Company phone : 331-332-1590

Population :

Number of potentially involved : 115

Estimated percentage with defect : 90 %

Vehicle Information :

Vehicle 1 : 2022-2023 IC Bus CE CB

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information :

- The suspect population is identified by all models built within the suspect build dates.
- The suspect build dates were determined by measurements made to multiple buses and manufactured in multiple months and years until buses were determined to have roof sheet joints within specification.
- The buses in the suspect population were built within the suspect build dates and all other models not subject to this Non-compliance were built outside of the suspect build dates. There are 46 CE commercial buses in the suspect population.

Production Dates : SEP 01, 2021 - DEC 15, 2022

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 2 : 2022-2023 IC Bus RE CB

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information :

- The suspect population is identified by all models built within the suspect build dates.
- The suspect build dates were determined by measurements made to multiple buses and manufactured in multiple months and years until buses were determined to have roof sheet joints within specification.
- The buses in the suspect population were built within the suspect build dates and all other models not subject to this Non-compliance were built outside of the suspect build dates. There are 69 RE commercial buses in the suspect population.

Production Dates : SEP 16, 2021 - NOV 03, 2022

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : One or more joints that connect the roof top sheets may not have been properly secured to the roof bow supports.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of an accident involving the roof of the bus, roof top sheets may separate and not protect the occupants sufficiently, increasing the risk of possible injury or death.

Description of the Cause : A machine that is not forming the roof bow supports correctly is currently under investigation for root cause.

Identification of Any Warning that can Occur : Water leaks into the passenger compartment of the bus may occur.

Involved Components :

Component Name 1 : Roof Bow

Component Description : Roof Bow created in manufacturing process.

Component Part Number : NPN

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

- 01/19/2023 – Navistar Manufacturing initiated an investigation of a leaking roof at water test and noticed insufficient overlap of the roof sheeting.
- 01/19/2023 and 01/20/2023 – Navistar Manufacturing audits the processes from bow former through topping sheet installation.
- 01/24/2023 – Navistar Manufacturing quarantines buses at the assembly plant and contains the issue in manufacturing.
- 1/25/2023 When testing compliance to FMVSS 221, Navistar pull tests of three suspect roof joints did not meet the 6,241 pound pull test requirement. Joints separated at 5,645 and 5,026 pounds.

- 01/31/2023 – Navistar Manufacturing meets with Compliance to review pull test results and initiate investigation to determine the impact to IC buses.
- 02/02/2023 – Navistar determines the suspect population and declares a Non Compliance recall.
- 03/02/2023 – Navistar reclassifies 23502 to a safety recall based on determination by Navistar Compliance and Certification Compliance that FMVSS 221 and CMVSS 221 apply to school bus only.

Description of Remedy :

| | |
|--|--|
| Description of Remedy Program : | <ul style="list-style-type: none"> • The remedy will involve measuring the rivet location for each joint and if they are not within specification, 24 screws will be added to the rear row of rivets to all joints that are out of specification. • Navistar's plan for reimbursement of pre-notification remedies, on file with NHTSA and dated 05/06/2022, applies and reimbursement instructions will be included in the customer notification. |
| How Remedy Component Differs from Recalled Component : | Buses built during this time frame; the bow bender was not forming the roof bows correctly. Buses built prior to this time; the bow bender was producing bows that were formed correctly. |
| Identify How/When Recall Condition was Corrected in Production : | 01/23/2023 – Navistar Manufacturing hand oil mists the raw material prior to installation into the roof bow forming machine and rotates the roof bow 180-degrees during installation to the bus chassis which positions the roof bow back into the topping sheet instead of away from the topping sheet. |

Recall Schedule :

| | |
|------------------------------------|---|
| Description of Recall Schedule : | It is estimated that the Customer and Dealer notification letters will be mailed by 04/03/2023. |
| Planned Dealer Notification Date : | APR 03, 2023 - APR 03, 2023 |
| Planned Owner Notification Date : | APR 03, 2023 - APR 03, 2023 |

* NR - Not Reported