

Part 573 Safety Recall Report

23V-148

Manufacturer Name : Terex Advance Mixer, Inc.**Submission Date :** MAR 07, 2023**NHTSA Recall No. :** 23V-148**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Terex Advance Mixer, Inc.

Address : 7727 Freedom Way

Fort Wayne IN 46818

Company phone : 999

Population :

Number of potentially involved : 20

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2022-2022 Front Discharge Mixer Commander

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Meritor contacted Terex Advance Mixer and informed them that 20 MX-23810 Axles, that were shipped to Terex, had a defect. Meritor provided all of the affected axle serial numbers and Terex determined what vehicles those axles were installed on.

Production Dates : JAN 18, 2022 - DEC 05, 2022

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Meritor MX-23810 axles may contain bolted joints that are suspect to improperly torqued fasteners at the steer arms, king pin caps, caliper to knuckle, and tie rod castle nuts. A improperly torqued fastener may become loose.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Loss of vehicle control or property damage could result from the loosening of a fastener, particularly if the vehicle has multiple fasteners affected by the condition.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Meritor, Inc

Address : 22021 Skyway Church Rd.
Maxton North Carolina 28364

Country : United States

Chronology :

Mar. 2, 2023 - Terex Advance Mixer and Meritor had a conference call where Meritor shared that 20 axles that were shipped to Terex Advance Mixer had a defect.

Mar. 7, 2023 - After internal discussions and analysis of the Meritor information, Terex Advance Mixer deemed this condition to be safety related. Therefore, a 573 defect report was initiated.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported