Part 573 Safety Recall Report

Manufacturer Name :	Navistar, Inc.
Submission Date :	MAY 24, 2023
NHTSA Recall No. :	23V-171
Manufacturer Recall No. :	23508

Manufacturer Information :

Manufacturer Name : Navistar, Inc. Address : 2701 Navistar Drive Lisle IL 60532 Company phone : 331-332-1590

Vehicle Information :

Vehicle 1:	2023-2023 Inter	rnational HV			
Vehicle Type :	BUSES, MEDIUM	I & HEAVY VEH	ICLES		
Body Style :	OTHER				
Power Train :	DIESEL				
Descriptive Information :	04GBN – (Electr • The inclu feature code 000	onic Park Brake usive dates of m 04GBN. Icles in the susp ot built with this	e) for Ti anufact ect pop s featur		er Applications. Ill vehicles built with
Production Dates :	JUN 24, 2022 - JI	JN 27, 2022			
VIN Range 1:	Begin :	NR	End :	NR	Not sequential
	DIESEL	I & HEAVY VEH		ified by models equipped	with feature code
 04GBN - (Electronic Park Brake) for Tractor or Truck with Trailer Applications. The inclusive dates of manufacture were determined by all vehicles built with feature code 0004GBN. The vehicles in the suspect population were built with 0004GBN and all other vehicles were not built with this feature code. There are 8 HX series trucks in the suspect population. 					
	MAV 92 9099	AUG 08 2022			
Production Dates :	MAI 23, 2022 - 1	100 00, 2022			



Number of potentially involved :

Estimated percentage with defect : 2 %

Population :

24

23V-171

Part 573 Safety Recall Report

Vehicle Type	. 2023-2023 Int	ternational Lon	eStar		
J 1	: BUSES, MEDIU				
Body Style :					
Power Train					
escriptive Information	04GBN - (Elec • The ind feature code 0 • The ve vehicles were 2 There is one (1)	tronic Park Bra clusive dates of 004GBN. hicles in the su not built with t 1) LoneStar ser	ike) for Tr `manufac spect pop his featur ies trucks	ractor or Truck ture were deter ulation were b e code.	s equipped with feature code with Trailer Applications. rmined by all vehicles built wit uilt with 0004GBN and all othe population
VIN Range 1		NR	End :	NR	Not sequential
vii viunge 1			Linu .		
			EHICLES		
	The inc feature code 0 The ve vehicles were	clusive dates of 004GBN.	`manufac spect pop his featur	ture were deter ulation were b e code.	with Trailer Applications. rmined by all vehicles built wit uilt with 0004GBN and all othe
Production Dates	: MAY 18, 2022	- AUG 05, 2022			
VIN Range 1	Begin :	NR	End :	NR	Not sequential
	DIESEL DIESEL O4GBN – (Elec The ind feature code 0	JM & HEAVY VE spect populatic tronic Park Bra clusive dates of 004GBN.	on is ident ike) for Tr `manufac spect pop	ractor or Truck ture were deter sulation were b	s equipped with feature code with Trailer Applications. rmined by all vehicles built wit uilt with 0004GBN and all othe
	vehicles were	not built with t			
Production Dates	vehicles were There are 4 RH	not built with t H series trucks i			1

The information contained in this report was submitted pursuant to 49 CFR §573

23V-171

Page 3

Description of Defect :

Description of the Defect :	As reported in Bendix's recall 23E-015; The Intellipark Tractor Park Valve Module (PVM) may intermittently become stuck in the un-parked position and may not transition from un-parked to parked when the Park Switch is pulled on the vehicle dashboard.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	AS reported in Bendix's recall 23E-015; An Intellipark PVM that intermittently becomes stuck in the un-parked position does not allow the vehicle spring brakes to exhaust when the driver pulls the Park Switch. The vehicle must be parked by depleting air storage by fanning-down the air brake system with the service brake pedal. If a driver does detect the Intellipark PVM malfunction indications and does not properly fan down the brakes, the vehicle may unintentionally move which increases the likelihood of a crash.
Description of the Cause :	• As reported in Bendix recall 23E-015; Mechanical components in the PVM that are at the upper limit of the design specification and other tolerance stack-ups allow for excessive internal air leakage. The internal leakage does not allow pressure to build properly when the pilot solenoid is activated.
	As reported in Bendix recall 23E-015; Park Indication LEDs on the park switch remain off after the Park Switch is pulled indicating that the spring brake system has not exhausted and the vehicle is not parked. Audible exhaust sounds that are typically heard as an air-braked vehicle is parked, will not be heard indicating that the vehicle has not parked. The vehicle manufactures have implemented dash display indications and alerts indicating that the vehicle has not parked in response to pulling the Park Switch.

Involved Components :

Component Name 1:	Park Valve Module (PVM)
Component Description :	Intellipark Tractor/Truck Towing variant Park Valve Module (PVM)
Component Part Number :	Bendix P/N S-1696

Supplier Identification :

Component Manufacturer

Name : Bendix Commercial Vehicle Systems, LLC

Address: 35500 Chester Rd

The information contained in this report was submitted pursuant to 49 CFR §573

Avon Ohio 44011 Country : United States

Chronology :

• 02/17/2023 – Navistar receives communication from Bendix that they have filed a defect report with NHTSA related to the Intellipark PVM for Towing vehicles.

- 02/20/2023 Navistar Engineering and Product Compliance initiate an investigation to determine the possible vehicle level impact to International products.
- 02/27/2023 Navistar Engineering and Bendix meet to determine root cause investigation.
- 03/02/2023 Navistar completes warranty analysis and found no instances of failure to park occurring with Navistar vehicles.
- 03/6/2023 Engineering and Product Compliance finalize their investigation and the suspect population.
- 03/09/2023 Navistar declares a Safety Recall.

Description of Remedy :

Description of Remedy Program :	 Navistar Engineering is validating the Bendix remedy on it's International brand trucks and will update Navistar's remedy when validation is completed and determines remedy. Navistar's plan for reimbursement of pre-notification remedies, on file with NHTSA and dated 05/06/2022, applies and reimbursement instructions will be included in the customer notification. An Interim notice will be mailed to affected customers advising them of the concern and the actions they should take when applying the park brake until a final remedy is developed.
How Remedy Component Differs from Recalled Component :	As reported in Bendix recall 23E-015; this is to be determined once root cause is known
dentify How/When Recall Condition was Corrected in Production :	

Recall Schedule :

Description of Recall Schedule :	It is estimated that the Customer and Dealer notification letters will be
	mailed by 05/15/2023.
Planned Dealer Notification Date :	MAY 15, 2023 - MAY 15, 2023
Planned Owner Notification Date :	MAY 15, 2023 - MAY 15, 2023

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573