OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-178

Manufacturer Name: Mercedes-Benz USA, LLC

Submission Date: APR 26, 2023 **NHTSA Recall No.:** 23V-178 **Manufacturer Recall No.:** 2023040011



Manufacturer Information:

Manufacturer Name: Mercedes-Benz USA, LLC

Address: 13470 International Parkway

Jacksonville FL 32218

Company phone: 1-877-496-3691

Population:

Number of potentially involved: 70,225 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2022-2023 Mercedes-Benz GLE 350

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Mercedes-Benz 2022-2023 GLE 32,127 vehicles The recall population was

determined through production records. Vehicles outside of the recall population

have the mounting of the rear door trim according to current production

specifications.

Production Dates: JAN 29, 2022 - FEB 14, 2023

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2022-2023 Mercedes-Benz GLE 450

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Mercedes-Benz 2022-2023 GLE 6,049 vehicles The recall population was determined

through production records. Vehicles outside of the recall population have the mounting of the rear door trim according to current production specifications.

Production Dates: JAN 22, 2022 - FEB 14, 2023

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 3:	2022-2023 Mer	cedes-Benz GL	E 580				
Vehicle Type :	LIGHT VEHICLE	S					
Body Style :							
Power Train :							
Descriptive Information :	Mercedes-Benz	2022-2023 GL	E 247 ve	ehicles The recall populati	on was determined		
The second second	through production records. Vehicles outside of the recall population have the mounting of the rear door trim according to current production specifications.						
Production Dates:	JAN 29, 2021 - F	EB 14, 2023					
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential		
Vehicle 4:	2022-2023 Mercedes-Benz GLS 450						
V 1	LIGHT VEHICLES						
Body Style :							
Power Train :	GAS						
Descriptive Information :							
	determined through production records. Vehicles outside of the recall population						
	have the mounting of the rear door trim according to current production						
	specifications.	TED 14 0000					
Production Dates:			ъ 1	ND	□ N		
VIN Range 1:	Begin:	NR	End:	NK	☐ Not sequential		
Vehicle 5:	2022-2023 Mer	cedes-Benz GL	S 580				
	LIGHT VEHICLES						
Body Style :							
Power Train :							
		2022-2023 GI	S 548 ve	hicles The recall nonulati	on was determined		
Descriptive information.	Mercedes-Benz 2022-2023 GLS 548 vehicles The recall population was determined through production records. Vehicles outside of the recall population have the						
				ing to current production			
Production Dates:	JAN 29, 2022 - F	EB 14, 2023					
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential		
** 1. 1. 0		1 2 16		V. G. O. O.			
	2022-2023 Mer		ybach G	aLS 600			
	LIGHT VEHICLE	S					
Body Style :							
Power Train :	GAS						
Descriptive Information :							
				outside of the recall popul			
Dec I de De	_		accord	ing to current production	specifications.		
Production Dates: JAN 29, 2022 - FEB 14, 2023 VIN Range 1: Begin: NR End: NR Not sequential							
VIN Range 1:	begin:	NR	Ena:	INK	☐ Not sequential		

	Mercedes-Benz 2022-2023 AMG GLE 11,053 vehicles The recall population was determined through production records. Vehicles outside of the recall population have the mounting of the rear door trim according to current production specifications.						
Production Dates : VIN Range 1 :		EB 14, 2023 NR	End: NR	☐ Not sequential			
Vehicle Type : Body Style : Power Train :							
Production Dates : VIN Range 1 :		TEB 14, 2023 NR	End: NR	☐ Not sequential			
Vehicle 9: 2022-2023 Mercedes-Benz AMG GLS 63 Vehicle Type: LIGHT VEHICLES Body Style: SUV Power Train: GAS Descriptive Information: Mercedes-Benz 2022-2023 AMG GLS 852 vehicles The recall population was determined through production records. Vehicles outside of the recall population have the mounting of the rear door trim according to current production specifications.							
Production Dates : VIN Range 1 :	JAN 29, 2022 - F	TEB 14, 2023 NR	End: NR	☐ Not sequential			
Description of Defect :							

Description of the Defect: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has

determined that on certain Model Year ("MY") 2022-2023 GLE and GLS (167, X167 platform) vehicles, the fastening of the rear door window trim bars might

not meet current production specifications.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Under certain driving conditions the trim bar might separate from the vehicle

Description of the Safety Risk: while driving. This might pose a risk of injury for other road users and

increase the risk of a crash.

Description of the Cause: Due to a deviation in the assembly process, the trim bars on the rear door

windows might not be fastened in accordance with current production

specifications.

Identification of Any Warning The driver will not receive a warning due to the nature of the failure

that can Occur: mechanism.

Involved Components:

Component Name 1: Side Window Pane **Component Description: Side Window Pane** Component Part Number: A1677301108

Component Name 2: Side Window Pane Component Description: Side Window Pane Component Part Number: A1677301308

Component Name 3: Side Window Pane **Component Description: Side Window Pane** Component Part Number: A1677300507

Component Name 4: Side Window Pane **Component Description: Side Window Pane** Component Part Number: A1677301208

Component Name 5: Side Window Pane Component Description: Side Window Pane Component Part Number: A1677301408

Component Name 6 : Side Window Pane
Component Description : Side Window Pane
Component Part Number : A1677300707

Component Name 7: Side Window Pane
Component Description: Side Window Pane
Component Part Number: A1677300607

Component Name 8 : Side Window Pane
Component Description : Side Window Pane
Component Part Number : A1677300807

Supplier Identification:

Component Manufacturer

Name: AGC Automotive Americas Co. Address: 34505 W. 12 Mile Road Suite 300

Farmington Hills Florida 48331

Country: United States

Chronology:

In March 2021, MBAG began an initial investigation of field reports from GLE and GLS vehicles describing trim bars that were loose or had detached from a vehicle during driving. These subject vehicles were outside of the prior recall measures 22V680.

In September 2022, during the course of its worldwide product monitoring, MBAG identified isolated field reports from the US of trim bars that were loose or had detached from a vehicle during driving. MBAG immediately began to investigate these field reports and the corresponding vehicle production records. Additionally, MBAG undertook a thorough review of the history of each vehicle identified in the field reports, including any plant rework, prior recall or workshop visits that involved issues in the affected area. MBAG completed these analyses in late 2022. The results were inconclusive in determining a failure mechanism. MBAG continued its investigation and launched an additional review of the production and its rework processes related to the trim bar on GLE and GLS vehicles.

In January 2023, MBAG conducted an analysis to identify potentially affected vehicles and determined that no specific GLE and GLS vehicles could be excluded.

Out of an abundance of caution, in early 2023, MBAG introduced a change in the process used to connect the

trim bar to the vehicle in production, designed to eliminate potential incorrect installation of the trim bars. On March 10, 2023, MBAG determined that a potential safety risk cannot be ruled out and decided to extend the recall population.

MBAG is currently aware of 11 claims related to this phenomenon (including warranty claims, field reports, and service reports) received in the US from February 2, 2022 to March 10, 2023. MBAG is not aware of any claims of crashes, injuries, or other third party damage as a result of this occurrence.

Description of Remedy:

Description of Remedy Program: An authorized Mercedes-Benz dealer will check the installation of the trim

bars on the rear door windows and rework them, if necessary.

Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since none of the involved vehicles would have been previously subject to the condition described

and all remain covered under the new vehicle warranty.

How Remedy Component Differs Side window pane installed according to current production specification.

from Recalled Component: Side Window Pane

A1677301108

A1677301308

A1677301208

A1677301408

A1677300507

A1677300707

A1677300607

A1677300807

Identify How/When Recall Condition A change in the production ensures that this issue can no longer occur

was Corrected in Production: from February 15, 2023 onwards.

Recall Schedule:

Description of Recall Schedule: Dealers will be notified of the pending voluntary recall campaign on

March 24, 2023. Owners will be notified of the voluntary recall campaign

before May 16, 2023. A copy of all communications will be provided

when available.

Planned Dealer Notification Date: MAR 24, 2023 - NR Planned Owner Notification Date: MAY 05, 2023 - NR

* NR - Not Reported