#### OMB Control No.: 2127-0004

Not sequential

# Part 573 Safety Recall Report

## 23V-238

**Manufacturer Name:** Daimler Trucks North America, LLC

Submission Date: APR 20, 2023 NHTSA Recall No.: 23V-238 Manufacturer Recall No.: FL970



#### **Manufacturer Information:**

Manufacturer Name: Daimler Trucks North America, LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

### **Population:**

Number of potentially involved: 306 Estimated percentage with defect: 1 %

#### **Vehicle Information:**

Vehicle 1: 2023-2023 Freightliner 114SD

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: Suspect population of front steering axles without production torque data and photo

evidence of cotter pin in-place following rework operations, suspect vehicles built

within the listed production date ranges.

Production Dates: JAN 26, 2022 - SEP 15, 2022

VIN Range 1 : Begin : NR End : NR

Vehicle 2: 2023-2023 Freightliner M2 106

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: Suspect population of front steering axles without production torque data and photo

evidence of cotter pin in-place following rework operations, suspect vehicles built

within the listed production date ranges.

Production Dates: JAN 26, 2022 - SEP 27, 2022

				NER C2		
•	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
Production Dates :	APR 04, 2022 - A	APR 04, 2022				
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential	
Vehicle Type : Body Style : Power Train :	DIESEL	I & HEAVY VEH	ICLES		ustion torque data and photo	
-	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
<b>Production Dates:</b>	FEB 04, 2022 - F	EB 04, 2022				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
				S2RV Chassis		
	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
<b>Production Dates:</b>	JAN 27, 2022 - A	UG 03, 2022				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
Vehicle Type : Body Style :	<ul> <li>: 2022-2023 Freightliner Custom Chass MT50E</li> <li>: BUSES, MEDIUM &amp; HEAVY VEHICLES</li> <li>: VAN</li> <li>: HYBRID ELECTRIC</li> </ul>					
Descriptive Information :	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
Production Dates: APR 27, 2022 - MAY 31, 2022						
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	

		0			
•	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.				
Production Dates :	,				
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential
Vehicle Type : Body Style : Power Train :	DIESEL	1 & HEAVY VEH			
	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.				
Production Dates :					
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential
			ICLES		
Descriptive Information :	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.				
Production Dates :					
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential
			ICLES		
•	ion: Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.				
Production Dates :			_		
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential

Vehicle 11:	2023-2023 Wes	tern Star 49X				
Vehicle Type :	BUSES, MEDIUM	1 & HEAVY VEH	ICLES			
Body Style :						
Power Train :	DIESEL					
Descriptive Information :	Suspect populat	ion of front stee	ering ax	les without pr	oduction torque data and photo	
•	evidence of cott	er pin in-place i	followir	ig rework oper	rations, suspect vehicles built	
	within the listed	l production da	te range	es.		
<b>Production Dates:</b>	FEB 01, 2022 - J	UL 13, 2022				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
	2022-2022 Freig	_		MT45G		
<b>J</b> 1	BUSES, MEDIUM	1 & HEAVY VEH	ICLES			
Body Style :						
Power Train:				_		
<b>Descriptive Information :</b>			_	-	oduction torque data and photo	
					rations, suspect vehicles built	
Dood out on Date of	within the listed production date ranges.					
Production Dates:			End.	ND	□ Not acquential	
VIN Range 1:	begin:	NR	End:	INK	☐ Not sequential	
Vehicle 13:	2023-2023 Frei	ghtliner 108SD				
	BUSES, MEDIUM	_	ICLES			
Body Style :						
Power Train:						
Descriptive Information :	Suspect populat	ion of front stee	ering ax	les without pr	oduction torque data and photo	
					rations, suspect vehicles built	
	within the listed	l production da	te range	es.	-	
<b>Production Dates:</b>	FEB 22, 2022 - A	APR 12, 2022				
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential	
	: 2022-2023 Freightliner Custom Chass MT55					
V -	BUSES, MEDIUM & HEAVY VEHICLES					
Body Style :						
Power Train :						
Descriptive Information :					oduction torque data and photo	
	within the listed				rations, suspect vehicles built	
Production Dates :		•	ie range			
VIN Range 1:		NR	End:	NR	☐ Not sequential	
viivitalige 1.	Degin .	1410	Liiu .	1110	Not sequential	

Vehicle 15:	2023-2023 Freightliner Custom Chass XCM Chassis						
		BUSES, MEDIUM & HEAVY VEHICLES					
Body Style :							
Power Train :							
Descriptive Information :	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.						
Production Dates :	FEB 02, 2022 - A	UG 22, 2022					
VIN Range 1:	Begin:	NR	End: NI	R	☐ Not sequential		
Vehicle 16:	Vehicle 16: 2023-2023 Freightliner Custom Chass XCR Chassis						
· -		BUSES, MEDIUM & HEAVY VEHICLES					
Body Style :		OTHER					
Power Train :	DIESEL						
Descriptive Information :	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.						
Production Dates:	: FEB 25, 2022 - MAY 23, 2022						
VIN Range 1:	Begin:	NR	End: NI	R	■ Not sequential		
Vehicle Type : Body Style :	Vehicle 17: 2023-2023 Freightliner Custom Chass XCS Chassis Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES Body Style: OTHER Power Train: DIESEL						
Descriptive Information :	: Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.						
Production Dates:	JAN 22, 2022 - M	IAR 09, 2022					
VIN Range 1:	Begin:	NR	End: NI	R	■ Not sequential		
Description of Defect :							

Description of the Defect: On the affected vehicles, front steer axle tie rod castle nut cotter pin may be

missing from the assembly.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: On the affected vehicles, the steer axle tie rod castle nut cotter-pin may be

missing. This may result in the castle nut backing off and displacement of the

taper-end from the steering arm. This may result in a loss of steering response and lack of direction control increasing the risk of crash.

Description of the Cause: Re-worked at a different station due to certain requirements, and was not

manufactured through standard process involving multiple inspection points.

Identification of Any Warning Driver may experience some additional free-play in the steering and/or feel an that can Occur: improper steering alignment.

#### **Involved Components:**

Component Name 1: Front Steer Axle

Component Description: Tie rod castle nut cotter-pin

Component Part Number: F2-Model 2, F3-Model 3 and F5-Model 5 front steer axles

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: Detroit Diesel Corp Address: 13400 Outer Dr W

Detroit Michigan 48239

**Country: United States** 

#### **Chronology:**

Mid-February 2023, DTNA received a report on an incident involving failed tie rod assembly and opened a preliminary investigation. Upon returned failed part analysis, it was determined that the driver's side tie rod disengaged from the steering arm during low speed maneuvering. Around late February 2023 through early March 2023, DTNA identified that the subject vehicle experiencing the failure, was re-worked at a different station due to certain requirements, and was not manufactured through standard process involving multiple inspection points. In about mid-March 2023, DTNA identified a population of certain axles, that were manufactured at a

rework station. DTNA opened an official investigation immediately following receiving this notice of a possible presence of a defect, and on March 29, 2023, out of an abundance of caution, DTNA decided to initiate a new voluntary safety recall to campaign all the listed vehicles. As of March 31st 2023, DTNA is aware of 1 field report and 0 warranty claims related to missing front steer axle tie rod castle nut cotter pin. DTNA is not aware of any accidents or injuries due to this defect condition. On April 7 2023, DTNA finalized the affected population after further determining precise vocational application of the vehicles.

#### **Description of Remedy:**

Description of Remedy Program: DTNA is preparing remedy and is currently under development. Repairs

will be performed free of charge by Daimler Truck North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter. Owners are directed to seek

reimbursement through authorized dealer.

How Remedy Component Differs Presence of required cotter-pin

from Recalled Component:

Identify How/When Recall Condition 2/23/2023: 2 Quality Alerts Posted: Red Tag required 100% at first was Corrected in Production: station on production line with NOK (Not Okay) operations, and Rework

Alert.

#### **Recall Schedule:**

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : JUN 04, 2023 - JUN 04, 2023 Planned Owner Notification Date : JUN 04, 2023 - JUN 04, 2023

\* NR - Not Reported