OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

23V-238

Manufacturer Name: Daimler Trucks North America, LLC

NHTSA Recall No.: 23V-238

Manufacturer Recall No.: FL970



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America, LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved: 354 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2023-2023 Freightliner 114SD

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: Suspect population of front steering axles without production torque data and photo

evidence of cotter pin in-place following rework operations, suspect vehicles built

within the listed production date ranges.

Production Dates: JAN 26, 2022 - SEP 15, 2022

VIN Range 1 : Begin : NR End : NR

Vehicle 2: 2023-2023 Freightliner M2 106

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: Suspect population of front steering axles without production torque data and photo

evidence of cotter pin in-place following rework operations, suspect vehicles built

within the listed production date ranges.

Production Dates: JAN 20, 2022 - SEP 27, 2022

		o .				
•	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
Production Dates :	,					
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
Vehicle Type : Body Style : Power Train :	DIESEL	I & HEAVY VEH		1 21 . 1		
	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
Production Dates :						
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
Descriptive Information :	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
Production Dates :					_	
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
			IICLES			
•	tion: Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.					
Production Dates:			-			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	

Vehicle 7:	2023-2023 Wes	stern Star 49X					
Vehicle Type :							
Body Style :							
Power Train :							
Descriptive Information :	Suspect popular	tion of front ste	ering ax	des without pro	duction torque data and photo		
	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built						
	within the listed production date ranges.						
Production Dates:	FEB 01, 2022 - SEP 09, 2022						
VIN Range 1:							
Vehicle 8:	2022-2022 Frei	ghtliner Custor	n Chass	MT45G			
Vehicle Type :	BUSES, MEDIUN	A & HEAVY VEH	HICLES				
Body Style :	VAN						
Power Train :	GAS						
Descriptive Information :	Suspect population of front steering axles without production torque data and photo						
	evidence of cotter pin in-place following rework operations, suspect vehicles built						
	within the listed	d production da	ite range	es.			
Production Dates :	JAN 13, 2022 - OCT 14, 2022						
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential		
Wildele O.	0000 0000 E	alatina a Casta	Cl	MTCOE			
	2022-2023 Freightliner Custom Chass MT50E						
V -	BUSES, MEDIUM & HEAVY VEHICLES						
Body Style :							
	HYBRID ELECT		_				
Descriptive Information :	Suspect population of front steering axles without production torque data and photo						
	evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.						
Production Dates :		_	ite range				
		NR	End:	ND	□ Not cognontial		
VIN Range 1:	Degiii.	NK	Ena .	INIC	☐ Not sequential		
Vehicle 10:	2022-2023 Frei	ghtliner Custor	n Chass	S2RV Chassis			
	BUSES, MEDIUN	O .					
Body Style :							
Power Train :							
		tion of front sta	oring av	des without pro	duction torque data and photo		
Descriptive information.			_	-	ations, suspect vehicles built		
	within the listed			_	, ,		
Production Dates :		_	J				
VIN Range 1:		NR	End:	NR	☐ Not sequential		
-					_		

Vehicle 11:	2022-2022 Freightliner Custom Chass S2c 106						
	BUSES, MEDIU						
Body Style :							
Power Train :							
Descriptive Information :	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.						
Production Dates :	FEB 04, 2022 - FEB 04, 2022						
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
	2023-2024 Thomas Built Bus B2 106						
V 1	BUSES, MEDIUM & HEAVY VEHICLES						
Body Style :							
Power Train :							
•	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.						
Production Dates :							
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
				NER C2			
Descriptive Information :	Suspect population of front steering axles without production torque data and photo evidence of cotter pin in-place following rework operations, suspect vehicles built within the listed production date ranges.						
Production Dates:	MAR 02, 2022	-OCT 28, 20	22				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
Description of Defect :							
D 1 1 0 1 D 0	. 0 .1 .00		.	1	1 .1		

Description of the Defect: On the affected vehicles, front steer axle tie rod castle nut cotter pin may be

missing from the assembly.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The steer axle tie rod castle nut cotter-pin on the affected vehicles may be

missing. This may cause the castle nut to back off, which might allow taperend to displace from the steering arm. This could lead to a loss of steering response and a lack of direction control, potentially increasing the risk of a

crash.

Description of the Cause: Re-worked at a different station due to certain requirements, and was not

manufactured through standard process involving multiple inspection points.

Identification of Any Warning Driver may experience some additional free-play in the steering and/or feel an

that can Occur: improper steering alignment

Involved Components:

Component Name 1: Front Steer Axle

Component Description: Tie rod castle nut cotter-pin

Component Part Number: F2-Model 2, F3-Model 3 and F5-Model 5 front steer axles

Supplier Identification:

Component Manufacturer

Name: Detroit Diesel Corp Address: 13400 Outer Dr W

Detroit Michigan 48239

Country: United States

Chronology:

Mid-February 2023, DTNA received a report on an incident involving failed tie rod assembly and opened a preliminary investigation. Upon returned failed part analysis, it was determined that the driver's side tie rod disengaged from the steering arm during low speed maneuvering. Around late February 2023 through early March 2023, DTNA identified that the subject vehicle experiencing the failure, was re-worked at a different station due to certain requirements, and was not manufactured through standard process involving multiple inspection points. In about mid-March 2023, DTNA identified a population of certain axles, that were manufactured at a rework station. DTNA opened an official investigation immediately following receiving this notice of a possible presence of a defect, and on March 29, 2023, out of an abundance of caution, DTNA decided to initiate a new voluntary safety recall to campaign all the listed vehicles. As of March 31st 2023, DTNA is aware of 1 field report and 0 warranty claims related to missing front steer axle tie rod castle nut cotter pin. DTNA is not aware of any accidents or injuries due to this defect condition.

Description of Remedy:

Description of Remedy Program: DTNA is preparing remedy and is currently under development. Repairs

will be performed free of charge by Daimler Truck North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter. Owners are directed to seek

reimbursement through authorized dealer.

How Remedy Component Differs Presence of required cotter-pin

from Recalled Component :

Identify How/When Recall Condition 2/23/2023: 2 Quality Alerts Posted: Red Tag required 100% at first was Corrected in Production: station on production line with NOK (Not Okay) operations, and Rework

Alert.

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: MAY 23, 2023 - MAY 23, 2023 Planned Owner Notification Date: MAY 23, 2023 - MAY 23, 2023

* NR - Not Reported