# Part 573 Safety Recall Report

<b>REV Recreation Group</b>
MAY 18, 2023
23V-351
230516REV

## Manufacturer Information :

Manufacturer Name :	<b>REV Recreation Group</b>
Address :	1031 U.S. 224 E
	P.O. Box 31 Decatur IN 46733
Company phone :	800 509 3417

## Vehicle Information :

Vehicle 1:	2020-2024 Fleet	wood Bounder	•		
Vehicle Type :	LOW VOLUME V	EHICLES			
Body Style :	OTHER				
Power Train :	GAS				
Descriptive Information :	Lippert Compon Southwind/Vaca	ents, Inc. for a s itioner C, K, GL,	specific   P mode	ned based upon a change hitch (B37-0006) used o els. The Lippert designed previous hitch was produ	on the Bounder/ hitch was
<b>Production Dates :</b>	OCT 24, 2019 - M	IAY 05, 2023			
VIN Range 1:	Begin :	NR	End:	NR	Not sequential
Vehicle 2:	2020-2024 Holic	lay Rambler Va	acatione	r	
	LOW VOLUME V OTHER	·	acatione	r	
Vehicle Type : Body Style :	LOW VOLUME V OTHER GAS The campaign po Lippert Compon Southwind/Vaca	EHICLES opulation was o ents, Inc. for a s itioner C, K, GL,	letermir specific ] , P mode		on the Bounder/ hitch was
Vehicle Type : Body Style : Power Train :	LOW VOLUME V OTHER GAS The campaign po Lippert Compon Southwind/Vaca implemented on manufacturer.	EHICLES opulation was o ents, Inc. for a s ationer C, K, GL, October 1, 201	letermir specific ] , P mode	ned based upon a change hitch (B37-0006) used o els. The Lippert designed	on the Bounder/ hitch was



Number of potentially involved : 1,186 Estimated percentage with defect : 90 %

**Population :** 

## 23V-351

23V-351

• •	Vehicle Type : LOW VOLUME VEHICLES Body Style : OTHER Power Train : GAS				
Descriptive Information :	Lippert Co Southwine	omponents, Inc. d/Vacationer C, ited on October	for a specific K, GL, P mode	hitch (B37-00 els. The Lipper	n a change of suppliers to 06) used on the Bounder/ t designed hitch was was produced by a different
Production Dates :					
VIN Range 1:	Begin :	NR	End :	NR	Not sequentia
<b>Description of Defect :</b>	ot · Tho I;	nnart taur hitah	racaivar or a	ortain DEV Day	creation Group gas motor
Description of the Dele	homes afterm use rel	s may become d narket appliance	amaged when es such as a dr iy increase lev	under stress l op hitch or by	by consumer added overloading of the RV. These s on the hitch and/or cause
	1: NR				
	2: NR				
Description of the Safety Ris	from t	he hitch cross to which could pro	ube resulting	in separation o	ion of the hitch to separate of the tow vehicle from the g in property damage and/
Description of the Cau	from in attach impact damag	mpact with the ments which m t could increase ge on the botton	ground or lev ay increase th the risk of da 1 side of the d	erage from cus e stresses on t mage to the hi rop hitch, fract	caused by stress on the hitch stomer added drop hitch he hitch receiver. Repeated itch. Failed parts analyzed had tured surface of the hitch f the top support plate.
Identification of Any Warn that can Occu	0	fractures may b	e present duri	ng inspection.	
nvolved Components :					

## Part 573 Safety Recall Report

Component Name 1 : Tow Hitch Receiver Component Description : Tow Hitch Receiver

Component Part Number : B37-0006

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : Lippert Address : Po Box 2888 Elkhart Indiana 46515 Country : United States

#### Chronology :

In May of 2023, REV Recreation Group notified Lippert that a risk to safety may occur on certain Lippert manufactured hitches and that REV Recreation Group would immediately conduct a recall out of an abundance of caution on behalf of the hitch supplier.

• In July 2022, REV Recreation Group received notification that a Lippert manufactured hitch had welds that broke while in use. A review of warranty history revealed no other reported failures of this part as of this time.

• In November 2022, REV Recreation Group received notice of a second reported failure of this hitch. The parts were returned to Lippert, the hitch manufacturer and it was determined that in each case involving a reported hitch failure, an approximate 6" customer added drop hitch was being utilized to facilitate flat towing of an SUV.

• December 2022, REV Recreation Group conducted a follow up meeting with Lippert and the assessment at that point indicated the failures were potentially related to use of aftermarket equipment contacting the ground during use or by stress added by leverage by consumer added drop hitches.

• Dec 2022 and ongoing, REV Recreation Group and Lippert started an investigation and reviewed testing data to determine the effect of consumers adding an aftermarket drop hitch.

• April 3, 2023 - A customer with REV Recreation Group gas motor home reported their Lippert hitch welds had a failure. Field data now shows that there are a total of 5 similar reports with the specific subject part number. Further evaluations were conducted and remain underway.

REV leadership and engineers met and discussed the specifications of the units with the failure and concluded that their safety committees should consider a campaign to replace the specific hitch with a redesigned, more robust part in the interest of customer safety.

#### **Description of Remedy :**

Description of Remedy Program :	Lippert has developed a new hitch design with specifications that are improved to reduce the stress created by consumer added drop hitches per FEA analysis. REV Recreation Group approved the hitches and started installing them effective April 7, 2023. Technicians will be provided technical instructions by REV RV to inspect and replace the hitch.
	The remedy component has been validated and tested by Lippert and REV Recreation Group engineering for additional strength.
	The recall condition was corrected in production in April 2023 when a more robust hitch design was received.

### **Recall Schedule :**

Description of Recall Schedule :	Dealer notification will be conducted via email, and owner notification
Planned Dealer Notification Date :	will be conducted via US Mail. JUL 12, 2023 - JUL 12, 2023
Planned Owner Notification Date :	JUL 15, 2023 <sup>-</sup> JUL 15, 2023

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573