

Part 573 Safety Recall Report

23V-393

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** JUN 01, 2023**NHTSA Recall No. :** 23V-393**Manufacturer Recall No. :** N798**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 29,861

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

Mahwah NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2017-2020 LAND ROVER DISCOVERY

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2017-2020MY Land Rover Discovery vehicles built at the Solihull Vehicle Assembly Plant from September 22, 2016, - January 31, 2019, and at the Nitra Vehicle Assembly Plant from September 21, 2018, - February 13, 2020 . 29,861 vehicles in the United States and Federalized Territories. The basis of the recall population is from the start of production, up to the point a change to the affected component was introduced.

Production Dates : SEP 22, 2016 - FEB 13, 2020

VIN Range 1 : Begin : SALRHBBV9HA000128 End : SALRR2RV3KA096624

 Not sequential

VIN Range 2 : Begin : SALRT2RK7K2400037 End : SALRU2RV2L2437411

 Not sequential**Description of Defect :**

Description of the Defect : A concern has been identified on certain 2017 to 2020 Model Year Land Rover Discovery vehicles where customers have reported a rear passenger door is unlatched when in the closed position and no reported indication provided of an unlatched condition on the instrument cluster. Some customers have reported that a rear passenger door has opened while the vehicle was in motion.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Rear passenger doors not latched may during driving, open. This can increase the risk of a vehicle crash or compromise the safety of vehicle occupants.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : Keyless Entry/Start - Passive, Double Locking Powe

Component Description : Keyless Entry/Start - Passive, Double Locking Power Lock Latch

Component Part Number : HY32 24994 EA

Component Name 2 : Keyless Entry/Start - Passive, Double Locking Powe

Component Description : Keyless Entry/Start - Passive, Double Locking Power Lock Latch

Component Part Number : HY32 24995 EA

Supplier Identification :

Component Manufacturer

Name : Brose CZ

Address : máje 2636
Rožnov pod Radhoštěm Foreign States 75661

Country : Czech Republic

Chronology :

See File "Recall N798 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to a Land Rover approved dealer who will complete the required repair to disable the Unilatch Keyless Vehicle (KV) entry function on the vehicle. There will be no charge to owners for this repair. Customers who have paid for a repair of this defect will be reimbursed by the Jaguar Land Rover reimbursement plan, subject to the usual terms and conditions.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Notifications to dealers will occur on June 15, 2023. Distribution of owner notification letters will occur on or before July 28, 2023.

Planned Dealer Notification Date : JUN 15, 2023 - JUN 15, 2023

Planned Owner Notification Date : JUL 28, 2023 - JUL 28, 2023

* NR - Not Reported