Part 573 Safety Recall Report

Manufacturer Name :	Ford Motor Company
Submission Date :	SEP 13, 2023
NHTSA Recall No. :	23V-440
Manufacturer Recall No. :	23S33

Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

Population :

Number of potentially involved : 14,452 Estimated percentage with defect : 100 %

云 🔨 🔁

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

23V-440

Vehicle Information :

Vehicle 1:			
	2019-2020 Ford Fusion		
Vehicle Type : 1	LIGHT VEHICLES		
Body Style :			
Power Train : 1	NR		
-	Affected vehicles were produced between 12/06/17 and 07/27/20 and are equipped with the 2.0L PHEV drivetrain and 30Ah high voltage batteries.		
t J	These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.		
Production Dates : DEC 06, 2017 - JUL 27, 2020			
VIN Range 1 : Begin : NR End : NR			
Description of Defect :			
Description of the Defect	t : Current Interrupt Device (CID) activation in a high voltage battery cell can result in excess voltage and current flow through the Battery Energy Control Module (BECM), which can cause damage to the BECM.		
Description of the Defect FMVSS 1	result in excess voltage and current flow through the Battery Energy Control Module (BECM), which can cause damage to the BECM.		
·	result in excess voltage and current flow through the Battery Energy Control Module (BECM), which can cause damage to the BECM.1 : NR		
- FMVSS 1 FMVSS 2	result in excess voltage and current flow through the Battery Energy Control Module (BECM), which can cause damage to the BECM.1 : NR		

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Page 2

develop when the battery has multiple charge and discharge cycles per day, charging to and storage at 100% State of Charge (SOC), and/or battery has aged and been in service at least two years.
 Identification of Any Warning that can Occur :

Involved Components :

Component Name 1:	High Voltage Battery
Component Description :	High Voltage Battery Assembly
Component Part Number :	KG98-10B759-B*

Supplier Identification :

Component Manufacturer

Name :PANASONIC AUTOMTOIVE SYSTEMS COMPANYAddress :194-4 TOKONABECHOU
KASAI CITY Foreign States 675-2332Country :Japan

Chronology:

On 6/17/2022, Ford's Trend and Early Warning Support (TEWS) team informed the Critical Concern Review Group (CCRG) of five reports of fire allegations that occurred in the trunk area on 2019 Fusion PHEV vehicles in North America equipped with 30Ah high voltage (HV) batteries. All of the incidents occurred between March and May 2022. The fires occurred while the vehicles were at dealerships during a replacement Battery Energy Control Module (BECM) service to remedy one or more voltage sense Diagnostic Trouble Codes (DTCs), a check engine light, no start, or loss of motive power concern. Analysis of the vehicles by Ford's High Voltage Battery Systems Team identified the fires originated in the BECM. The HV batteries were sent to the supplier for analysis. The supplier confirmed the Current Interrupt Device (CID) was activated in HV battery cells from the suspect units, but the root cause of the CID activation is unknown. On 8/16/2022, Ford's CCRG placed the investigation on monitor based on the rate and severity of the concern. On 2/8/2023, a Technical Service Bulletin (TSB) was published providing direction to replace the HV battery if vehicles came in for service with one or more voltage sense DTCs rather than only replacing the BECM. On 5/2/2023, the issue returned to CCRG for review. Two additional fires occurred during the monitor period, both while a customer was driving the vehicle. At that time, the CCRG was aware of seven fires and 270 warranty claims resulting in a loss of motive power as a result of this concern. On 6/16/2023, Ford's Field Review Committee (FRC) reviewed the concern and approved a field action. From June to August 2023, Ford worked with suppliers to understand root cause of the CID activation. On 8/25/2023, Ford's FRC approved an updated remedy associated with the 23S33 field

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

action based on increased understanding of the issues root cause. Ford is not aware of any accidents or injuries as a result of this concern. Description of Remedy :		
	As an interim remedy, when parts are available, owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have a BECM fuse block installed and have the BECM software reflashed to disable charging. There will be no charge for this service.	
	Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2023.	
	Ford will forward a copy of the notification letters to dealers to the agency when available.	
	The BECM fuse block KG98-10D811-AA will provide circuit protection in the event of a CID activation. The replacement battery KG98-10B759-CA will not be subject to excessive gas generation when installed in conjunction with the updated BECM software which reduces the maximum state of charge by 11%.	
Identify How/When Recall Condition was Corrected in Production :	NR	
Recall Schedule :		
Description of Recall Schedule :	Notification to dealers is expected to occur on September 8, 2023. Mailing of owner notification letters is expected to begin October 27, 2023 and is expected to be completed by November 17, 2023.	
Planned Dealer Notification Date : Planned Owner Notification Date :	SEP 08, 2023 - SEP 08, 2023	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573