

Part 573 Safety Recall Report

23V-663

Manufacturer Name : Winnebago Industries, Inc.**Submission Date :** JAN 04, 2024**NHTSA Recall No. :** 23V-663**Manufacturer Recall No. :** 178**Manufacturer Information :****Population :****Manufacturer Name :** Winnebago Industries, Inc.**Number of potentially involved :** 4,968**Address :** PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436**Estimated percentage with defect :** 100 %**Company phone :** 1-641-585-3535**Vehicle Information :****Vehicle 1 :** 2020-2024 Winnebago Revel**Vehicle Type :****Body Style :****Power Train :** NR**Descriptive Information :** The recall population was determined by identifying all Winnebago Revel motorhomes with a lithium house power system.**Production Dates :** DEC 20, 2019 - SEP 25, 2023**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential**Description of Defect :****Description of the Defect :** Cables in the area of lithium batteries may come into contact with hold down brackets, becoming damaged and resulting in a short circuit.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** A short circuit can result in a thermal incident.**Description of the Cause :** Improper routing and retention of current carrying cables.**Identification of Any Warning that can Occur :** No warning can be identified that precedes failure.**Involved Components :**

Component Name 1 : Harness-Anderson, 36 Inch

Component Description : Harness-Anderson, 36 Inch

Component Part Number : 000242259A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On or about 07/16/2023 NHTSA ODI provided Winnebago with a customer complaint regarding a worn electrical cable. An investigation was subsequently initiated based on this complaint.

On or about 08/16/2023 Winnebago was made aware of a field incident where an electrical cable had been worn or chaffed and created a short circuit which resulted in a fire which was contained by the customer. An investigation of the incident found worn cables in contact with the battery hold down bracket as the cause of the short circuit. A further review of production routing and all available data was conducted.

On 9/28/2023 the Product Safety Committee reviewed all available information and determined the issue presented an unreasonable risk to motor vehicle safety and a recall was initiated.

Winnebago is aware of 5 incidents potentially related to this condition, the first wear incident occurred on or about January 2022.

Winnebago is not aware of any injuries as a result of this issue.

Description of Remedy :

Description of Remedy Program : The remedy to correct this recall condition is to reroute and add securement of the cables.

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component :	The remedy component will have proper routing, securement and protection of the cable.
Identify How/When Recall Condition was Corrected in Production :	Hold notice #1142 was issued to contain unshipped product and provide updated work instructions to manufacturing.

Recall Schedule :

Description of Recall Schedule :	The recall schedule will follow the 60 day requirement.
Planned Dealer Notification Date :	OCT 13, 2023 - OCT 13, 2023
Planned Owner Notification Date :	DEC 28, 2023 - DEC 28, 2023

* NR - Not Reported