



ADMINISTRATION BULLETIN - SAFETY RELATED RECALL

Global Recall
Action
Number: N780

Subject: Turbocharger Oil Return Pipe Gasket - Install	Publication No.: N780
	Model: Range Rover (LK)
	Model Year: 2023
	Date of Issue: 13 April 2023

To:	Jaguar Land Rover North America, LLC.
For the Attention of:	The approved Jaguar Land Rover (JLR) retailer/authorized repairer.

FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:

National Highway Traffic Safety Administration (NHTSA) reference number: **23V-222**

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer/authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.

REGULATORY INFORMATION

Jaguar Land Rover North America, LLC have informed the National Highway Traffic Safety Administration (NHTSA) of their intent to perform a Safety Recall on certain 2023 Range Rover vehicles imported into the United States markets. Information relating to this Safety Recall will be posted on the NHTSA website.

This Safety Recall Administration Bulletin serves as notification to all retailers in United States markets that any new affected vehicles may not be sold and delivered for customer use until the Safety Recall repair is completed. Violation of this requirement by a retailer/authorized repairer could result in a maximum civil penalty of up to the equivalent of \$26,315.00 USD per violation and the equivalent of \$131,564,183.00 USD for a related series of violations.

DESCRIPTION OF ISSUE AND THE EFFECT ON VEHICLE OPERATION

A concern has been identified on 4.4L V8-cylinder Gasoline Engines, fitted to Land Rover Range Rover vehicles where a gasket has been miss-fitted or is missing from the Turbocharger oil drain pipe. A miss-fitted or missing gasket from a Turbocharger oil drain pipe may result in an oil leak. Leaked oil can come into contact with the exhaust manifold, which may lead to a fire in the Engine compartment.

OWNER NOTIFICATION

Initial owner notification is expected to occur on or before 26th May 2023.

ACTION TO BE TAKEN

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

This Recall affects the following single Vehicle Identification Number (VIN) SALKP9E72PA035831 with R0145 - Land Rover Portland, as the Responsible Retailer.

Retailers/authorized repairers are required to Quarantine affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already with customers should be updated at the next available opportunity. JLR North America recommends that affected sales demonstrator and loaner vehicles are repaired before use and that used vehicles are repaired before sale. Retailers/authorized repairers who choose to proceed against this recommendation, where legally permitted, must clearly and conspicuously disclose the open recall to the applicable customers.

The Recall repair procedures and any required parts and/or software are not currently available. A Recall repair campaign will be published when all repair procedures and all required parts and/or software are available.

Retailers/authorized repairers are reminded that they must not sell vehicles identified as affected by this campaign until such time as the repair has been successfully completed.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director