Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Senior Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Recall Campaign Launch Notification		
Inspect Rear Seat Belt Buckle Bolts	DATE: July 14, 2023	
MY22-23 EQS (297 platform)		

IMPORTANT RECALL CAMPAIGN UPDATE

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Senior Manager, Vehicle Compliance & Analysis

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company



News Channel Update Vehicle Compliance & Analysis

Recall Cam	July 14, 2023				
Campaign No. :	NHTSA ID	Campaign Desc. :	Increat Dear Seat Polt Puelde Polte		
2023070009	23V464	23P9290014	Inspect Rear Seat Belt Buckle Bolts		
This is to notify you of the Recall Campaign Launch to inspect the rear seat belt buckle bolts on <u>6</u> Model Year ("MY") 2022-2023 EQS (297 platform) vehicles. The recall campaign will be visible on the <u>www.NHTSA.gov</u> website and may generate questions from customers. Affected VINs will be flagged in VMI as "OPEN" on July 14, 2023.					
Background					
Issue		Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2022-2023 EQS (297 platform) vehicles, the bolts that secure the rear seat belt buckles to the body might not meet current torque specifications. In this case, the bolts might loosen due to vibrations while driving, or in the event of a crash. As a result, the restraining effect of the rear seat belts might be impaired, which could increase the risk of injury for vehicle occupants.			
What We're Doing			ary recall. An authorized Mercedes-Benz dealer will inspect the rear affected vehicles and rework the bolts, if necessary.		
Parts		The remedy is available and	-		
		Vehicles Aff	ected		
Vehicle Model Year(s)		2022-2023			
Vehicle Model		EQS			
		Vehicle Popu	lations		
Total Recall Population	1	6			
Total Vehicles in Deale	r Inventory	1			
Given this notice, it is a violation of Federal law for a dealer to sell or lease any new vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Once the remedy is available, the vehicles will be flagged as "OPEN" and Work Instructions will be available in NetStar VMI and Xentry Portal. Once the repair is complete the vehicle may be sold or leased.					
			at not be retailed until repaired. As a matter of normal service hich might be applicable to the vehicle(s).		
Additionally, given this notice, it is a violation of Federal Law for car rental companies to rent new vehicles covered by this notification until the vehicle has been repaired.					
Next Steps/Notes					
Customer Notification	Timeline	Customer letters will be ma	ailed on or before July 28, 2023.		
AOMS/SOMS		AOMs – This recall may gen your dealers ASAP.	nerate questions from your dealers. Please forward this notice to		
Rental Fleet Partners		representative for further in preferred MBUSA dealer.	les in your fleet. Please contact your respective MBUSA fleet nformation and next steps. For repairs, please contact your		
Customer Reimbursem	lent	Customer reimbursement i	s not being offered for this campaign.		
			o maintain a high level of vehicle quality and customer satisfaction. ssistance Center at 1-800-FOR-MERCEDES.		

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company



Recall Campaign Bulletin



Campaign No. 2023070009, July 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model EQS (297 platform) Model Year 2022-2023

Inspect Rear Seat Belt Buckle Bolts

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2022-2023 EQS (297 platform) vehicles, the bolts that secure the rear seat belt buckles to the body might not meet current torque specifications. In this case, the bolts might loosen due to vibrations while driving, or in the event of a crash. As a result, the restraining effect of the rear seat belts might be impaired, which could increase the risk of injury for vehicle occupants. An authorized Mercedes-Benz dealer will inspect the rear seat belt buckle bolts on the affected vehicles and rework the bolts, if necessary.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 6 vehicles are affected.

Order No. P-RC-2023070009

Recall Campaign Bulletin

Recall Campaign Bulletin

Inspect Rear Seat Belt Buckle Bolts

Work Procedure

- Remove rear seat cushion padding.

 For basic data, see AR91.12-P-1022EQS.
- 2. Check the torque (1 35) of both bolts on the right and left of the rear seat belt buckles (A and B, Figure 1) and correct if necessary.




Figure 1

3. Assemble in reverse order.

Note: The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage	Operation	Description	Labor Time
Code	Number		(hrs.)
92 900 14	12-1768	Check torque of the rear seat belt buckles, correct if necessary	0.3

Note: Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.

2