

RECALL CAMPAIGN

CR5374E

REFERENCE:	Nova Bus Manuals
SECTION:	09: Engine and Cooling
RS N°:	_
EFFECTIVE IN PROD.:	LE84 (2023JA)
TC RECALL Nº:	_
NHTSA RECALL Nº:	23V054

APPLICATION DEADLINES: N/A
CLAIM REFERENCE NUMBER: SR5374

SUBJECT:	Power Steering Hydraulic Hose
JUSTIFICATION:	Certain power steering hoses manufactured by a certain manufacturer during a certain time period may have not been assembled properly. This may cause a power steering assist lost.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
	DESCRIPTION	LABOUR	MATERIAL	IIIVIE
1	Replace the hydraulic hoses N95735-32, N95740-37, N95740-52 and N95841-01.	Nova Bus	Nova Bus	2h30
2	_	_	_	_

MATERIAL REQUIRED PER VEHICLE

QTY	PART N°	REV.	DESCRIPTION			
LEVEL 1						
1	N95735-32	_	HOSE WITH GUARD			
1	N95740-37	В	HOSE HYD HI-PAC WIRE BRAID			
1	N95740-52	Α	HOSE HYD PWR STEERING ASSY			
1	N95841-01	_	HOSE ASSY HI-PAC WIRE BAND			
2	N37749	В	DUAL CLAMP TIE			
LEVEL 1 - SHOP SUPPLY						
3 Li	HYDRAULIC OIL		A MAXIMUM OF 3 LITERS OF HYDRAULIC OIL WILL BE REFUNDABLE UPON CLAIM.			
LEVEL 2						
_	_	_	_			

Materials will be available within 35 days once your order has been placed.

To order, please contact novabus.parts@volvo.com

Or by phone for CANADA 1-800-771-6682, for USA 1-877-999-8808

Specify document number, quantity of parts required and shipping address.

DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED *	RETAINED	* Dispose of the unused parts and the defective parts	
	Yes	_	accordance with local environmental standards in effect.	

REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2023MR06	Initial release	Annie St-Jacques

APPROVED BY: PAGE 1 OF 9

NQF705003 VERSION 5

CLIENT	OBDER	ROAD	IUMBER	VIN (2NVY/4RKY)		ОТУ
CLIENT	ORDER	FROM	то	FROM	то	QTY
Chicago Transit Authority - CTA - Illinois	LE87	8461	8463	L82J5N97786	L82J5N97786	3





FOLLOW YOUR INTERNAL SAFETY PROCEDURES.

PROCEDURE

- 1.1. Park the vehicle on an even surface with the transmission on neutral.
- 1.2. Apply the parking brake and set the master control switch to the *stop* position.
- 1.3. Set the battery disconnect switch in the battery compartment to the off position.

DRAIN HYDRAULIC OIL



Refer to the maintenance manual, section 09: Engine and Cooling, for HYDRAULIC OIL DRAIN PROCEDURE.

- 1.4. Open the rear engine access door. Locate the hydraulic reservoir and place a clean container to recover the oil (Figure 1).
- 1.5. Drain the oil. Keep the oil, it will be reused to fill the reservoir after the work has been completed.
- 1.6. Open the right front access door, locate the drain plug on the 90 deg fitting and place a clean container under it (Figure 2).
- 1.7. Remove plug and drain the remaining oil from the pipe. Keep the oil, it will be reused to fill the reservoir after the work has been completed.



Figure 1 - Place Container to Collect Hydraulic Oil






Figure 2 - Place Container to Collect Remaining Hydraulic Oil

REPLACE HYDRAULIC HOSE N95740-37

1.8. At the rear of the vehicle, remove the RH lamp support panel and the RH rear end corner (Figure 3).




Figure 3 - Remove RH Lamp Support and Rear end Corner



Locate hydraulic pipe N95740-37 (Figure 4).




Figure 4 - Replace Hydraulic Hose N95740-37

- 1.10. Remove any dual clamps securing the hose (note their position for reinstallation).
- 1.11. Disconnect the hose N95740-37 and remove from the vehicle.
- 1.12. Install the new hose N95740-37 in place and tighten both fittings to the torque value of 48 ±2 lb-ft (65 ±3 N·m).



NOTE

Refer to the maintenance manual, section 99: General Practices, for ORS-TYPE AND SAE 37°-JIC-TYPE FITTING INSTALLATION.

1.13. Secure the new hose with new dual clamp ties N37749, replacing the ones removed at step 1.10.

REPLACE HYDRAULIC HOSES N95735-32 AND N95841-01

1.14. Raise the vehicle.



CAUTION

For information on hoisting and towing of the vehicle, see section 18: HOISTING AND TOWING IN the Nova Bus maintenance manual. Use appropriate hoisting equipment for your protection and to prevent damage to the vehicle.



- 1.15. Remove the dust pan shown in Figure 5.
- 1.16. Locate the hydraulic hose N95735-32 between the hydraulic pump and the hydraulic oil filter and the hydraulic hose N95841-01 between the hydraulic pump and the hydraulic oil reservoir (Figure 6).
- 1.17. Remove the two P-clamps securing the two hoses. Keep the P-clamps and the hardware for later reinstallation.
- 1.18. Disconnect the two hoses and remove from the vehicle.




Figure 5 - Remove Dust Pan




Figure 6 - Location of Hydraulic Hoses N95735-32 and N95841-01



- 1.19. Install the new hose N95735-32 between the hydraulic pump and the hydraulic oil filter. Tighten by hand. Install the new hose N95841-01 between the hydraulic pump and the hydraulic oil reservoir. Tighten by hand. Tighten to the torque values shown in Figure 7.
- 1.20. Reinstall the two P-clamps with the hardware removed at step 1.17. Apply medium thread locker or equivalent on screw.




Figure 7 - Replace Hydraulic Hoses N95735-32 and N95841-01

REPLACE HYDRAULIC HOSE N95740-52

- 1.21. Remove the dust pan shown in Figure 8.
- 1.22. Locate the hydraulic hose N95740-52, it is the shorter of the 2 hydraulic hose (Figure 9).
- 1.23. Remove the 3 double clamps. Keep double clamps and the hardware for later reinstallation.
- 1.24. Disconnect the hose N95740-52 and remove from the vehicle.
- 1.25. Install the new hose N95740-52 and tighten both fittings to the torque value of 48 ±2 lb-ft (65 ±3 N·m).
- 1.26. Reinstall the 3 double clamps with the hardware removed at step 1.23. Torque at the torque value of 9 lb-ft (12 N·m) and apply torque seal.




Figure 8 - Remove Dust Pan




Figure 9 - Replace Hydraulic Hose N95740-52

REFILL HYDRAULIC RESERVOIR

1.27. Fill the hydraulic oil reservoir to the required level.



Refer to the maintenance manual, section 09: Engine and Cooling, for HYDRAULIC OIL FILLING PROCEDURE.



CHECK FOR LEAKS

1.28. Start the vehicle and turn the steering wheel back and forth.

Figure 1 - Inspect hoses N95735-32, N95740-37, N95740-52 and N95841-01 connections to ensure there are no leaks.

1.29. Stop the engine.

CLEAN AND CLOSE

- 1.30. Clean any excess oil.
- 1.31. Reinstall the removed dust pans.
- 1.32. Lower the vehicle.
- 1.33. Reinstall the RH lamp support panel the RH rear end corner.
- 1.34. The vehicle can return in service. ❖