

[2/24/2026 - Updated information regarding SST Tools](#)

PLEASE READ - All Mazda Dealers:

If you have any questions about this Repair Procedure or the Scan Tool, please fill out Dealer Recall Help on OneMazda

On all CX-30 vehicles, you must use the Repair Calculator for recall 5823D available in MGSS. The requirements to complete the inspection of this repair are below:

1. Review the video links in this repair procedure showing how to use the Scan Tool.
2. A working, Windows laptop with Microsoft Excel or Google Sheets.
3. The SST Scan Tool sent to Mazda dealers

Safety Recall 5823D – 2022-2023 CX-30 and 2023 CX-50 Brake Pedal Travel May Increase

A. VEHICLE INSPECTION PROCEDURE – AND PREPARE FOR REPAIR

1. Verify that the vehicle is within the following ranges and there is a Not Launched or OPEN 5823D recall in eMDCS:

SUBJECT VEHICLES


Model	Subject VIN range	Subject production date range
2022-2023 CX-30	3MVDMBDL* NM 459744 – 459745 3MVDM**** PM 514284 – 519945	From November 28, 2022 through December 15, 2022
2023 CX-50	7MMVA**** PN 128031 – 128823	From December 3, 2022 through December 7, 2022

The asterisk symbol "*" can be any letter or number.

- If the vehicle is one of the above listed ranges and 5823D is OPEN or Not Launched in eMDCS, proceed to Step 2. If the vehicle **does not** have an OPEN or Not Launched 5823D campaign, return vehicle to the customer or inventory.

2. Perform an eMDCS Warranty Vehicle Inquiry and inspect the vehicle for a Campaign Label with **5823D** attached to the vehicle's hood, driver door or firewall.

NOTE: Be sure to verify the campaign number as the vehicle may have multiple campaign labels.



eMDCS - Warranty Vehicle Inquiry Results:

If eMDCS displays:	Campaign Label is:	Action to perform:
If no repair date is displayed on the line with CAMPAIGN 5823D, it has not been completed on this vehicle	Present	Fill out Dealer Recall Help on OneMazda contact or the Mazda Warranty Department at warrantydept@mazdausa.com to review vehicle history.
	Not present	Proceed to "REPAIR PROCEDURE".
If repair date is displayed for CAMPAIGN 5823D is "CLOSED"	Present	Return vehicle to inventory or customer.
	Not present	Complete a label and apply to vehicle's hood with repair date and dealer code from eMDCS Warranty Inquiry.
CAMPAIGN 5823D is not displayed	See Action	The vehicle is not affected by Recall 5823D

REPAIR OUTLINE

CX-30 Vehicles: The repair is to inspect the serial number with the provided SST Scan Tool, then determine if the vehicle needs repair.

CX-50 vehicles: The repair is to replace the DSC HCU (ABS HCU) Module on all 9 affected vehicles.

GENERAL CAUTIONS/WARNINGS – PLEASE READ:



Air Bag Connectors and Battery Disconnect: Do not work on the vehicle without disconnecting the vehicle battery as this could result in damage to the vehicle or safety systems.

Customer Personal Items: If personal belongings need to be removed from vehicle interior trunk area or inside, please remember to neatly replace any customer items in the same location after the repair is completed.

Damage to interior or exterior: Care should be taken, and protective cover(s) used when working on any Mazda vehicle. Damage to any components, interior trim, body panels and paint will not be reimbursed by Mazda.

All of these items above could delay repairs, compromise safety, as well as negatively affect the customer experience and Mazda dealer-customer relationship.

B. REPAIR PROCEDURE – CX-50 ONLY *(As of launch all the CX-50 vehicles in 5823D campaign have been repaired):*

1. Follow the steps in MGSS to replace the ABS HCU unit on the vehicle. [CX-50 ABS HCU \(DSC HU/CM\) REMOVAL AND REPLACEMENT](#)
2. Move to Section D "CAMPAIGN LABEL INSTALLATION to attach a completed campaign label to the vehicle firewall, driver door jamb or radiator crossmember.

C. REPAIR PROCEDURE – CX-30 ONLY

REQUIRED TOOL INFORMATION

NOTE: If your USB Scan Tool does not work or you have a question about this procedure please contact Dealer Recall Help on OneMazda. If your question is technical in nature, please watch the video on using the tool and contact Tech Hotline if more assistance is needed.

No.	Part Names (CX-30 vehicles ONLY)	SCANNER - SST Tool Models
①	Laptop with Windows 7, 10, or 11 with Microsoft Excel or Google Sheets	ALLOWABLE SST ONLY – must be stored in your tool shed TERA 1100D EYOYO-015P Do not use this tool: FYOYO-009P if you received this tool take a photo showing the model number and fill out Dealer Recall Help ASAP and we will replace this tool.
②	USB SST Scan Tool with the supplied cable (do not use the USB Dongle for connection) ONE OF 3 MODELS	

Use the Scan Tool with the black cable only, please do not use the “Bluetooth” dongle in the SST Scan Tool box as it does not work (red X in the box photo).



EY-015P. ONLY USE THE USB CABLE. DO NOT USE THE USB DONGLE TO SCAN



SST Tool NOTE:


LOST or MISPLACED SST TOOLS: If you are a Mazda dealer who was active on 5/8/2023 and later (including buy-sells that took over service) you will need to purchase the Tera 1100D tool from Amazon or an reputable online retailer as all tools were provided once, free of charge in May 2023: [Click here for the Amazon link to a Tera 1100D new tool](#)

NON-WORKING EXISTING TOOL: If your tool is not working or malfunctioning, Please fill out Dealer Recall Help on OneMazda with a photo of the tool, and describe in detail your issue. Then based on the response we will advise if a new tool is needed.


NEW DEALERS (NOT BUY-SELL) ACTIVE AFTER JUNE 2023: If you are a brand new Mazda dealer and need this tool, please fill out Dealer Recall Help for a loaner tool. A tool will be sent with a return UPS label to return the tool.

A working Windows laptop and Microsoft Excel or Google Sheets is required for this repair.

1. Obtain the SST Scan Tool from your Tool Shed and a Windows Laptop, with Microsoft Excel or Google Sheets installed.
2. Disconnect the vehicle battery cable following the procedure in MGSS. [NEGATIVE BATTERY DISCONNECT](#)
3. **With the laptop computer Open the Repair Calculator from MGSS in Excel or Google Sheets.** Enable all MACROS if needed. [Click Here for a tutorial on how to install and use Google Sheets.](#) [This document is also available on MGSS under the 5823D recall.](#)
 - a. In the Calculator, Excel or Google Sheets, "Enable Content" to Enable Macros



4. Connect the black USB cable to the USB Scan Tool and the Windows Laptop.
ONLY USE THE BLACK USB CABLE, DO NOT USE THE USB WIRELESS DONGLE



- Scan the barcode on the driver door jamb using the SST Tool or enter the VIN Manually. The VIN check must state "VALID 5823D VIN" to proceed.

ENTER OR SCAN VIN THEN SCAN	Enter Data with SST	
	5823D - VIN	ABS HCU SERIAL NUMBER
QR CODE ON ABS HCU	[REDACTED]	
CLEAR VIN and SERIAL		
VIN CHECK	Inspection Results	
VALID 5823D VIN	SERIAL CHECK	Inspection results
	N/A - GOOD PART	ENTER VIN - INVALID VIN

- With the hood raised, place the Laptop on the Engine Cover with the USB Scan Tool Connected. Locate the ABS Unit (DSC HCU) under the rear LH side engine bay. You will need to scan the QR Code on the ABS Unit.



- Place the cursor in the "ABS HCU SERIAL NUMBER" Field. Using the Barcode Scanner, Press and Hold the Orange button and scan the QR Code on the ABS Unit (DSC HCU). [Click Here to see a VIDEO on how to scan the QR Code "Video to Scan QR Code. This VIDEO is also available in MGSS under the 5823D Documents.](#)

ENTER OR SCAN VIN THEN SCAN	Enter Data with SST	
	5823D - VIN	ABS HCU SERIAL NUMBER
QR CODE ON ABS HCU	[REDACTED]	[REDACTED]
CLEAR VIN and SERIAL		
VIN CHECK	Inspection Results	
VALID 5823D VIN	SERIAL CHECK	Inspection results
	N/A - GOOD PART	ENTER VIN - INVALID VIN

5. Scanning the ABS HCU Serial Number. There will be 3 outcomes:

- a. If the Inspection results state "SERIAL NUMBER ALREADY USED":
 - i. This serial number has been used in a prior, paid warranty claim. Check eMDCS for the claim and do not proceed to repair and find out why this was repaired already.
 - ii. Fill out Dealer Recall Help if you have any questions.

	Enter Data with SST	
ENTER OR SCAN VIN THEN SCAN	5823D - VIN	ABS HCU SERIAL NUMBER
QR CODE ON ABS HCU →		0227062102636240012230802327
CLEAR VIN and SERIAL		
	Inspection Results	
SERIAL CHECK	SERIAL CHECK	Inspection results
	SERIAL NUMBER ALREADY USED	ENTER SERIAL AND VIN

- b. If the results state "GOOD PART, DO NOT REPLACE":
 - i. Copy the serial number to repair order (**required in claim "Repair Text"**)
 - ii. Take an exact screenshot of below and save for the warranty claim AS IT MUST BE ATTACHED AND WILL BE VERIFIED PRIOR TO ACCEPTANCE
 - iii. Click on "CLEAR VIN AND SERIAL" and close the Calculator
 - iv. Proceed to section D and install a campaign label.

3. TAKE A SCREENSHOT AND COPY THE SERIAL NUMBER TO THE REPAIR ORDER (REQUIRED FOR THE WARRANTY CLAIM)

	Enter Data with SST	
ENTER OR SCAN VIN THEN SCAN	5823D - VIN	ABS HCU SERIAL NUMBER
QR CODE ON ABS HCU →	[REDACTED]	0227062102636240022232201761
CLEAR VIN and SERIAL		
	Inspection Results	
VIN CHECK	SERIAL CHECK	Inspection results
VALID 5823D VIN	N/A - GOOD PART	GOOD PART, DO NOT REPLACE

- c. If the Inspection results state "REPLACE PART # DGYB437A0":
 - iii. Copy the serial number to repair order (**required in claim "Repair Text"**)
 - iv. Take an exact screenshot of below and save for the warranty claim AS IT MUST BE ATTACHED AND WILL BE VERIFIED PRIOR TO ACCEPTANCE
 - v. Click on "CLEAR VIN AND SERIAL" and close the Calculator
 - vi. Move to Step 6

ENTER OR SCAN VIN THEN SCAN	Enter Data with SST	
	5823D - VIN	ABS HCU SERIAL NUMBER
QR CODE ON ABS HCU →		022706210263624002232201760
CLEAR VIN and SERIAL		
	Inspection Results	
VIN CHECK	SERIAL CHECK	Inspection results
VALID 5823D VIN	022706210263624002232201760	REPLACE PART # DGYR437A0

6. Follow the steps in MGSS to replace the ABS HCU unit on the vehicle. [CX-30 ABS HCU \(DSC HU/CM\) REMOVAL AND REPLACEMENT](#)
7. Move to Section D "CAMPAIGN LABEL INSTALLATION" to attach a completed campaign label to the vehicle firewall, driver door jamb or radiator crossmember.

D. CAMPAIGN LABEL INSTALLATION

- a. Fill out a Black "Campaign Label" (9999-95-055A-06) with Campaign No: "5823D", your dealer code, today's date.

CAMPAIGN LABEL


CAMPAIGN NO: _____

DEALER CODE: _____

DATE: //

PIN 9999-95-055A-06

- b. Affix it to the hood as shown:



END OF REPAIR PROCEDURE