

GROUP	NUMBER
RECALL	24-01-013H
DATE	MODEL(S)
FEBRUARY 2024	KONA (SX2)

SUBJECT:

REAR SEAT BELT RETRACTOR RETAINER FASTENER PIN INSPECTION AND REPLACEMENT (RECALL 250)

This TSB supersedes 23-01-081H to add instructions to carefully remove the transverse trim piece on page 6 and add op codes under the Warranty Information table in case transverse trim replacement is necessary on pages 3-4.

### \* IMPORTANT


Vehicle repairs related to safety recalls are critically important and must be performed properly in accordance with TSB procedures. Review this bulletin in its entirety prior to beginning any repair work.

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must also perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

Access the "Vehicle Information" screen via WebDCS to identify open recalls.

**Description:** The rear lefthand and righthand seat belt assemblies in the subject vehicles may have undergone improper pin installation, potentially inhibiting extension of the seat belt webbing. An inability to fasten the seat belt in an occupied seat poses a failure to comply with Federal Motor Vehicle Safety Standard ("FMVSS") number 208, "Occupant Crash Protection," and FMVSS number 209, "Seat Belt Assemblies," increasing the risk of injury in a crash.

This bulletin provides the service procedure to inspect the retainer fastener pins and replace the rear seat belt assembly if necessary.





### Applicable Vehicles (Certain):

2024MY Kona (SX2) vehicles produced between 6/19/2023 – 9/02/2023.

### **Parts Information:**

Part Name	Figure	Part Number	Remarks
Rear Seat		89870BE-200NNB (LH)	- 1EA - LH
Belt		89880BE-200NNB (RH)	- 1EA - RH
Rear Seat Bush		89396-BE000	- 2EA - Replace only if needed, per step 16 on page 11.
Rear Transverse Trim		85770-BE000NNB (BLACK) 85770-BE000T9Y (GRAY)	- 1EA of either: 85770-BE000NNB OR 85770-BE000T9Y  **Replace only if part cannot be reused if damaged during removal.

### **SST Information:**

Tool Name	Part Number	Figure	Remarks
GIT Borescope	G0DKDNN039	GS.HI	This is an essential tool that has already been shipped to dealers. If dealer has broken or missing components or needs a replacement borescope, please contact GIT America at (888) 437-0308.

TSB #: 24-01-013H Page 2 of 15

**Warranty Information:** 

Model	odel Op. Code Operation		Op. Time	Nature Code	Cause Code
	31D114R0	Rear Seat Belt Retractor Retainer Fastener Pin Check	ainer Fastener Pin 0.4 M/H		
	31D114R1	Rear Seat Belt Retractor Retainer Fastener Pin Check and LH Rear Seat Belt Replacement	0.7 M/H		
	31D114R2	Rear Seat Belt Retractor Retainer Fastener Pin Check and RH Rear Seat Belt Replacement	0.7 M/H		
	31D114R3	Rear Seat Belt Retractor Retainer Fastener Pin Check and LH/RH Rear Seat Belt Replacement	1.1 M/H		
	31D114R5	Rear Seat Belt Retractor Retainer Fastener Pin Check and Rear Transverse Trim Replacement (85770-BE000NNB/BLACK)	0.4 M/H		
	31D114R6	Rear Seat Belt Retractor Retainer Fastener Pin Check, LH Rear Seat Belt Replacement, and Rear Transverse Trim Replacement (85770-BE000NNB/BLACK)	0.7 M/H		
Kona (SX2)		Rear Seat Belt Retractor Retainer Fastener Pin Check, RH Rear Seat Belt Replacement, and Rear Transverse Trim Replacement (85770-BE000NNB/BLACK)	0.7 M/H	192	ZZ7
	31D114R8	Rear Seat Belt Retractor Retainer Fastener Pin Check, LH/RH Rear Seat Belt Replacement, and Rear Transverse Trim Replacement (85770-BE000NNB/BLACK)	1.1 M/H		
	31D114R9	Rear Seat Belt Retractor Retainer Fastener Pin Check and Rear Transverse Trim Replacement. (85770-BE000T9Y/GRAY)	0.4 M/H		
	31D114RA	Rear Seat Belt Retractor Retainer Fastener Pin Check, LH Rear Seat Belt Replacement, and Rear Transverse Trim Replacement (85770-BE000T9Y/GRAY)	0.7 M/H		
	31D114RB	Rear Seat Belt Retractor Retainer Fastener Pin Check, RH Rear Seat Belt Replacement, and Rear Transverse Trim Replacement (85770-BE000T9Y/GRAY)	0.7 M/H		

TSB #: 24-01-013H Page 3 of 15

31D114RD	Rear Seat Belt Retractor Retainer Fastener Pin Check, LH/RH Rear Seat Belt Replacement, and Rear Transverse Trim Replacement (85770-BE000T9Y/GRAY)	1.1 M/H		
----------	---	---------	--	--

NOTE 1: Submit Claim on Claim Entry Screen as "Campaign" type.

**NOTE 2:** If a part is found in need of replacement while performing this recall and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

**NOTE 3:** This TSB includes Repair validation photos. Op times include VIN, Mileage, and Repair validation photos as outlined in the Digital Documentation Policy.

**NOTE 4:** The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.** 

#### **SERVICE PROCEDURE:**

## STUI



This TSB includes Repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

TSB #: 24-01-013H Page 4 of 15

#### I. REAR SEAT BELT RETRACTOR RETAINER FASTENER PIN INSPECTION

1. Connect the VCI-II into the vehicle's DLC connector under the driver side instrument panel and connect to the VCI-II on STUI to take pictures using the borescope (A).

Before starting the procedure, make certain that the battery of the Tablet and the borescope are sufficiently charged.

## *i* Information

Review the "STUI Borescope Guide" on hyundaitechinfo.com for connection instructions.

Diagnostic Tools > GDS and STUI Tips > No. 687 STUI Borescope Guide

## *i* Information

For technical assistance or replacement parts, contact GIT America at (888) 437-0308.

2. Remove the center covering shelf (B).





P/N: G0DKDNN039



TSB #: 24-01-013H Page 5 of 15


3. Remove the luggage covering mat and luggage board (C) and the rear transverse trim (D).

### **NOTICE**

Wear gloves to prevent injuries to hands.

Be careful not to damage the parts when using a trim remover.

Be careful not to bend or scratch the panels.




- 1. Remove the 2 holding clips (1) on the sides.
- 2. Carefully pry open one of the sides (2) in order to disengage the holding clip (2).
- 3. Carefully work towards the opposite side by popping the 4 retaining clips (3).
- 4. Remove trim.


#### **NOTICE**

Do not pull from bottom of the trim as trim may crack.

Pry open from one of the sides first and carefully pop clips to remove trim.











TSB #: 24-01-013H Page 6 of 15


5. Fold the LH/RH rear seat as shown on the right (E).



6. Remove the LH luggage side trim fixing screws (F).



7. Remove the RH luggage side trim fixing screws (G).



TSB #: 24-01-013H Page 7 of 15

8. Open the LH luggage side trim as shown in the picture on the right to check the mounting of the retainer fastener pin (H) with the borescope camera.

### **NOTICE**

Replace damaged clip(s) with new one(s).

## i

### Information

Attach the 90-degree camera lens on the borescope for best view of the fastener pins. There were two camera lenses (a straight and a 90-degree lens) included in the initial borescope kit to dealers.



TSB #: 24-01-013H Page 8 of 15

 Using the borescope camera, check the LH rear seat retainer fastener pin (I) is mounted.

## *i* Information

View to the fastener pin is partially obstructed by the seat belt webbing when fully retracted.

Extending seat belt out will provide better visibility to the fastener pin.





Take a photo of the LH rear seat retainer fastener pin using the borescope and upload to STUI.

Sample to the right is a 'Good' photo using the GIT borescope.

A 'No Good' photo would have the pin missing in the center.

Upload the photo to STUI. Label as 'LH' in the 'Note' section.





## *i* Information

Only one of the three retainer fastener pins need to be checked on each side to determine if it's good or no good.





TSB #: 24-01-013H Page 9 of 15


10. If retainer fastener pins are installed, then reassemble in the reverse order to complete the procedure for the LH.

If fastener pins are missing, follow procedure in Step II to replace the rear seat belt after inspection of RH seat belt fastener pins.

11. Open the RH luggage side trim as shown in the picture on the right and check the mounting of the retainer fastener pin (J) with borescope camera.

#### **NOTICE**

Replace damaged clip(s) with new one(s).




12. Check the installation of the RH rear seat retainer fastener pin (K) using the borescope camera.

## *i* Information

Fastener pins are facing the interior of the vehicle so aim camera towards the interior trim.


Use the 90-degree camera lens on the borescope for best view of the fastener pins.



TSB #: 24-01-013H Page 10 of 15

### *i* Information

Only one of the three retainer fastener pins need to be checked on each side to determine if it's good or no good.



## STUI



Take a photo of the RH rear seat retainer fastener pin using the borescope and upload to STUI.

Sample to the right is a 'Good' photo using the GIT borescope.


A 'No Good' photo would have the pin missing in the center.

Upload the photo to STUI and label as 'RH' in the 'Note' section.



13. If retainer fastener pins are installed, then reassemble in the reverse order to complete the inspection procedure.

Continue to Step II to replace the rear seat belt(s) if necessary.



**Note**: The `Good' and `No Good' views are for reference only. They show if the pins are installed (good) and if pins are not installed (no good) if the panel is removed.

TSB #: 24-01-013H Page 11 of 15


#### II. REAR SEAT BELT REPLACEMENT PROCEDURE

This procedure shows replacement for the LH side. RH side is the same.

14. Disconnect the battery (-) terminal (A).

### **Tightening Torque:**

lb-ft	5.8 ~ 7.2
kgf.m	0.8 ~ 1.0
N.m	7.8 ~ 9.8



15. Remove the rear seat cushion assembly (B).

#### Refer to Shop Manual:

 Body (Interior / Exterior / Electrical) > Rear Seat > Rear Seat Cushion Cover Assembly

### **NOTICE**

Be careful not to damage, bend, or scratch the parts when using trim remover.




16. Remove the bolt and remove the rear seat back assembly (C).

#### Refer to Shop Manual:

 Body (Interior / Exterior / Electrical) > Rear Seat > Rear Seat Back Cover Assembly


### **Tightening Torque:**

lb-ft	32.5~39.8
kgf.m	4.5 ~ 5.5
N.m	44.1~53.9



TSB #: 24-01-013H Page 12 of 15


17. Remove the LH/RH rear seat to the side by lifting it in the direction of the right arrow on the picture (D).



## **CAUTION**

When removing the seat back assembly, be careful not to damage the rear seat bush (E).

Replace with a new supplied rear seat bush if it is damaged during removal.



18. Remove the luggage side trim.


Refer to Shop Manual:

 Body (Interior / Exterior / Electrical) > Luggage Trim > Luggage Side Trim

Remove the mounting bolt and remove the rear seat belt lower anchor (F).




lb-ft	32.5~39.8
kgf.m	4.5 ~ 5.5
N.m	44.1~53.9




TSB #: 24-01-013H Page 13 of 15

19. Disconnect the rear seat belt retractor connector (G).



20. Loosen the mounting bolts and remove the rear seat belt retractor (H).




21. Replace with supplied rear seat belt retractor.

## STUI



Usign STUI, take a photo of the rear seat belt retractor showing the fastener pin with the last 6 digits of the VIN, the side replaced (LH or RH), and the date of repair on a piece of paper.


Upload the photo to STUI.



TSB #: 24-01-013H Page 14 of 15

## **Tightening Torque:**

lb-ft	32.5~39.8
kgf.m	4.5 ~ 5.5
N.m	44.1~53.9



22. Reinstall in reverse order of removal and repeat procedure for RH side if necessary.

Reconnect battery (-) terminal and check functionality of the rear seat belt(s) to complete procedure.

TSB #: 24-01-013H Page 15 of 15