

GROUP	NUMBER
RECALL	24-01-027H
DATE	MODEL(S)
	SANTA FE SPORT (AN)
APRIL 2024	(AN) SONATA HYBRID

(YF HEV)

SUBJECT:

ANTI-LOCK BRAKING SYSTEM (ABS) FUSE REPLACEMENT (RECALL 251)


* IMPORTANT

Vehicle repairs related to safety recalls are critically important and must be performed properly in accordance with TSB procedures. Review this bulletin in its entirety prior to beginning any repair work.

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must also perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

Access the "Vehicle Information" screen via WebDCS to identify open recalls.

Description: Certain 2013MY Santa Fe Sport (AN) and 2011-2015MY Sonata Hybrid (YF HEV) vehicles may develop an electrical short in the Anti-Lock Brake System (ABS) module, increasing the risk of an engine compartment fire. Follow the procedures in the bulletin to replace either the ABS multifuse (on Santa Fe Sport/AN) or the two individual ABS single fuses depending on the model.





Applicable Vehicles (Certain):

- 2013MY Santa Fe Sport (AN) produced 7/12/2012 6/15/2013
- 2011-2015MY Sonata Hybrid (YF HEV) produced 12/02/2010 10/31/2014

Parts Information:

Model	Part Name	Part Number	Figure	Remarks
Santa Fe	Fuse Kit 91AN1-		Multi-fuse Upper Cover	Apply the label to
Sport (AN)		91AN1-11200QQH	Upper Cover Fuse Label The content of the conten	Apply the label to the junction box upper cover.
	Hybrid Fuse Kit 91YF1-11020QQH		30A 20A	Apply the appropriately
Sonata Hybrid (YF HEV)		91956-00500 30A 30A 20A 30A 30A 20A 30A 20A 30A 20A	sized labels to the junction box upper cover as described in the service procedures.	

TSB #: 24-01-027H Page 2 of 9

Warranty Information:

Model	Op. Code	Operation	Op. Time	Casual Part	Nature Code	Cause Code
Sonata Hybrid (YF HEV)	41D013R0	ABS Single Fuse Installation	0.2 M/H	58920-4Z000	770	
Santa Fe Sport (AN)	41D013R1	ABS Multi-Fuse Installation	0.2 M/H	58920-4R000	111	ZZ3

NOTE 1: Submit claim on Claim Entry Screen as "Campaign" type.

NOTE 2: If a part is found in need of replacement while performing this recall and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

NOTE 3: This TSB includes Repair validation photos. Op times include VIN, Mileage, and Repair validation photo(s) as outlined in the Digital Documentation Policy.

NOTE 4: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

TSB #: 24-01-027H Page 3 of 9

Service Procedure:



Information

Service procedures for Santa Fe Sport (AN) can be found on page 4 of this TSB. Service procedures for Sonata Hybrid (YFE) can be found on page 7 of this TSB.

STUI



This TSB includes Repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

i

Information

Refer to the QR code or link below for guided video information: Hyundai Service Learning – Recall 251 Service Procedure



i

Information

If the "ABS", "ESC", or "Brake" indicator lights are illuminated, refer to the appropriate section in the shop manual for diagnosis and repair **before** performing this Recall.

Santa Fe Sport (AN): Replacement of Multi-fuse

1. Record customer's radio presets, then disconnect the negative (–) battery terminal.


Tightening Torque:

lb-ft	3.7	
lb-in	44	
N.m	5	



TSB #: 24-01-027H Page 4 of 9


2. Locate the junction box and remove the cover.




3. Remove the multi-fuse nut and junction box cable. Release the locking tab and remove the multi-fuse.

Tightening Torque:

lb-ft	8.0	
lb-in	96	
N.m	11	







TSB #: 24-01-027H Page 5 of 9

5. Clean the surface, then apply the supplied label to the new upper cover.



6.

STUI




Using STUI, take one photo with the last 6 digits of the VIN and the date of repair on a piece of paper. Photo must show:

- New multi-fuse installed in junction box
- Junction box cover with newly applied label

Upload the photo to STUI.

- 7. Install the new junction box upper cover.
- 8. Reconnect the negative (-) battery terminal.
- 9. Reset customer's radio presets.
- 10. Start the engine to confirm proper operation.
- 11. Service procedure is now complete.



TSB #: 24-01-027H Page 6 of 9

Sonata Hybrid (YF HEV): Replacement of Two Single Fuses

1. Record customer's radio presets, then disconnect the negative (–) battery terminal.

Tightening Torque:


lb-ft	3.7	
lb-in	44	
N.m	5	


2. From the engine compartment, locate the junction box and remove the cover.





3. Locate the HECU fuses, 40A (ESC1) and 30A (ESC2). Remove the HECU fuses.






TSB #: 24-01-027H Page 7 of 9

4. Install the two new single fuses as shown.

ESC1 position (40A fuse originally) Install new 30A fuse (pink).


ESC2 position (30A fuse originally): Install new 20A fuse (blue).



5. Select the appropriately sized labels with the corresponding amperage values for the two fuses installed.

Clean the surface, then apply the supplied labels to the junction box cover as shown:

Position	Original Value	New Value
ESC1	40A	30A
ESC2	30A	20A



TSB #: 24-01-027H Page 8 of 9

6.

STUI



Using STUI, take one photo with the last 6 digits of the VIN and the date of repair on a piece of paper. Photo must show:

- New fuses installed in junction box
- Junction box cover with newly applied labels

Upload the photo to STUI.



- 7. Reinstall the junction box cover.
- 8. Reconnect negative battery terminal.
- 9. Reset customer's radio presets.
- 10. Start the engine to confirm proper operation.
- 11. Service procedure is now complete.

TSB #: 24-01-027H Page 9 of 9