Technical Instructions

Safety Recall SR-23-05-0

Rear Seat Temperature Control Software

Model: Air

Year: 2022 / 2023

Market: USA / CAN / KSA

Rev 1

Release Date: 12/06/2023

I. PROCESS OVERVIEW



II. VIN ELIGIBILITY

Model	Year	Market
Air	2022 / 2023	USA / CAN / KSA

III. WORK ORDER DOCUMENTATION

Include the following information in the work order:

Concern	The rear seat heater can overheat the seat covers to the point of discoloration or charring
Cause	Software change inadvertently removed active temperature monitoring in certain non-driving modes
Correction	Confirm and/or update to Software version 2.1.26 or later

IV. DOCUMENTATION DETAILS

To ensure that vehicle campaign repairs are documented correctly, please reference the following when creating work orders for SR-23-05-0:

Job Code	SR-23-05-0 Rear Seat Temperature Control Software	
Рау Туре	Campaign [Customer Cars]	
	Rectify [Lucid Internal Vehicles]	
Defect Code	Campaign	
Causal PN	P11-NSP0XX	

Select the Labor Op code that best reflects the procedure performed on the vehicle:

Labor Op Code	Description	FRT*
96.230501	SR-23-05-0 - No Software Update Required + Seat Inspection OK	0.1
96.230502	SR-23-05-0 - Software Update Required + Seat Inspection OK	0.8
96.230503	SR-23-05-0 - No Software Update Required + Replace Damaged Rear Seats	0.5
96.230504	SR-23-05-0 - Software Update Required + Replace Damaged Rear Seats	1.3

*Flat Rate Time (FRT) is subject to change

NOTE: Safety Recall Campaign claim should be submitted as "CAMPAIGN" Pay Type.

V. PART NUMBER

Replace the damaged seat components as required. NOTE: Check VIN/vehicle for correct interior color code

VI. IMPORTANT INFORMATION

<u>A</u>CAUTION: Ensure the use of all appropriate PPE when performing this repair.

VII. REPAIR INSTRUCTIONS

- Use latest Technical Instructions (TI)
 Use the latest revision Technical Instructions (TI) by checking the revision (REV) number displayed
 on the title page and in the document footer.
- Confirm VIN Eligibility
 Eligible VIN will have an open Service Campaign Asset in Salesforce.
 Title: SR-23-05-0 Rear Seat Temperature Control Software

VIII. SOFTWARE UPDATE



IX. REAR SEAT CUSHION/SEATBACK INSPECTION

1. Inspect rear seat cushion/seatback:

- a) If rear cushion and/or seatback's show damage (i.e. darker colored sections or material deformed) from excessive heat produced by the seat heaters, proceed to section X. REAR SEAT CUSHION/SEATBACK REPLACEMENT
- b) If the seats do not show signs of any damage, proceed to **Step #2**.
- 2. No further action required. The campaign is complete. Release vehicle.

X. REAR SEAT CUSHION/SEATBACK REPLACEMENT

1. Replace the rear seat components as required. Refer to the Service Manual.

Service Manual / Body Interior / Seating / <u>Seatback Assembly 40</u>

Service Manual / Body Interior / Seating / Seatback Assembly 60

Service Manual / Body Interior / Seating / Rear Seat Cushion Remove and Replace

- 2. Attach a photo of the damaged rear seat components in the Work Order. Include a description of the damage found and the components that were affected.
- 3. No further action required. The campaign is complete. Release vehicle.