

GROUP	MODEL
Safety Recall Campaign	2015-2019MY
	Soul EV (PS EV)
NUMBER	DATE
SC287	December 2023

# SAFETY RECALL CAMPAIGN

# SUBJECT: ECM EPB OPERATION LOGIC IMPROVEMENT (SC287)

This bulletin provides information to update the Electronic Parking Brake (EPB) software logic on certain 2015-2019MY Soul EV (PS EV) vehicles produced from July 15, 2014 through September 28, 2018. When the vehicle is left unattended while powered 'ON' and the parking brake is not manually engaged, unintended vehicle movement may occur intermittently even though the gear shift lever in the 'P' (Park) position. This is caused by intermittent failure of the parking pawl to engage the parking gear. Unintended vehicle movement can increase the risk of a crash. Follow the procedure outlined in this publication to upgrade the software logic of the Electronic Parking Brake (EPB) system using the KDS ECU Upgrade function as described in this bulletin on the applicable vehicle and apply the provided leaflet to the Owner's Manual. For confirmation that the latest reflash has been applied to a vehicle you are working on, verify the ROM ID using the table on page 3 of this bulletin.



#### **NOTICE**

There is no charge to the vehicle owner for this repair. Under applicable law, you may not sell or otherwise deliver any affected vehicle until it has been repaired pursuant to the procedures set forth in this bulletin.

Repair status for a VIN is provided on KDealer+ (Service  $\rightarrow$  Warranty Coverage  $\rightarrow$  Warranty Coverage Inquiry  $\rightarrow$  Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs  $\rightarrow$  Not Completed Recall  $\rightarrow$  Recall VIN  $\rightarrow$  Select Report), which includes a list of affected vehicles.

# ECM EPB OPERATION LOGIC IMPROVEMENT (SC287)

#### **ECU Upgrade Procedure:**

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

#### Upgrade Event Name

710.PS EV EPB operation logic improvement

#### **NOTICE**

- Confirm a <u>fully charged battery</u> (12.3 volts or higher is necessary) is used <u>or</u> utilize a fully charged jump starter box connected to the battery.
- Ensure the KDS GDS is sufficiently charged at 60% or higher prior to reflash.
- All ECU upgrades must be performed with the ignition set to the 'ON' position unless otherwise stated.
- Damaged VCI II units should not be used and promptly replaced.
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- DO NOT start the engine during ECU upgrade.
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.
- ONLY use approved ECU upgrade software designated for the correct application.

#### **(i)** IMPORTANT

It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.



#### **NOTICE**

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.

#### **ROM ID INFORMATION TABLE:**

Upgrade Event #710

Model	System IMMO 🔁 ECU P/No.	ECLLD/No	ROM ID		
Model	System		ECO P/NO.	Previous	New
PS EV	EPB	Yes	59790 E4000 59790 E4500	1.1 1.2 1.3 2.4	1.5 2.7

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.

### **NOTICE**

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.

Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

# **NOTICE**

The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.




2. With the ignition **ON**, turn ON the KDS tablet. Select **'KDS'** from the home screen.





# ECM EPB OPERATION LOGIC IMPROVEMENT (SC287)

Confirm communication with VCI (A) and then configure the vehicle (B) using the 'AUTO VIN' (C) feature.



Select 'ECU Upgrade'.



 The KDS will check the server for recently uploaded Events and then automatically download Upgrade Event #710.

### **■** NOTICE

The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.

After the download is complete, the program will shut down to install.

Please wait until the program restarts.

Event Status

271.QF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT Downloading

273.TF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT Ready


Do not touch any system buttons while performing this function.

KDS screenshot shown above is for demonstration purposes only. Events shown in screenshot are not applicable to this bulletin.

6. Select Auto Mode.

# **A**CAUTION

Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.





## ECM EPB OPERATION LOGIC IMPROVEMENT (SC287)

7. Select **'EPB'** system and applicable **'Event Group'** (D) for the vehicle:


**Event #710.PS EV EPB operation logic** improvement



8. The ECU upgrade will begin, and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

### **A**CAUTION

Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.



 If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Select 'OK' and restart the from step 4.

#### **NOTICE**


If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.






# ECM EPB OPERATION LOGIC IMPROVEMENT (SC287)

10. When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Select 'OK' to continue.



11. Once the upgrade is complete, select **'OK'** to finalize the procedure.



12. When prompted, select 'YES' to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



13. Start the engine to confirm normal operation of the vehicle.



#### **Manual Upgrade Procedure:**

# **NOTICE**

The manual upgrade should ONLY be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition 'OFF' for about 10 seconds then place it back in the 'ON' position to reset the control unit BEFORE performing manual upgrade.

See table below for 'Manual Mode' passwords.

#### Manual Mode ECU Upgrade Passwords


Menu	Password
PS EV EPB : 59790-E4000/500 (S/W ver 1.1~1.3)	0979
PS EV EPB : 59790-E4500 (S/W ver 2.4)	4500

- 1. Within the ECU Upgrade screen displayed, select **Manual Mode**.
- 2. Select the **'EPB'** system under the System selection menu. Select **Upgrade Event #710** and select **Upgrade** to continue.
- 3. Select the appropriate control unit part number with reference to the ROM ID Information Table on page 3, and select **OK**.
- 4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
- 5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
- 6. When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Select OK.
- 7. Once the upgrade is complete, select **OK** to finalize the procedure.
- 8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
- 9. Start the engine to confirm proper operation of the vehicle.



### **Leaflet Application Instructions:**

- 1. Print leaflet.
- 2. Fold and insert leaflet shown below with the owner's manual in the glove box.





#### AFFECTED VEHICLE RANGE:

Model	Production Date Range
Soul EV (PS EV)	July 15, 2014 to September 28, 2018

#### **REQUIRED TOOL:**

Tool Name	Figure	Comments
KDS		Kia Diagnostic System

#### **REQUIRED PART:**

Part Name	Part Number	Figure	Qty.
Leaflet	Print a copy of page 8 and cut to size.	CONTROL CONTRO	1

#### **WARRANTY INFORMATION:**

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
R	59790 E4000	0	(SC287) EPB Operation Logic Improvement	231127R0	0.3 M/H	HE40E U72CLQQK	1

# **NOTICE**

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference <a href="SC287">SC287</a> when accessing the KDealer+ system.

