



Kia America, Inc.
Corporate Headquarters
111 Peters Canyon Road, Irvine, CA 92606-1790 USA

RENOTIFICATION

IMPORTANT SAFETY RECALL

NHTSA Recall Number: 23V634

This notice applies to your vehicle: **Insert VIN**

AUGUST 15, 2024

THIS IS A RENOTIFICATION OF AN EARLIER COMMUNICATION ISSUED ON DECEMBER 18, 2023, WHICH NOTIFIED OWNERS OF THE AFFECTED 2018-2021 MY KIA STINGER VEHICLES EQUIPPED WITH A 2.0L T-GDI ENGINE OF A SAFETY RECALL. OUR RECORDS INDICATE THAT YOU ARE THE CURRENT REGISTERED OWNER OF THIS VEHICLE AND THAT THIS RECALL HAS NOT BEEN COMPLETED.

KIA IS REQUESTING THAT YOU CONTACT AN AUTHORIZED KIA DEALERSHIP IMMEDIATELY TO SCHEDULE AN APPOINTMENT TO INSPECT AND, IF NECESSARY, REPLACE THE HIGH-PRESSURE FUEL PUMP AND UPDATE THE ECU SOFTWARE IN YOUR VEHICLE AT NO COST TO YOU.

IF YOU HAVE ALREADY TAKEN YOUR VEHICLE TO A KIA DEALER AND HAD THIS SAFETY RECALL PERFORMED, PLEASE DISREGARD THIS NOTICE.

IMPORTANT SAFETY RECALL

NHTSA Recall Number: 23V634

This notice applies to your vehicle: **Insert VIN**

FOLLOW-UP NOTICE

December 18, 2023

Dear Kia Stinger Vehicle Owner:

Kia has identified a defect in your vehicle which relates to motor vehicle safety.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Kia America, Inc. has decided that a defect which relates to motor vehicle safety exists in 2018-2021 MY Stinger vehicles equipped with a 2.0L Turbo Gasoline Direct Injection (T-GDI) engine. The defect can result in a loss of drive power in your vehicle. A loss of drive power increases the risk of a crash. Our records indicate that you own or lease one of the affected vehicles.

The remedy is now available for your vehicle.


What Is The Problem?

The fuel control valve plunger may stick inside the high-pressure fuel pump, causing over-pressurization and loss of drive power. A loss of drive power can increase the risk of a crash.

Kia Will Inspect, And If Necessary, Replace The High-Pressure Fuel Pump and Update The ECU Software Free of Charge At No Cost To You.

Kia dealers will inspect the high-pressure fuel pump, and if necessary, replace it with a new one. Dealers will also update the Engine Control Unit ("ECU") software logic. This recall will be performed **free of charge at no cost to you**. The estimated time required to perform this recall will be approximately one (1) to two (2) hours. We recommend scheduling a service appointment to minimize your inconvenience.

What Should You Do?

- **WARNING:** You may experience the illumination of Check Engine Light . If this occurs, pull over to a safe location and contact Kia Roadside Assistance at 1-800-333-4542 or online at kia.rsahelp.com to request to have your vehicle towed to the nearest authorized Kia dealership as soon as possible.

- To find your nearest dealer, visit www.kia.com and click the “Find Dealer” button in the upper right corner (“Dealers” on a mobile device). You can also use the QR code below with your mobile device to access this information (*see the bottom of this letter for more information about QR code use*):



What If You Have Already Paid To Have This Situation Corrected?

If you have incurred expense to remedy this issue prior to the date of this notice, you may have the opportunity to obtain reimbursement for that expense. You may submit your receipts online to Kia via the Owners section of www.kia.com or mail your receipts with a copy of the attached Request for Reimbursement form directly to Kia for review and consideration:

**Kia Customer Care
Kia America, Inc.
P.O. Box 52410
Irvine, CA 92619-2410
1-800-333-4542**

Pursuant to the General Reimbursement Plan issued by Kia pursuant to Federal Regulation 49 CFR 573.13, Kia will use its best efforts to respond to your claim within sixty (60) days of receipt and at that time Kia may either accept or reject that claim or it may request more information to evaluate the claim.

Have You Changed Your Address Or Sold Your Kia?

If you have changed your home address, sold your Kia vehicle, or no longer own your vehicle, please complete the attached prepaid “Change of Address/Ownership” card and mail it to us. You can also contact the Kia Customer Care Center phone number listed below.

What If You Are A Vehicle Lessor?

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

What If You Have Other Questions?

If your dealer does not respond to your service request in a timely manner, we suggest that you call Kia’s Customer Care Center at 1-800-333-4542. This number has TTY capability. If your dealer fails or is unable to remedy this defect without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

This action has been taken in the interest of your safety, and we regret any inconvenience this situation may cause you.

Sincerely,

Customer Care Department

QR Code Use:

- A QR Code is a square, 2-dimensional barcode that can be read by mobile devices loaded with an appropriate barcode or QR Code Reader App. The app reads the barcode image and then launches/uploads the specific information the code contains, such as URLs, text, photos, videos.
- With a mobile device, **download a QR Code Reader App.** With many devices, you can do this through an app store or marketplace.
- **Open the QR Code Reader App on your mobile device. The app will utilize your device’s camera.** Center the code in the camera viewing area. With some apps, the URL or other information will automatically load when the code is recognized. For others, you may have to snap or take a picture of the QR code. Refer to the QR Reader Code App instructions.

