



PREVOST

SAFETY RECALL


SR23-304

DATE :	June 2023	SECTION :	18 BODY
SUBJECT:	Missing Weld on Passenger Flip-Up Seat		

First Release

06-08-2023

APPLICATION

NOTICE TO SERVICE CENTERS	
<i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of PreVost website.</i>	
Model	VIN
X3-45 Commuter Model Year: 2020 - 2023	 <p>From 4RKJ33496L9 [REDACTED] up to 4RKJ33496P9 [REDACTED] incl.</p>
<p>This Safety Recall does not necessarily apply to all the above-mentioned vehicles. Some vehicles may also have been modified before delivery. The owners of the vehicles affected by this recall will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.</p>	

DESCRIPTION

On the vehicles affected by this recall, some of the foldable passenger seat frames may have been improperly welded.

Therefore, all vehicles must have their folding seats inspected and their frames replaced as necessary following the inspection procedure provided below.

The work will be entirely performed by authorized AMSECO technicians at the customer facilities


SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:




**Safety
First!**




 **DANGER**

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.




VEHICLE SEAT CONFIGURATION SHOWING FLIP-UP SEATS POSITION




FLIP-UP SEAT FRAME

- 1. The tubes, brackets, and center pivot are to be welded as shown below in blue. The weld will be on both sides of the recline bracket and center pivot.



2. The tubes and brackets are to be welded as shown below in green. The weld will be on both sides of the pedestal brackets.



OTHER

VBC Bulletin	N/A
Fail Code	18.03-2
Defect Code	09
Syst.Cond	R
Causal Part	868087

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>
or scan the QR-Code with your smart phone.
E-mail us at technicalpublications_prev@volvo.com and
type "ADD" in the subject to receive our warranty bulletins by e-mail.





**Safety Recall
Certification Sheet
(Ref: 0BSR23-304)**

VEHICLE SERIAL NUMBER:

PERFORMED BY		OWNER/OPERATOR	
We hereby certify that Safety Recall Instructions with regard to Safety Recall 0BSR23-304 have been performed.			
Name: _____		Name: _____	
Addr: _____		Addr: _____	
Phone: _____		Phone: _____	
Fax: _____		Fax: _____	
Signature : _____		Signature : _____	
Date: _____		Date: _____	

If the information mentioned above is incorrect or you are not the owner of this vehicle anymore, please fill this section and return to sender.

NEW OWNER: _____
BUSINESS: _____
ADDRESS (including County): _____

TELEPHONE: _____ **FAX:** _____

Please return this completed document with your A.F.A. form