23PBD - Peterbilt 579 MLU Alternator Wire Chafing

Number

23PBD / 23V423 / 2023-343

Description

Alternator Cable Chafing – Peterbilt 579 MLU With PACCAR MX-13 and PACCAR 160-amp Alternator.

Date

6/27/2023

What's New

On certain Model Year 2022 and 2023, 579 MLU trucks, built between 04/26/2021 and 07/29/2022, equipped with a PACCAR MX-13 engine and PACCAR 160-amp alternator, the alternator positive cable may chafe against the left-hand side, front spring bracket, top rearward fastener, if the fastener was installed with the head on the outside of the frame rail. Chafing of the alternator positive cable insulation may result in an increased risk of a fire.

Introduction

The alternator positive cable may chafe against the left-hand side, front spring bracket, top rearward fastener, if the fastener was installed with the head on the outside of the frame rail.

Chafing of the alternator positive cable insulation may result in an increased risk of a fire.

Situation

5,425 (4,914 US and 511 CAN) MY 2022 and 2023, Model 579 MLU built between 04/26/2021 and 07/29/2022, with a PACCAR MX-13 engine and PACCAR 160-amp alternator.

Resolution

Campaign

- Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
- Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.
- Use the attached procedure.
- Review SIR for "Complete" next to the "23PBD" campaign code prior to performing this repair.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

There is no time or mileage limit for this safety recall.

Peterbilt will pay for parts at dealer net plus applicable mark-up and labor.

• 0.7 hours labor to remove huck fastener from frame, replace with bolt, and inspect alternator wire for damage per repair procedures. Use Quick Claim Code 23PBDA.

• **1.5 hours** labor to remove huck fastener from frame, replace with bolt, and inspect alternator wire for damage, and replace alternator wire per repair procedures. Use Quick Claim Code **23PBDB**.

• 1.6 hours labor to remove huck fastener from frame, replace with bolt, inspect alternator wire for damage, R&R aero bumper for access to alternator

wire, and replace alternator wire per repair procedures. Use Quick Claim Code **23PBDC**.

• For extraordinary circumstances please use code **23PBD**, add from "Recommended Repairs", and then select the gear icon to edit Parts/Labor/Misc.

• File the claim within 14 days in accordance with the Warranty Policy.

Take-Off Parts Disposition: Dispose of takeoff parts 30-days after claim is paid.

PRWS CLAIM CODING				
Campaign Code:	23PBD	Campaign Type:	Safety Recall	
Claim Category:	Truck	Repair Type:	Proactive	
Customer Concern Code:	225	Causal Code:	49	
Corrective Action Code:	12	Responsibility Code:	Camp	
Failure Location:	032-001-042	Causal Part:	N92-6006- 4AHBA0120	
Supplier Code:	N/A	SRT Code:	B23-PBD 0.7 hours Labor to remove huck fastener from frame and replace with bolt and inspect alternator wire for damage per	

	repair procedure.
	ECA-006 0.8 hours Labor to replace alternator
	wire per repair procedure.
	014-114 0.1 hours
	Labor to remove and reinstall aero
	bumper for access – when equipped.

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

The repair procedure can be found in the Links section.

Parts

Quantity	Part Number	Description			
MUST BE ORDERED DSP					
1	W34-1160-080	Bolt - Finished Hex, M16			
1	W20-1028-016	Nut Hex Locking M16 Magni			
1 (If Needed)	N92-6006- 4AHBA0120	Cable - Battery (Pos) Assembly			
As Needed	D2973-2367	Shield - Hose			
AVAILABLE FROM PACCAR PARTS					
2	W34-1162-016	Washer Hard M16 Magni			
SOURCE LOCALLY					
As Needed	Source Locally	Spray Paint			
As Needed	Source Locally	Zip Tie Straps			

Links

23PBD Repair Procedures 23PBD Chassis List 23PBD US Customer Letter 23PBD Canadian (English) Customer Letter