23PBG: Safety Bulletin - Dana Driveline Weld

Number	
23PBG / 23V616 / 2023-496	
Supplier	
Dana	
Description	
Safety Recall - Dana Driveline Weld	
Date	
9/22/2023	
What's New	

Safety Recall

On certain Peterbilt model 220 chassis equipped with Dana SPL100 drivelines, the driveline tube seam weld may separate or tear under certain stress loads, resulting in driveline separation and sudden loss of drive power. A sudden loss of drive power may increase the risk of a crash.

Parts and repair procedures are now available to correct this issue.

Introduction

On certain Peterbilt model 220 chassis the driveline tube seam weld may separate or tear under certain stress loads, resulting in driveline separation and sudden loss of drive power. A sudden loss of drive power may increase the risk of a crash.

There will be no noticeable signs/indications preceding the described failure.

Reference Dana recall 23E052 for more information.

11/8/23, 8:47 AM Federal Recall Bulletin

Situation

22 (18 U.S., 4 Canada) Model year 2023, Peterbilt model 220 chassis built from 08/29/22 through 10/07/22 equipped with Dana SPL100 drivelines with certain driveline serial numbers.

Resolution

Safety Recall

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

- 1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
- 2. In Service Management, select campaign 23PBG to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the Campaign in Service Management.
- 3. If you are not using Service Management to start repair orders, review SIR for "Complete" next to the 23PBG campaign code prior to performing this

repair.

4. Follow the repair procedures attached in the Links section.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

There is no time or mileage limit for this safety recall.

Peterbilt will pay for parts at dealer net plus applicable mark-up and labor:

- Reference the attached Parts List by Chassis document and use the Quick Claim Code listed for the chassis you're working on.
 - Please note that cost of paint has been accounted for in the quick claim.
 - The paint reimbursement cost is estimated based on 2 12oz cans of black spray paint per driveshaft.
 - o If the driveshaft(s) require(s) a custom paint color, use code 23PBG and attach an invoice for the cost of the paint to the claim.
- For extraordinary circumstances please use code 23PBG, add from "Recommended Repairs", and then select the gear icon to edit Parts/Labor/Misc.
- File the claim within 7 days in accordance with warranty policy.
- Peterbilt dealers may perform 23PBG repairs on Kenworth chassis, but Quick Claims do not apply. For Kenworth chassis repairs, file a long-form

claim and use the claim codes below.

Take-Off Parts Disposition: Destroy take-off parts so that they cannot be reused or put back into service, as soon as possible.

	PRWS CLAIM CODING		
Campaign	23PBG	Campaign	Safety
Code:	23700	Туре:	Recall
Claim Category:	Truck	Repair Type:	Proactive
Customer Concern Code:	029	Causal Code:	62
Corrective Action Code:	12	Responsibility Code:	SUPP
Failure Location:	024- 002-043	Causal Part:	90-70-28X
Supplier Code:	05036AJ	SRT Code:	024-111 0.5 hours Medium duty driveshaft. Slip yoke to rear axle. 024-113 0.7 hours Medium duty driveshaft. Transmission or intermediate driveshaft and carrier bearing, without slip

	yoke. Does not include disassembly of the driveshaft.
	053-073
	1.1 hours
	Driveshaft -
	refinish
	(complete)
	(time is per
	driveshaft)

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

- You must reference the Parts List by Chassis document in the Links section prior to starting repairs.
- Please note that, in most cases, not all driveshafts on a given chassis will require replacement.
- ONLY replace the driveshafts listed for the specific chassis in the Parts List by Chassis document!
- Please see attachment in Links section below for driveshaft R&R procedures.

Parts



NOTE

You must reference the "Parts List by Chassis" document in the Links section prior to starting repairs or ordering parts.

Please note that, in most cases, not all driveshafts on a given chassis will require replacement.

ONLY replace the driveshafts listed for the specific chassis in the "Parts List by Chassis" document!

The following parts are available through PACCAR Parts Direct Ship Program:



NOTE

Due to the low volume needed for this Safety Recall, all driveshafts must be ordered through the Direct Ship Program (DSP) using order types XS (Stock) or XE (Emergency) on PartsOnline.

Part Number	Part Description	Quantity
100CS54001- 560M	DRIVESHAFT	*AS NEEDED
100CS54001- 690M	COUPLING SHAFT	*AS NEEDED
100CS54001- 795M	COUPLING SHAFT	*AS NEEDED
100CS54001G- 1075M	DRIVESHAFT XS (STEEL)	*AS NEEDED
100CS54004- 1080M	PNG - DANA DRIVESHAFT	*AS NEEDED
100CS54004- 895M	COUPLING SHAFT	*AS NEEDED
100CS54004- 935M	PNG - DANA DRIVESHAFT	*AS NEEDED
100CS54004- 970M	DRIVESHAFT	*AS NEEDED
100DS55002- 800M	PNG - DANA DRIVESHAFT	*AS NEEDED
100DS55006- 420M	DRIVESHAFT	*AS NEEDED
100DS55006- 480M	DRIVESHAFT	*AS NEEDED

100DS55007- 1100M	PNG - DANA DRIVESHAFT	*AS NEEDED
100DS55007- 880M	DRIVESHAFT ASSY.	*AS NEEDED
100DS55007- 976M	DRIVESHAFT	*AS NEEDED

The following part is available through PACCAR Parts.

Part Number	Part Description	Quantity
90-70-28X	KIT-STRAP-453 PDC	*AS NEEDED

The following part must be sourced locally.

Part Number	Part Description	Quantity
Locally Sourced	12oz Spray Paint (black or matching chassis color)	2 Per Driveshaft

Links

23PBG Chassis List

23PBG Parts List By Chassis

23PBG Repair Procedure

23PBG FINAL US Customer Letter

23PBG FINAL Canada (English) Customer Letter

23PBG FINAL Canada (French) Customer Letter

Revision History

11/08/2023 - Bulletin has been changed from an interim notification to a final bulletin. Parts and repair procedures are now available to correct the issue.