

U.S. Department of Transportation

National Highway Traffic Safety Administration

June 6, 2024

1200 New Jersey Avenue SE Washington, DC 20590

Karen Szabo
Karma Automotive LLC
9950 Jeronimo Road
Irvine, CA 92618

NEF-107SS
24V-379

Subject: Turn Signals May Fail Intermittently

Dear Karen Szabo:

This letter serves to acknowledge Karma Automotive LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

KARMA/REVERO GS-6/2020-2022 KARMA/REVERO GT/2020-2022 KARMA/REVERO GTS/2020-2022

Mfr's Report Date: May 29, 2024

NHTSA Campaign Number: 24V-379

Components:

EXTERIOR LIGHTING:TURN SIGNAL

Potential Number of Units Affected: 269

Problem Description:

Karma Automotive (Karma) is recalling certain 2020-2022 Revero GS-6, Revero GS-6s, Revero GS-6L, Revero GTS, and Revero GT vehicles. A communication error with the vehicle control module (VCM) may cause the front turn signals to fail intermittently. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associate Equipment."

Consequence:

Turn signals that do not function properly may fail to indicate the driver's intention to change vehicle direction, increasing the risk of a crash.

Remedy:

Dealers will install new headlights with updated software, free of charge. Owner notification letters are expected to be mailed July 25, 2024. Owners may contact Karma customer service at 1-855-288-6109.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Karma Automotive LLC's contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

