OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24E-071

Manufacturer Name: GE Appliances, a Haier Company

Submission Date: AUG 26, 2024 NHTSA Recall No.: 24E-071 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: GE Appliances, a Haier Company

Address: 4000 Buchel Bank Road

Louisville KY 40225

Company phone:

Population :

Number of potentially involved: 4,963 Estimated percentage with defect: 100 %

Equipment Information:

Brand / Trade 1: GE Appliances

ARC13MACB ARC13MACW ARC13MHCB ARC13MHCW ARC15MACB

ARC15MACW ARH13MHCB ARH13MHCW ARH15MACB ARH15MACW

Model: PLC15MAHB PLH13BAHW-BK PLH13MAHB PLH13MHHB PLH13MHHW

PLH15BAHB PLH15BAHW PLH15BAHW-BK PLH15MAHB PLH15MAHW

87016ABH5400 GEASST-1

Part No.: N/A Size: NR

Function: Air Conditionin

Descriptive Information: Approximately 4,963 recreational vehicles manufactured by third parties that

incorporate third-party ICM Controls' ICM870-16A-BH5400 soft start units that

were supplied by GE Appliances and/or GE Appliances' recreational air

conditioning units incorporating the ICM870-16A-BH5400 soft start unit. All of the affected air conditioning units and/or soft start units contain the same components, but the percentage of ICM870-16A-BH5400 soft start units that contain a design and/or manufacturing defect and/or that may demonstrate the

unsafe condition is unknown to GE Appliances at this time.

Production Dates: JUN 01, 2022 - MAY 29, 2024

Description of Defect:

Description of the Defect: GE Appliances did not design or manufacture the ICM870-16A-BH5400 soft start units. GE Appliances incorporated the ICM870-16A-BH5400 soft start units manufactured by third-party manufacturer ICM Controls into certain recreational vehicle air conditioners distributed by GE Appliances. It also sold some number of the ICM870-16A-BH5400 soft start units directly to manufacturers, maintenance and/or repair entities, and/or individuals.

> Upon information currently available to GE Appliances, the ICM Controls ICM870-16A-BH5400 soft start units manufactured prior to the spring of 2024 may contain some unknown design and/or manufacturing defect that increases the risk of thermal events in the affected soft start units. In coordination with ICM Controls, which manufactured and supplied the soft start units, GE Appliances continues to investigate the cause and scope of this defect, including whether any specific operating or other condition may cause these thermal events to occur and/or contribute to the possibility of such events occurring.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: In the event that an ICM870-16A-BH5400 unit undergoes and/or initiates a thermal event, the unit may emit smoke containing the byproducts of plastic or other component material combustion and/or experience a thermal breach the soft start's enclosure, leading to the destruction of the soft start and/or localized thermal damage to the area of the air conditioning where the soft start is located. Although unconfirmed at this time, the thermal event may, in very limited instances, have the potential to spread beyond the recreational vehicle's air conditioning into the recreational vehicle's construction.

Description of the Cause: In coordination with ICM Controls, GE Appliances is still investigating the root cause of the failure mechanism, including soliciting failure analysis from ICM Controls regarding the failure mechanism occurring in the ICM870-16A-BH5400 soft start controller. Upon information currently available to GE Appliances, the ICM Controls ICM870-16A-BH5400 soft start units manufactured prior to the spring of 2024 may contain some unknown design and/or manufacturing defect that creates a possibility of thermal events in the

Identification of Any Warning Based on currently available information, it appears that potentially affected that can Occur: recreational vehicle air conditioning units may cycle excessively or cease cooling if the ICM870-16A-BH5400 soft start fails, resulting in the inoperability of the installed air conditioning's compressor. Units may emit smoke and/or a burning odor, either into the RV cabin or through the external (roof mounted) housing of the unit.

Involved Components:

Component Name: ICM Controls ICM870-16A-BH5400 Series Soft Start

Component Description: Electronic soft start device for residential, commercial, RV & marine air

conditioning units

Component Part Number: ICM870-16A-BH5400

Supplier Identification:

Component Manufacturer

Name: ICM Controls

Address: 7313 William Barry Blvd.

Syracuse Kentucky 13212

Country: United States

Chronology:

GE Appliances incorporated the ICM870-16A-BH5400 soft start into multiple models of its recreational vehicle air conditioning units without a reported thermal incident until May 15, 2024. On that day, GE Appliances was notified of a thermal event in a GE Appliances model PLH15XAHWI1 RVAC that appeared to originate in the soft start unit. GE Appliances first contacted ICM Controls on June 3, 2024 to report the incident and to solicit information from ICM Controls regarding thermal events ICM Controls had previously observed in the ICM870-16A-BH5400 units. On June 18, 2024, ICM Controls responded, indicating that it had not previously received any report of any such thermal event in this type of application. GE Appliances subsequently shipped this soft start to ICM Controls for further failure analysis.

Between July 3, 2024 and August 16, 2024, GE Appliances received 10 reports of thermal events in GE Appliances RVAC units. GE Appliances made every effort to obtain additional information, including artifact evidence, from each of these events, and it appears from the evidence that could be obtained during this time period that the thermal events appeared to involve and/or originate in the ICM870-16A-BH5400 soft start device. Additionally, GE Appliances received insurance claims on July 17, 2024 and July 23, 2024 alleging RV property damage from fires originating in an GE Appliances RVAC unit; no further information on these claims is known at this time, including whether they contained a soft start unit. Upon receiving and analyzing the evidence related to these incidents, GE Appliances filed the instant report.

Description of Remedy:

Description of Remedy Program: GE Appliances is still determining an appropriate remedy for the defect. At present, GE Appliances anticipates that the remedy component may incorporate a ICM870-16A-BH5400 soft start unit manufactured after the spring of 2024 that reflects a new design and manufacture, pending substantiation by ICM Controls that these units do not contain any potential defect that may increase the risk of a thermal event. Further, GE Appliances anticipates that the remedy may incorporate a metal housing or similar enclosure around the soft start unit to create an additional containment mechanism for any potential thermal events in the soft start unit. To eliminate the potential for the defect condition/safety risk to occur, the ICM870-16A-BH5400 soft start unit can be removed from any installed recreational vehicle air conditioning unit.

from Recalled Component:

How Remedy Component Differs GE Appliances is still determining an appropriate remedy for the defect. At present, GE Appliances anticipates that the remedy component may incorporate a ICM870-16A-BH5400 soft start unit manufactured after the spring of 2024 that reflects a new design and manufacture, pending substantiation by ICM Controls that these units do not contain any potential defect that may increase the risk of a thermal event. Further, GE Appliances anticipates that the remedy may incorporate a metal housing or similar enclosure around the soft start unit to create an additional containment mechanism for any potential thermal events in the soft start unit.

Identify How/When Recall Condition According to ICM Controls, that company made various component, was Corrected in Production: design, and/or manufacturing changes to the ICM870-16-BH5400 soft start module in the spring of 2024. GE Appliances' previous inventory of the ICM870-16-BH5400 utilized in its production consisted of units delivered between approximately May 12, 2022 and March 28, 2023. GE Appliances has stopped manufacturing and/or distributing any air conditioners with the ICM870-16A-BH5400 soft start and/or the ICM870-16A-BH5400 soft start as a separate component pending replacement of its ICM870-16A-BH5400 inventory and further evaluation and testing of the soft start unit and/or any necessary enclosure for the soft start unit.

Recall Schedule:

Description of Recall Schedule: GE Appliances is still determining an appropriate remedy for the defect.

Once the appropriate remedy is determined, GE Appliances will be able to

establish a corresponding recall schedule.

Planned Dealer Notification Date: OCT 11, 2024 - OCT 18, 2024 Planned Owner Notification Date: OCT 11, 2024 - OCT 18, 2024

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: Forest River Inc Address: 900 Co Rd 1

Elkhart IN 46514

Country: US

Company Phone: (574) 389-4600

Name: Genesis Supreme RV Inc.

Address: 23129 Cajalco Rd

Perris CA 92570

Country: US

Company Phone: 951-337-0254

Name: Intelli-CORE, LLC

Address: 24094 Minnesota HWY 22

Litchfield MN 55355

Country: US

Company Phone: (320) 298-1600

Name: Jayco

Address: 903 S. Main Street

Middlebury IN 46540

Country: US

Company Phone: (574) 825-5861

Name: Keystone RV Company

Address: 2642 Hackberry Drive

Goshen IN 46526

Country: US

Company Phone: (574) 535-2100

Name: Rich Specialty Trailer/Kuntry Kustom RV

Address: 423 S. Main Street

Topeka IN 46571

Country: US

Company Phone: (260) 593-2208

Name: Outback Customs

Address: 8333 Southwest 29th Street

Oklahoma City OK 73179

Country: US

Company Phone: (405) 745-6666

Name: Thor Motor Coach Address: 601 E Beardsley Ave

Elkhart IN 46514

Country: US

Company Phone: (574) 970-7460

Name: Winnebago Industries Inc

Address: NR

13200 Pioneer Trail, Suite 150 Eden Prairie MN 55347

Country: US

Company Phone: (952) 829-8600

^{*} NR - Not Reported