The information contained in this report was submitted pursuant to 49 CFR §573

6

Part 573 Safety Recall Report

Manufacturer Name :Lode-King Industries, Ltd.Submission Date :JAN 18, 2024NHTSA Recall No. :24V-021Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Lode-King Industries, Ltd. Address : Box 1146

Company phone : 999

Vehicle Information :

Vehicle 1:	2018-2024 Prestige & Lode K	ing AHV45-3 and AHV	50-3
Vehicle Type :	TRAILERS		
Body Style :			
Power Train :	NR		
Descriptive Information :	Trailers in this recall were identified based on the particular ABS brake system that was employed. There are six (6) semi-trailers included in this recall.		
Production Dates :	DEC 03, 2018 - NOV 30, 2023		
VIN Range 1:	Begin : NR	End: NR	☐ Not sequential

Population :

Description of Noncompliance :

-	The vehicle system that is affected is the ABS brake function, and in particular, trailers that employ a 2S2M or 4S2M ABS system. The nature of this issue is that the ABS sensors may be plugged into the wrong connections on the ABS computer module. In other words, the ABS sensors may be connected backwards to the ABS computer.
FMVSS 1 :	121 - Air brake systems
FMVSS 2 :	NR
Description of the Safety Risk :	The potential safety risk is that if wheel lock up is sensed at one wheel end during a braking event, the ABS computer may modulate the air brakes on the opposite side of the trailer. This would reduce the braking effectiveness of the service brake system.
Description of the Cause :	Insufficient technical data and training provided for personnel building the trailers.
Identification of Any Warning that can Occur :	None known.



Number of potentially involved :

Estimated percentage with defect : 100 %

$\mathbf{24V}\text{-}\mathbf{021}$

Part 573 Safety Recall Report

Involved Components :

Component Name 1: N/A

Component Description : NR

Component Part Number: NR

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

During a recent quality system audit it was detected that a particular trailer had failed the end of line test for the ABS system. Upon further investigation we learned that the ABS sensors had been plugged into the wrong ports on the ABS computer. After a more in depth review it was determined that following a design change to the air tank location and ABS valve orientation the particular shop building this model of trailer were not given the necessary information about how the change affected the installation and testing of the system.

Description of Remedy :

Description of Remedy Program :	End user customers may take their trailer to a dealer location to have the corrective action carried out at no cost to them. Alternatively, if the customer wishes to perform the work themselves we will provide a Field Service Bulletin describing the procedure and we will reimburse them for one hour of labor time to carry it out.
How Remedy Component Differs from Recalled Component :	N/A
	As noted above, this problem was identified when different, more experienced personnel were assigned to perform our end of line test on the ABS system. All new production trailers as of January 12, 2024 are now being fully tested and validated before they are shipped to a dealer or end user.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

24V-021

Recall Schedule :

Description of Recall Schedule : NR Planned Dealer Notification Date : JAN 22, 2024 - FEB 09, 2024 Planned Owner Notification Date : JAN 22, 2024 - FEB 16, 2024

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573