

Part 573 Safety Recall Report

24V-086

Manufacturer Name : Jaguar Land Rover North America, LLC

Submission Date : FEB 08, 2024

NHTSA Recall No. : 24V-086

Manufacturer Recall No. : H468



Manufacturer Information :

Population :

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 2

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

Mahwah NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2019-2020 JAGUAR I-PACE

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : HYBRID ELECTRIC

Descriptive Information : Jaguar Land Rover is conducting a voluntary safety recall campaign involving 2018-2019 I-PACE vehicles built at the Graz Vehicle assembly plant from June 8, 2018 - July 18, 2019. 2 vehicles in the United States and Federalized Territories. The basis for the recall population was Jaguar I-PACE vehicles identified through data related to battery pack electrical conditions where an abnormal resistance was identified at the busbar connections.

Production Dates : JUN 08, 2018 - JUL 18, 2019

VIN Range 1 : Begin : SADHD2S19K1F61469 End : SADHC2S13L1F85741 Not sequential

Description of Defect :

Description of the Defect : A concern has been identified on a small number of I-PACE vehicles where the fasteners for the battery module to module electrical connecting busbars may not be sufficiently secure, which under some circumstances could result in arcing at the busbar to module connection point. Arcing will generate heat which may lead to a thermal overload condition.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A vehicle thermal overload condition such as fire or smoke can result in an increased risk of occupant injury and/or injury to persons outside the vehicle, as well as property damage.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : EV Battery

Component Description : EV Battery

Component Part Number : T4K16281

Supplier Identification :**Component Manufacturer**

Name : LG ES

Address : LG Energy Solution Wrocław Sp. z o.o
ul. LG 1A, Biskupice Podgórne Kobierzyce Foreign States 55-040

Country : Poland

Chronology :

See file "Jaguar Land Rover Recall Notification H468 Chronology"

Description of Remedy :

Description of Remedy Program : Vehicles will have the busbar fixings inspected and as required new components installed. Customers who have paid for a repair of this defect will be reimbursed by the Jaguar Land Rover reimbursement plan, subject to the usual terms and conditions. There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealer notification date is February 22, 2024. Customer letter mailing on or before March 28, 2024.

Planned Dealer Notification Date : FEB 22, 2024 - FEB 22, 2024

Planned Owner Notification Date : MAR 28, 2024 - MAR 28, 2024

* NR - Not Reported