

Part 573 Safety Recall Report

24V-252

Manufacturer Name : Terex Advance Mixer, Inc.**Submission Date :** JUN 11, 2024**NHTSA Recall No. :** 24V-252**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Terex Advance Mixer, Inc.

Address : 7727 Freedom Way

Fort Wayne IN 46818

Company phone : 999

Population :

Number of potentially involved : 12

Estimated percentage with defect : 95 %

Vehicle Information :

Vehicle 1 : 2023-2023 Terex Advance Mixer Commander

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Hendrickson contacted Terex Advance Mixer and informed them that 18 Composolite SC20 axles, that were shipped to Terex, had a defect. Hendrickson provided the serial numbers of the affect axles. Terex determined that 6 of the 18 axles were still on site and scheduled repair with Hendrickson. Terex determined what vehicles the remaining 12 axles had been installed on.

Production Dates : OCT 02, 2023 - OCT 20, 2023

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : A limited number of Hendrickson COMPOSILITE EXS20 and SC20 steerable auxiliary lift axle suspension assemblies and individual steering knuckle assembly components are equipped with bearing journals that may not have been seated correctly to the backbones of the left and right-side steering knuckle assembly components during manufacture.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In some cases, the above-referenced condition may cause a loss of oil lubricant from the wheel end hub assemblies. Over an extended period of operation, use of the lift axle suspension assemblies in this condition can result in (1) the respective axle spindles to become loose from the steering knuckle assemblies or otherwise fracture and/or (2) wheel end hub damage. This can further result in foreign object debris on the roadway, increasing the risk of a crash and/or injury.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : AXLE,SUS,HEND COMPOSILITE SCT20K

Component Description : NR

Component Part Number : 36675

Supplier Identification :

Component Manufacturer

Name : Hendrickson USA. L.L.C

Address : 2021 Parkside Drive
Schaumburg Illinois 60173

Country : United States

Chronology :

On November 13th, 2023 - Terex Advance was notified of the issue by Hendrickson via Email.

November 15th, 2023 - Terex Advance and Hedrickson had a conference call to discuss the issue. During this we asked, based on their subject matter expertise, if this is a safety related issue. At that point they did not believe so, but were still determining that. However, they indicated that they were going to use there service network to inspect the trucks (equipped with the subject axles) and make repairs if necessary. At this time 6 of the 18 subject axles were still within Terex's possession. Hendrickson subsequently came to our facility to inspect the axles and make repairs if necessary. 12 trucks, with the subject axle, were shipped prior to this meeting, and were under the possession of the customer. We worked with Hendrickson to put them in contact with the impacted customers so they could arrange to visit the customers location and inspect and remedy the axles involved.

March 19th, 2024 - Terex Advance received formal notification, by way of a NHTSA email, indicating that Hendrickson had filed a recall notification related to the specific axles they we discussed with Hendrickson on November 15th.

April 2nd, 2024 - Terex Advance after internal discussions and analysis of Hendrickson report, deemed this condition to be safety related. Therefore, a 573 defect report was authored. As of the authoring of this defect

report, all 18 of the subject axles have been inspected and the remedy applied if necessary.

Description of Remedy :

Description of Remedy Program : All Customers that could possibly be impacted by this issue will be contacted and provided inspection instructions to determine if their vehicle is impacted by this issue. if their vehicle is impacted parts and any labor associated with the remedy of the condition will be reimbursed to the customer.

How Remedy Component Differs from Recalled Component : The replacement steering knuckle assemblies will include journal rings that are fully seated into the knuckle backbones.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : We do not have dealers. Customer letters were sent out on 6/5/2024.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : MAY 13, 2024 - NR

* NR - Not Reported