

Part 573 Safety Recall Report

24V-561

Manufacturer Name : Hyundai Motor America**Submission Date :** JUL 26, 2024**NHTSA Recall No. :** 24V-561**Manufacturer Recall No. :** 265**Manufacturer Information :**

Manufacturer Name : Hyundai Motor America

Address : 10550 Talbert Avenue

Fountain Valley CA 92708

Company phone : 800-633-5151

Population :

Number of potentially involved : 49,719

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2024-2024 Hyundai Santa Fe

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Based on manufacturing and sales records, the subject vehicles include 40,144 certain model year 2024 Hyundai Santa Fe ICE vehicles produced on the specified dates by Hyundai Motor Manufacturing Alabama ("HMMA") for sale in the U.S. market. Other than those listed in this report, no other Hyundai/Genesis vehicles use the same component being recalled.

Production Dates : DEC 28, 2023 - JUL 18, 2024

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2024-2024 Hyundai Santa Fe HEV

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : HYBRID ELECTRIC

Descriptive Information : Based on manufacturing and sales records, the subject vehicles include 9,575 certain model year 2024 Hyundai Santa Fe HEV produced on the specified dates by Hyundai Motor Manufacturing Alabama ("HMMA") for sale in the U.S. market. Other than those listed in this report, no other Hyundai/Genesis vehicles use the same component being recalled.

Production Dates : MAR 06, 2024 - JUL 23, 2024

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : The main floor wire harness used in the subject vehicles could become damaged due to contact with the passenger-side, second-row bench seat's folding hinge assembly. A damaged main floor wire harness could result in illumination of the air bag warning light, inadvertent air bag deployment, and/or an inability to deploy the air bags during a crash.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Inadvertent air bag deployment and/or an inability to deploy the air bags during a crash could increase the risk of injury to occupants.

Description of the Cause : Inconsistent routing location of the floor wiring harness, or harness not properly secured in routing position.

Identification of Any Warning that can Occur : Air bag warning lamp illumination

Involved Components :

Component Name 1 : WIRING ASSY-FLOOR

Component Description : Main floor wire harness for Santa Fe (MX5)

Component Part Number : 91500-R6***

Component Name 2 : WIRING ASSY-FLOOR

Component Description : Main floor wire harness for Santa Fe (MX5) HEV

Component Part Number : 91500-HB***

Supplier Identification :**Component Manufacturer**

Name : Kyungshin Lear

Address : 100 Smothers Rd
Montgomery Alabama 36117

Country : United States

Chronology :

Please see attached chronology.

Description of Remedy :

Description of Remedy Program : Hyundai plans to have all owners of the subject vehicles notified by first class mail with instructions to bring their vehicles to a Hyundai dealer to inspect and properly secure the wire harness. In the event wire harness damage is confirmed, the floor wire harness will be replaced with a new one. This remedy will be offered at no cost to owners for all affected vehicles, regardless of whether the affected vehicles are still covered under Hyundai's New Vehicle Limited Warranty. Additionally, Hyundai will provide owners of affected vehicles reimbursement for out-of-pocket expenses incurred to obtain a remedy for the recall condition in accordance with the reimbursement plan submitted to NHTSA on February 22, 2024. As a precaution, if any of the warning symptoms specified in this report are confirmed present in vehicle, owners are advised to visit a dealer immediately for diagnosis and repair as the recall remedy is currently available.

How Remedy Component Differs from Recalled Component : The floor wire harness will be reinstalled and secured with new clip(s) to prevent interference with the seat folding mechanism.

Identify How/When Recall Condition was Corrected in Production : March 9, 2024 - Add band cable to reduce moving length.
May 22, 2024 - Reduce wire length (LH/RH).
July 10, 2024 - Add band cable to the floor to reduce movement.

Recall Schedule :

Description of Recall Schedule : Dealers will be notified electronically on the specified dates.
Owners will be notified by certified mail on the specified dates.

Planned Dealer Notification Date : JUL 26, 2024 - JUL 26, 2024

Planned Owner Notification Date : SEP 23, 2024 - SEP 23, 2024

* NR - Not Reported