OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-732

Manufacturer Name: Porsche Cars North America, Inc.

NHTSA Recall No.: 24V-732

Manufacturer Recall No.: ARB6 / ARB7



Manufacturer Information:

Manufacturer Name: Porsche Cars North America, Inc.

Address: One Porsche Drive

Atlanta GA 30354

Company phone: 1-800-767-7243

Population:

Number of potentially involved: 27,527 Estimated percentage with defect: 2 %

Vehicle Information:

Vehicle 1: 2020-2024 Porsche Taycan

Vehicle Type: LIGHT VEHICLES

Body Style: 4-DOOR

Power Train: HYBRID ELECTRIC

Descriptive Information: The vehicles were identified by data analytics to identify affected clusters of

production.

Production Dates: OCT 21, 2019 - FEB 01, 2024

VIN Range 1: Begin: WP0AC2Y16LSA70165 End: WP0AD2Y10RSA48040 ✓ Not sequential

Description of Defect:

Description of the Defect: Certain Taycan high-voltage batteries might experience short circuits within

the battery modules, which can lead to thermal events and in some cases fires.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A short circuit in the high-voltage battery module can increase the risk of a

thermal event.

Description of the Cause: The root cause analysis suggests that supplier production issues in the high-

voltage battery modules can, in rare instances, increase the risk of internal

short circuits.

Identification of Any Warning There are no warnings.

that can Occur:

Involved Components:

Component Name 1: Cell block module in high-voltage battery

Component Description: Cell block module in high-voltage battery

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: LG ENERGY SOLUTION WROCŁAW sp. z o.o.

Address: LG 1A

Kobierzyce Foreign States 55040

Country: Poland

Chronology:

This is a supplement to prior recalls: 23V840 (manufacturer recall identification code APB5); 24V215 (manufacturer recall identification code ARA4); and 24V217 (manufacturer recall identification code ARA5)

As a precautionary measure, Porsche decided to continue data analytics and hardware analyses for this issue.

On 23 September 2024, Porsche determined that a safety-related defect exists in additional Taycan vehicles identified via data analytics and hardware analyses and decided to initiate this recall (manufacturer recall identification codes ARB6/ARB7).

This recall (ARB6/ARB7) applies to a vehicle population for which Porsche currently has no positive knowledge that data anomalies exist in the high-voltage battery modules. For ARB6, Porsche does not have sufficient high-voltage battery data to assess whether data anomalies exist in the high-voltage battery or not. For ARB7, Porsche does have sufficient high-voltage battery data which currently show no data anomalies. Even if Porsche currently has no positive knowledge that data anomalies exist, Porsche cannot exclude that these high-voltage battery modules might show data anomalies in the future.

Description of Remedy:

Description of Remedy Program: Regarding ARB6, as a precaution, the owner notification letter will advise that affected vehicles should only be charged to a maximum of 80% of the battery capacity as an interim remedy.

> Regarding ARB7, an interim remedy (i.e., a reduction of the battery capacity to a maximum of 80%) is not necessary. This is because ARB7 applies to vehicles which allow Porsche continuous over-the-air access to continuously monitor and assess high-voltage battery data and detect future battery module anomalies in a timely and reliable manner by using data analytics. If a battery module anomaly is detected, the affected modules in the high-voltage battery will be replaced and the owner notification letter will advise that affected vehicles should only be charged to a maximum of 80% of the battery capacity until the replacement.

As a final remedy (for both ARB6 and ARB7), an on-board diagnostic software will be installed on affected vehicles to detect future battery module anomalies.

Before the on-board diagnostic software is installed on affected vehicles, the high-voltage battery modules will be analyzed. If this analysis shows no anomalies, the on-board diagnostic software will be installed. If this analysis shows anomalies, the affected high-voltage battery module will be replaced prior to the installation of the on-board diagnostics software.

Once installed, the on-board diagnostic software will use data analytics to detect future anomalies in high-voltage battery modules. If an anomaly is detected, the vehicle will display a warning message in the head unit and will limit the high-voltage battery charging capacity (in a first step to 80% and - after a certain time - to less than 80% presumably 50%). Affected high-voltage battery modules will be replaced. As the high-voltage battery consists of several modules, it can be possible that different modules show data anomalies leading to the replacement of several modules.

How Remedy Component Differs The vehicles will receive an on-board diagnostics software. This report from Recalled Component: will be updated as necessary.

Identify How/When Recall Condition Vehicles produced after 04.03.2024 are not subject to this recall because of was Corrected in Production: production countermeasures at the supplier.

Recall Schedule:

Description of Recall Schedule: Owners will be notified via mail within 60 days of the filing of this report.

Planned Dealer Notification Date: OCT 16, 2024 - OCT 16, 2024 Planned Owner Notification Date: NOV 29, 2024 - NOV 29, 2024