

# Part 573 Safety Recall Report

# 24V-783

**Manufacturer Name :** Rimac D.O.O.**Submission Date :** DEC 23, 2024**NHTSA Recall No. :** 24V-783**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Rimac D.O.O.

Address : 1950 Opportunity Way  
Reston VA 20190

Company phone : 818-309-8161

**Population :**

Number of potentially involved : 9

Estimated percentage with defect : 10 %

**Vehicle Information :**

Vehicle 1 : 2023-2024 Rimac Nevera

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : HYBRID ELECTRIC

**Descriptive Information :** A potential incorrect assembly/tightening of the C19 low voltage cable, resulting in a potential deviation from its correct position, potentially leading to damage to the isolation of the cable itself during the normal usage of the car. The lack of isolation on the cable may create a short-circuit with the monocoque which can act as high resistance. As a result, it increases the cable's temperature resulting in the cable melting, potentially increasing the risk of fire.

Production Dates : APR 25, 2023 - JUL 26, 2024

VIN Range 1 : Begin : V39A32AZ3P4AB8002 End : V39A32AZ2R4AB8074  Not sequential**Description of Defect :**

**Description of the Defect :** A potential incorrect assembly/tightening of the C19 low voltage cable, resulting in a potential deviation from its correct position, potentially leading to a damage to the isolation of the cable itself during the normal usage of the car. The lack of isolation on the cable might create short-circuit with monocoque which acting as very high resistance makes cable temperature to increase and melt, potentially increasing the risk of fire.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** A potential incorrect assembly/tightening of the C19 low voltage cable, resulting in a potential deviation from its correct position, potentially leading to a damage to the isolation of the cable itself during the normal usage of the car. The lack of isolation on the cable might create short-circuit with

monocoque which acting as very high resistance makes cable temperature to increase and melt, potentially increasing the risk of fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : Smell and smoke

## Involved Components :

Component Name 1 : C19

Component Description : Low Voltage Cable

Component Part Number : 001591962

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

October 7.,2024 Wrong routing detected, stop of assembly operations.

October 8, 2024 Start of investigation and internal analysis

October 10, 2024 Investigation closed. Root cause identified as man error. Product Safety Committee decided to report the event and kick-off a recall campaign to inspect customers' vehicles

October 18,2024 Notification sent to NHTSA

October 25,2024 Notification to dealers and customer started

## Description of Remedy :

Description of Remedy Program : Affected Customers will be contacted and informed that there is a potential defect on their vehicle and that needs to be checked. A visual check of the low voltage cable will determine if the car is affected and in the event that it is affected the car will be repaired by Bugatti Rimac. Bugatti Rimac will reimburse customers in accordance with the reimbursement plan submitted with this recall. All affected vehicles are within the new vehicle limited warranty. As a result, customers will be advised that all associated costs will be covered by Bugatti Rimac which includes transport to and from an authorized Rimac service center.

How Remedy Component Differs from Recalled Component : If improper routing of the cable is identified upon inspection the following steps must be taken:  
1) 12V check power line  
2) Loosen C19 cable fastening bolt  
3) Route C19 cable at a 90 degree angle, parallel to the C15 cable  
4) Fasten/torque C19 bolt at 90 degree angle to the C15 cable  
5) Check C19 cable for no movement

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : Vehicles will be recalled and the customer will receive an initial letter via mailing address advising that currently their vehicle is potentially non compliant from a safety perspective, preventing the vehicle from being driven until the car is inspected. The inspection is confirmed and validated by our Rimac After Sales personnel and authorizes Rimac service partners will recontact the customers individually to arrange an appointment for the collection and inspection of the car.

Planned Dealer Notification Date : OCT 25, 2024 - NOV 25, 2024

Planned Owner Notification Date : NOV 18, 2024 - JAN 18, 2025

\* NR - Not Reported