

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Gregory Gunther, Senior Manager, Vehicle Compliance and Analysis, Engineering Services
RE: Recall Campaign Launch Notification Replace Main Fuse Box(es) MY23-24 C-Class, CLE, E-Class, EQE, EQE SUV, EQS, EQS SUV, GLC, S-Class, and SL (206, 214, 223, 232, 236, 254, 294, 295, 296 and 297 platform)	DATE: March 21, 2024

IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Senior Manager, Vehicle Compliance & Analysis



Recall Campaign Launch Notification			March 21, 2024
Campaign No. :	NHTSA ID	Campaign Desc. :	Replace Main Fuse Box(es)
2024030008	24V115	24P8297011	
This is to notify you of the Recall Campaign Launch to replace the main fuse box(es) on 31,848 Model Year (“MY”) 2023-2024 C-Class, CLE, E-Class, EQE, EQE SUV, EQS, EQS SUV, GLC, S-Class, and SL (206, 214, 223, 232, 236, 254, 294, 295, 296 and 297 platform) vehicles. The recall campaign will be visible on the www.NHTSA.gov website and may generate questions from customers. Affected VINs will be flagged in VMI as “OPEN” on March 21, 2024 .			
Background			
Issue	Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2023-2024 C-Class, CLE, E-Class, EQE, EQE SUV, EQS, EQS SUV, GLC, S-Class, and SL (206, 214, 223, 232, 236, 254, 294, 295, 296 and 297 platform) vehicles, certain 80A fuses which were installed might not meet production requirements. As a result, a contact interruption or an increased triggering resistance might occur. In this case, systems connected to the fuse might become inoperable. The vehicle might also lose propulsion without warning, and restraint functions or the instrument cluster might be impaired, which could increase the risk of a crash or injuries. In addition, a risk of fire cannot be ruled out.		
What We’re Doing	MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will replace the respective main fuse box(es) on the affected vehicles.		
Parts	The remedy is available and can be performed.		
Vehicles Affected			
Vehicle Model Year(s)	2023-2024		
Vehicle Model	C-Class, CLE, E-Class, EQE, EQE SUV, EQS, EQS SUV, GLC, S-Class, and SL		
Vehicle Populations			
Total Recall Population	31,848		
Total Vehicles in Dealer Inventory	2,576		
Given this notice, it is a violation of Federal law for a dealer to sell or lease any new vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Once the remedy is available, the vehicles will be flagged as “OPEN” and Work Instructions will be available in NetStar VMI and Xentry Portal. Once the repair is complete, the vehicle may be sold or leased. Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired. As a matter of normal service process, please check for other repair measures which might be applicable to the vehicle(s). Additionally, given this notice, it is a violation of Federal Law for car rental companies to rent new vehicles covered by this notification until the vehicle has been repaired.			
Next Steps/Notes			
Customer Notification Timeline	Customer letters will be mailed on March 29, 2024.		
AOMS/SOMS	AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.		
Rental Fleet Partners	This recall may affect vehicles in your fleet. Please contact your respective MBUSA fleet representative for further information and next steps. For repairs, please contact your preferred MBUSA dealer.		
Customer Reimbursement	Customer reimbursement is not being offered for this campaign.		
While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.			



Recall Campaign Bulletin



Mercedes-Benz

Campaign No. 2024030008, March 2024

Revision B: December 6, 2024

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Various Models**
Model Year 2023 – 2024

Replace Fuse Box(es)

Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2023-2024 C-Class, CLE, E-Class, EQE, EQE SUV, EQS, EQS SUV, GLC, S-Class, and SL (206, 214, 223, 232, 236, 254, 294, 295, 296 and 297 platform) vehicles, certain 80A fuses which were installed might not meet production requirements. As a result, a contact interruption or an increased triggering resistance might occur. In this case, systems connected to the fuse might become inoperable. The vehicle might also lose propulsion without warning, and restraint functions or the instrument cluster might be impaired, which could increase the risk of a crash or injuries. In addition, a risk of fire cannot be ruled out. An authorized Mercedes-Benz dealer will replace the respective main fuse box(es) on the affected vehicles.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 31,848 vehicles are affected.

Order No. P-RC-2024030008

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Replace Fuse Box(es)

i **Modification notes:** Path for parts determination on model 232 updated below the parts table.

Work Procedure A

i For models 192, 206, 214, 223, 232, 236, and 254

1. Disconnect ground line of 12 V battery (**Figure 1**).

Nm Screw/nut, electric line to battery terminal of on-board electrical system battery: **6 Nm**.



Figure 1

2. Remove floor mat, remove trim (**Figure 2, A**) from A-pillar / passenger door sill panel, and fold back floor covering on right front footwell.

i **Step 2 is not required for model 232** - Only remove the molded part under the floor mat.



Figure 2

3. Unscrew nuts (**Figures 3, A**) of interior prefuse box cover and remove the cover.

i For model 232: Unscrew fuse box holder support (**Figure 4, A**) covering prefuse box (**Figure 4, B**), place to one side keeping electrical lines connected.




Figure 3, Interior prefuse box cover, shown on model 206




Figure 4, Support bracket (A), covering prefuse box (B), shown on model 232

4. Replace **interior** compartment prefuse box (**F150/2**).

-  For basic data on **models 192 and 232**, see AR54.15-P-1350SLY.
-  For basic data on **model 223**, see AR54.15-P-1350S.
-  For basic data on **models 206, 214, 236, and 254**, see AR54.15-P-1350WT.

 **Mounting nuts must be reused.**

 **M6** nut, positive line to vehicle interior prefuse box: **8 Nm**.

 **M8** nut, positive line to vehicle interior prefuse box: **16 Nm**.

 Torque specifications must be followed; Invoices for subsequent complaints are subject to debit!

 Connections of the electrical lines are shape-coded to match the prefuse box and cannot be mixed up.




Figure 5

5. Re-connect ground line of 12 V battery.

6. Read out and erase fault memory.

Replace Fuse Box(es)

Work Procedure B

i For models 294, 295, 296, and 297; non-AMG models.

1. Disconnect ground line of 12 V battery.

Hm Screw/nut, electric line to battery terminal of on-board electrical system battery: **6 Nm**.

2. Remove trim on A-pillar / door sill panel.

3. Replace **interior** prefuse box (**F150/7**).

i For basic data on **models 294, 295, 296, and 297**, see AR54.15-P-1350EQS.

- Step 1 – Remove floor covering on front passenger side, see:
 - AR68.80-P-0008EQD for **294** and **296**
 - AR68.80-P-0008EQS for **295** and **297**

i To make it easier to fold back the floor covering, the trim (Figure 6, C) and the stowage tray (Figure 6, D) in front of the center console must be partially removed.

i Mounting nuts must be reused.

Hm M6 nut, positive line to vehicle interior prefuse box: **8 Nm**.

Hm M8 nut, positive line to vehicle interior prefuse box: **16 Nm**.

i Torque specifications must be followed; Invoices for subsequent complaints are subject to debit!

i Connections of the electrical lines are shape-coded to match the prefuse box and cannot be mixed up.

i Positive lines are secured with additional cable ties.




Figure 6

4. Connect ground line of 12 V battery.

5. Read out and erase fault memory.

Replace Fuse Box(es)

Work Procedure C

WARNING – HV training required / HV power down must be performed by certified technician 

 For models 294, 295, 296, and 297; only AMG models.

 On AMG-EQ models, front prefuse box in the major assembly compartment is replaced in addition to the interior prefuse box.

1. Remove trim on A-pillar / door sill panel.

2. Replace **interior** prefuse box (F150/7).

 For basic data on **models 294, 295, 296, and 297**, see AR54.15-P-1350EQS.

- Step 1 – Remove floor covering on front passenger side, see:
 - AR68.80-P-0008EQD for **294** and **296**
 - AR68.80-P-0008EQS for **295** and **297**

 To make it easier to fold back the floor covering, the trim (Figure 6, C) and the stowage tray (Figure 6, D) in front of the center console must be partially removed (see Work Procedure B).

 Mounting nuts must be reused.

 M6 nut, positive line to vehicle interior prefuse box: **8 Nm**.

 M8 nut, positive line to vehicle interior prefuse box: **16 Nm**.

 Torque specifications must be followed; Invoices for subsequent complaints are subject to debit!

 Positive lines are shape-coded to match the prefuse box and cannot be mixed up.

 Positive lines are secured with additional cable ties.

3. Replace **front** prefuse box (F150/3).

  For basic data on **models 294, 295, 296, and 297**, see AR54.15-P-1330EQS.



Figure 7, HV electrical connectors with protective covers (001 589 06 91 00)

 Pay close attention that High Voltage electrical connectors for DC/DC converter are clean and free from coolant.

 Recommend performing **Step 4.2 prior to 4.1** of AR54.15-P-1330EQS to aid in removal of DC/DC converter.

NOTE: For AR54.15-P-1330EQS **Step 5**; disconnect electrical connections first, then unclip from bracket (**Figure 8**).




Figure 8

4. Re-connect ground line of 12 V battery.
5. Read out and erase fault memory.

Primary Parts Information

Qty.	Part Name	Part Number
1	Interior prefuse box	*
As required (1)	Front major assembly compartment prefuse box ONLY 294-AMG, 295-AMG, 296-AMG, 297-AMG	*
As required	Cable tie Only required for models 294, 295, 296, 297	A 000 995 90 06

* Prefuse boxes must be determined according to the vehicle identification number via XENTRY Portal Parts Information.

* The required **interior** prefuse box can be found in the XENTRY Parts Information under **main group 54 electrical equipment and instruments** in **picture chart 058 – control units / fuse boxes / relays in the vehicle interior** and **picture number (500 – model 232)**, (560 – models 206, 223, 254), (400 – model 214), (30 – model 236), (550 – model 294), (530 – models 295, 296, 297).

* The required **front** prefuse box can be found in XENTRY Parts Information under **main group 54 electrical equipment and instruments** in **picture chart 054 – control units / fuse boxes / relays in engine compartment – number 280**.

Old parts must be scrapped on site and **must not be reused**.

 Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

 **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
82 970 11	12-2055	Replace interior prefuse box Models: 192 and 232 Includes: Delete fault memory	1.0
	12-2055	Replace interior prefuse box Models: 206, 214, 223, 236, and 254 Includes: Delete fault memory	0.7
	12-2055	Replace interior prefuse box Models: 294, 295, 296, 297 (non-AMG) Includes: Delete fault memory	0.8
	12-2056	Replace interior and front major assembly compartment prefuse boxes Models: 294-AMG, 295-AMG, 296-AMG, 297-AMG Includes: Delete fault memory	ZM

 **Note:** Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.