News Channel Update

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Senior Manager, Vehicle		
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services		
RE: Recall Campaign Launch Notification			
Update Battery Management System Software –	DATE: lung 15, 2024		
Wave 2	DATE: June 15, 2024		
MY23-25 EQE and EQS (294, 295, 296, and 297)			

IMPORTANT RECALL CAMPAIGN UPDATE

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Senior Manager, Vehicle Compliance & Analysis



News Channel Update

Vehicle Compliance & Analysis

Recall Campaign Launch Notification			June 15, 2024		
Campaign No.:	NHTSA ID	Campaign Desc. :	Update Battery Management		
2024060002	24V372	24P5496226	System Software – Wave 2		
This is to notify you of the Recall Campaign Launch to update the Battery management System software on <u>15,351</u> Model Year ("MY") 2023-2025 EQE and EQS (294, 295, 296, and 297 platform) vehicles. The recall campaign will be visible on the www.NHTSA.gov website and may generate questions from customers. <u>13,351</u> Affected VINs were flagged in VMI as "OPEN" on <u>June 7, 2024</u> . An Additional <u>1,378</u> affected VINs will be flagged as "OPEN" on <u>June 15, 2024</u> .					
		Backgrou			
Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined to MY 2023-2025 EQE (294 and 295 platform) and EQS (296 and 297 platform) monitoring software of the Battery Management System ("BMS") might not production specifications and may lead to a shutdown of the high-voltage system situations. The contactors of the high-voltage battery might open, potentially resulting propulsion without warning. As a consequence, the risk of a crash might increase. When comes to a standstill it can be restarted.			nd 295 platform) and EQS (296 and 297 platform) vehicles, the Battery Management System ("BMS") might not meet current d may lead to a shutdown of the high-voltage system in specific the high-voltage battery might open, potentially resulting in a loss of s a consequence, the risk of a crash might increase. When the vehicle e restarted.		
What We're Doing		MBUSA will conduct a volunta software on the potentially af	ary recall. An authorized Mercedes-Benz dealer will update the BMS fected vehicles.		
Parts		The remedy is available and	d can be performed.		
		Vehicles Aff	ected		
Vehicle Model Year(s)		2023-2025			
Vehicle Model		EQE and EQS			
		Vehicle Popu	lations		
Total Recall Population		13,973 (Wave 1) + 1,378 (Wa	ve 2)		
Total Vehicles in Dealer	Inventory	543 (Wave 2)			
Given this notice, it is a violation of Federal law for a dealer to sell or lease any new vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Once the remedy is available, the vehicles will be flagged as "OPEN" and Work Instructions will be available in NetStar VMI and Xentry Portal. Once the repair is complete, the vehicle may be sold or leased.					
Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired. As a matter of normal service process, please check for other repair measures which might be applicable to the vehicle(s).					
Additionally, given this notice, it is a violation of Federal Law for car rental companies to rent new vehicles covered by this notification until the vehicle has been repaired.					
		Next Steps/	Notes		
Customer Notification T	imeline	Customer letters will be ma	ailed on or before June 28, 2024.		
AOMS/SOMS		AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.			
Rental Fleet Partners		This recall may affect vehicles in your fleet. Please contact your respective MBUSA fleet representative for further information and next steps. For repairs, please contact your preferred MBUSA dealer.			



Customer Reimbursement

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction.

Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Customer reimbursement is not being offered for this campaign.

Recall Campaign Bulletin



Campaign No. 2024060002, June 2024

Revision A: 6/14/2024

Recall Campaign Bulletin

Recall Campaign Bulletin

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model EQE and EQS (294, 295, 296, and 297 platform)

Model Year 2023 - 2025

Update Battery Management System Software – Wave 2

Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2023-2025 EQE (294 and 295 platform) and EQS (296 and 297 platform) vehicles, the monitoring software of the Battery Management System (BMS) might not meet current production specifications and may lead to a shutdown of the high-voltage system in specific situations. The contactors of the high-voltage battery might open, potentially resulting in a loss of propulsion without warning. As a consequence, the risk of a crash might increase. When the vehicle comes to a standstill it can be restarted. An authorized Mercedes-Benz dealer will update the BMS software on the potentially affected vehicles.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 15,351 vehicles are affected.

Order No. P-RC-2024060002

- Always use the latest XENTRY Diagnosis software release with all available add-ons.
 - Follow the operation steps exactly as described in XENTRY Diagnosis.
 - Use a battery charger to ensure sufficient power supply to the vehicle's **on-board electrical battery system** (greater than 12.5 V).
 - If XENTRY Diagnosis is already connected to the vehicle, start with Work Procedure Step 2.
- If two or more software updates or SCN codings are performed during single workshop visit, operation items 02-4762 and 02-5058 may be invoiced only on one of the workshop orders.

Work Procedure

- 1. Connect XENTRY Diagnosis.
- 2. Update Battery Management System (BMS) control unit software.

To do this, select menu item "Quick test view – N82/2 Battery management system (BMS) – Adaptations – Control unit update – Update of control unit software".

i Then follow the user guidance in XENTRY Diagnosis.

NOTE: To confirm the BMS software, the Software Version will read "23/XX" or newer in XENTRY Diagnosis (Figure 1).




Figure 1

3. Disconnect XENTRY Diagnosis.

Note: The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
54 962 26**	02-9334	Update Battery Management System (BMS) control unit software (with XENTRY Diagnosis connected)	0.1
	02-4762*	Connect/disconnect diagnostic system (XENTRY Diagnosis)	0.1
	02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1

Note: Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.

^{*} Invoice operation item only once for each workshop order.
** Requirement for punch times will be waived for this campaign.