

Safety Recall

N232426400 Tailgate May Open Unexpectedly



Release Date: February 2024

Revision: 00

Attention: Please note: The 2020-2023 model year Chevrolet Silverado 1500 and GMC Sierra 1500 VINs are for Canada only. These VINs are equipped with RPO Z49 (Canadian Base Equipment).

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

Vehicles involved in this recall were placed on stop delivery February 1, 2024. Once the service procedure contained in this bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

Until replacement parts are available, vehicles in inventory at dealerships may have the touchpad switch disabled. In addition, if a current owner requests that their vehicle's switch be disabled before replacement parts are available, dealers may also follow these instructions.

When replacement parts are available, disabled touchpad switch assemblies will be replaced through a separate customer satisfaction campaign.

The Notice to Customer at the end of this bulletin must be provided to the customer for all inventory vehicles sold to customers, and current owner's that had the main liftgate switch disable repair completed. **Note: Dealers should also retain a copy for their files.**

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Silverado 2500 HD/3500 HD	2020	2024		
GMC	Sierra 2500 HD/3500 HD	2020	2024		
Chevrolet	Silverado 1500 (Canada only)	2020	2023		
GMC	Sierra 1500 (Canada only)	2020	2023		

Involved vehicles are marked "Incomplete Remedy Not Available" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs. When replacement parts are available, VINs that did not have the touchpad switch assemblies disabled will be marked "Open" under this bulletin for the final parts repair.

Condition	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2020 - 2024 model year Chevrolet Silverado Heavy Duty (2500/3500 series) and GMC Sierra Heavy Duty (2500/3500 series) vehicles equipped with power-unlatching tailgates. Under certain conditions water may intrude into these vehicles' tailgates and come into contact with the electronic gate-release switch, potentially causing a short circuit. The gate may inadvertently unlatch while the vehicle is in Park. If the driver does not manually close the gate before beginning a drive, cargo in the bed of the truck may exit the vehicle and become a road hazard, increasing the risk of a crash. Until the recall is completed, owners should check that the tailgate closed and latched before driving.
Correction	Dealers will replace the exterior touchpad switch assemblies. Until replacement parts are available, vehicles in inventory at dealerships and owners who wish to do so may have the touchpad switch disabled. When replacement parts are available, disabled touchpad switch assemblies will be replaced through a separate customer satisfaction campaign.

Parts

Quantity	Part Name	Part No.
1	Red Duraseal Splice Sleeve (10 pack)	19300089

Important: Due to limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock. Please validate your shelf stock prior to ordering for this Recall.

Reminder: Parts may be removed from SPRINT and Retail Inventory Management (RIM) and be non-returnable. Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Safety Recall

N232426400 Tailgate May Open Unexpectedly



Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9107258	Disable Main Liftgate Switch Regular Tailgate Multi-Pro Tailgate (RPO EZ3) Add: if the vehicle is equipped with tailgate speaker accessory	0.4 0.3 0.1	ZFAT	*
9107259	Customer Reimbursement Approved - For USA and Canada dealers only	N/A	ZFAT	**
9107260	Customer Reimbursement Denied – For USA dealers only	N/A	ZFAT	***
9107261	Floor Plan Reimbursement – NEW INVENTORY ONLY	N/A	ZFAT	****
9107262	Working Capital Assistance Program Reimbursement – USED INVENTORY ONLY	N/A	ZFAT	*****

* The amount identified in “Net Item” should represent the actual sum total of the current GMCC&A Dealer net price for Splice Sleeve needed to perform the required repairs, not to exceed \$0.42 USD, \$0.57 CAD, plus applicable Mark-Up or Landed Cost (for Export).

Note: To avoid having to “H” route the customer reimbursement / floor plan / WCAP transaction for approval, it must be submitted prior to the repair transaction.

** For USA & Canada: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement. Submit \$20.00 USD (\$25.00 CAD) administrative allowance in Net/Admin Allowance.

*** Submit \$10.00 USD administrative allowance in Net/Admin Allowance.

Floor Plan Reimbursement – NEW INVENTORY ONLY

**** **USA & Canada Dealers Only** – For vehicles eligible for floor plan reimbursement, the amount should be submitted in Net Item/Miscellaneous. This amount should represent the product of the vehicle’s average daily interest rate (see table below) multiplied by the actual number of days the vehicle was in dealer inventory and not available for sale. This reimbursement is limited to the number of days from the date of the stop delivery message (February 1, 2024) to the date the repair is completed, and the vehicle is ready for sale (not to exceed 25 days).

Vehicle	Floor Plan Reimbursement Amount	
	USA	Canada
2020 Chevrolet Silverado 2500 HD/3500 HD	\$17.88	N/A
2021 Chevrolet Silverado 2500 HD/3500 HD	\$19.19	N/A
2022 Chevrolet Silverado 2500 HD/3500 HD	\$20.22	\$15.26
2023 Chevrolet Silverado 2500 HD/3500 HD	\$20.83	\$13.52
2024 Chevrolet Silverado 2500 HD/3500 HD	\$22.04	\$19.14
2020 GMC Sierra 2500 HD/3500 HD	\$19.68	N/A
2021 GMC Sierra 2500 HD/3500 HD	\$22.92	N/A
2022 GMC Sierra 2500 HD/3500 HD	\$23.15	\$13.68
2023 GMC Sierra 2500 HD/3500 HD	\$25.07	\$18.37
2024 GMC Sierra 2500 HD/3500 HD	\$26.34	\$18.78
2020 Chevrolet Silverado 1500	N/A	N/A
2021 Chevrolet Silverado 1500	N/A	N/A
2022 Chevrolet Silverado 1500	N/A	\$8.67
2023 Chevrolet Silverado 1500	N/A	\$16.03
2020 GMC Sierra 1500	N/A	N/A
2021 GMC Sierra 1500	N/A	N/A
2022 GMC Sierra 1500	N/A	\$12.97
2023 GMC Sierra 1500	N/A	\$15.79

Working Capital Assistance Program (WCAP) Reimbursement – USED INVENTORY ONLY

Note: USA & Canada Only - To avoid having to “H” route the WCAP transaction for approval, it must be submitted prior to the repair transaction.

Important: The WCAP ZSET transaction labor code, 9800127, provided in the dealer message sent on February 16, 2024, must have been submitted prior to the submittal of the ZFAT transaction labor code or the claim will reject.

Safety Recall

N232426400 Tailgate May Open Unexpectedly



***** **USA & Canada Dealers Only** - For vehicles eligible under the Working Capital Assistance Program, the amount should be submitted in Net Item/Miscellaneous. This amount has been calculated to a daily value for the days that the vehicle was in used dealer inventory and not available for sale. This reimbursement is limited to the number of days from the date of the stop sale/stop delivery order (February 1, 2024) to the date the inspection or repair closed the recall bulletin (not to exceed 25 days).

Vehicle	Working Capital Assistance Program Reimbursement Amount	
	USA	Canada
2020 Chevrolet Silverado 2500 HD/3500 HD	\$15.38	\$27.67
2021 Chevrolet Silverado 2500 HD/3500 HD	\$17.12	\$31.04
2022 Chevrolet Silverado 2500 HD/3500 HD	\$18.72	\$34.15
2023 Chevrolet Silverado 2500 HD/3500 HD	\$20.12	\$38.13
2024 Chevrolet Silverado 2500 HD/3500 HD	\$22.28	\$42.60
2020 GMC Sierra 2500 HD/3500 HD	\$16.55	\$28.06
2021 GMC Sierra 2500 HD/3500 HD	\$18.05	\$30.19
2022 GMC Sierra 2500 HD/3500 HD	\$18.48	\$33.21
2023 GMC Sierra 2500 HD/3500 HD	\$19.98	\$35.77
2024 GMC Sierra 2500 HD/3500 HD	\$29.70	N/A
2020 Chevrolet Silverado 1500	N/A	\$20.46
2021 Chevrolet Silverado 1500	N/A	\$21.35
2022 Chevrolet Silverado 1500	N/A	\$25.63
2023 Chevrolet Silverado 1500	N/A	\$30.13
2020 GMC Sierra 1500	N/A	\$21.46
2021 GMC Sierra 1500	N/A	\$22.98
2022 GMC Sierra 1500	N/A	\$30.00
2023 GMC Sierra 1500	N/A	\$32.98

Service Procedure


1. Remove the Liftgate Exterior Release Switch. Refer to *Liftgate Exterior Release Switch Replacement* in SI.



6554826

2. Cut the yellow wires close to the switch as shown, being sure to stagger the cuts by at least one inch.
3. Using red duraseal splice sleeves, cover the exposed harness end of both yellow wires.

Safety Recall
N232426400 Tailgate May Open Unexpectedly




6554952

4. Heat the sleeves until they have shrunk and sealed the wires completely.

Safety Recall

N232426400 Tailgate May Open Unexpectedly



6554953

5. (Multi-pro Tailgates Only) Zip tie the yellow harness to the blue harness as shown.
6. Reinstall the Liftgate Exterior Release Switch. Refer to *Liftgate Exterior Release Switch Replacement* in SI.
7. **The Notice to Customer at the end of this bulletin must be provided to the customer for all inventory vehicles sold to customers, and current owner's that had the main liftgate switch disable repair completed. Note: Dealers should also retain a copy for their files.**

Dealer Responsibility – For USA & Export (USA States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

Dealer Responsibility – All

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this recall must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

Safety Recall

N232426400 Tailgate May Open Unexpectedly



All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory you must take the steps necessary to ensure the program correction has been made before selling the vehicle. In addition, for vehicles entering your facility for service, you are required to ensure the customer is aware of the open recall and make every reasonable effort to implement the program correction as set forth in this bulletin prior to releasing the vehicle.

Dealer Reports – For USA & Export

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this recall. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall may be a violation of law in several states.

Courtesy Transportation – For USA & Canada

Courtesy transportation is available for customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual for courtesy transportation program details.

Customer Notification

USA & Canada - General Motors will notify customers of this recall on their vehicle.

Important: Please see the below Notice to Customer that must be provided to the customer upon sale of the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**

Safety Recall

N232426400 Tailgate May Open Unexpectedly



NOTICE TO CUSTOMER

This vehicle is equipped with a tailgate that is affected by a recently announced GM safety recall. On February 1, 2024, GM notified the National Highway Traffic Safety Administration and Transport Canada that under certain conditions water may intrude into these vehicles' tailgates and come into contact with the electronic gate-release switch, potentially causing a short circuit. The gate may inadvertently unlatch while the vehicle is in Park. If the driver does not manually close the gate before beginning a drive, cargo in the bed of the truck may exit the vehicle and become a road hazard, increasing the risk of a crash.

Your dealer has performed a repair on this vehicle that has disabled the main liftgate switch. A future customer satisfaction field action will be issued when replacement parts are available, and you will receive a letter to return to the dealer for a replacement switch.

Acknowledgement:

By signing this form, I understand and acknowledge that the dealer has performed a repair on this vehicle that has disabled the main liftgate switch.

Purchaser's Printed Name: _____

Purchaser's Signature: _____

VIN: _____

Dealership: _____

Fleet Account Number (FAN): _____

Date: _____

To be kept in deal jacket, vehicles' glovebox, and made available to GM upon request until the replacement switch is installed.

If you sell this vehicle before having the replacement switch installed, you should provide this notice to the buyer of your vehicle.

If you have any questions or need any assistance, please contact your dealer or the appropriate Customer Assistance Center at the number listed below.

For the hearing or speech impaired, please contact our Customer Assistance Center using the Telecommunication Relay Service by dialing 711 then providing the appropriate Customer Assistance Center number for your vehicle.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	1-800-833-2438
GMC	1-800-462-8782	1-800-833-2438
Puerto Rico – English	1-866-467-9700	
Puerto Rico – Español	1-866-467-9700	
Virgin Islands	1-866-467-9700	