



SIM 34 01 24

2025-02-20

RECALL 24V-104: INTEGRATED BRAKING SYSTEM (IB)

This Service Information Bulletin (Revision 7) replaces SI M34 01 24 **dated November 2024**.

What’s New:

- Correction updated (some previous part numbers deleted)
- Procedure updated
- Parts Information revised
- Claim Information revised
- Attachments for “Wet IB” and “Dry IB” from Revision 6 no longer needed

| | |
|--------------------------|--------------------------------|
| <input type="checkbox"/> | THIS REPAIR IS MOBILE FRIENDLY |
|--------------------------|--------------------------------|

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop if the campaigns have a status of remedy available. Otherwise, please release the vehicle.

MODEL

| E-Series | Model Description |
|----------|------------------------------|
| F65 | MINI Cooper S Hardtop 4 Door |
| F66 | MINI Cooper S Hardtop 2 Door |
| U25 | MINI Countryman |

AFFECTED VEHICLES

- Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary, or Warranty Vehicle Inquiry.
- Please make sure you check your dealer inventory as soon as possible. As of August 9, 2024, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

SITUATION

BMW AG is amending Voluntary Safety Recall (effective August 8, 2024) to add certain Model Year 2023 - 2025 MINI vehicles.

The Integrated Brake (IB) module may not function according to specifications. If this happens, a warning lamp and message will be displayed in the instrument cluster. There will be a reduction in power assist braking, which could lead to an extended stopping distance and increase the risk of a crash. The Antilock Brake System (ABS) and Dynamic Stability Control (DSC) system may also not function, which could affect vehicle handling and control. Please note that higher pedal force may be required.

The Recall Notice and FAQ have been attached for further information.

Important: For vehicle which received the In-Car/In-App Communication message, refer to SI M34 03 24 to claim the Repair Code in conjunction with the work performed in this SI M34 01 24, as this will remove the daily In-Car/In-App communications to the customer for this recall.

CAUSE

Certain vehicles could experience signal disturbances in the Integrated Brake (IB) module.


CORRECTION

Replace the IB with either a “wet” pre-filled unit or a “dry” unfilled unit.



“Wet” IB pre-filled: Brake fluid reservoir is filled (arrow) and brake fluid line ports are plugged with bolts (circled)

5B67B85



“Dry” IB unfilled: Brake fluid reservoir is empty; brake fluid line ports are sealed with labels.

Part numbers:
5B3C874

Note: Additional work is necessary to install these “Dry” units, refer to the Claim Information section.

PROCEDURE

If you have received a **“wet”** unit, follow the REP34 51 601 Replacing hydraulic unit.



If you have received a **“dry”** unit, follow the REP 34 51 602 Replacing the hydraulic unit (not filled).

Important:

Prior to connecting the negative battery cable as per the REP instructions follow up works step 23, manually fill the brake fluid reservoir to just below the rim of the filler, above the “MAX” mark. Reinstall the fluid reservoir cap and continue REP procedures

Failure to fill prior to battery connection may result in extended or additional bleeding procedures

PARTS INFORMATION

Use and invoice the applicable part numbers below.

YOCV Campaign Code for retailed & third party rental vehicles:

MINI = 3104649800

YOCV Campaign Codes for inventory & loaner vehicles:

MINI = 3104606529

Refer to the weekly Parts Matrix for the most up-to-date ordering information.

| Part Number | Description | Quantity |
|---------------------------|---|----------|
| | | |
| 34 50 5B67B85 | Power brake (WET unit) | 1 |
| Or | | |
| 34 50 5B3C874 | Power brake (DRY unit) | 1 |
| 34 50 5 A59 585 | Seal brake booster | 1 |
| 07 11 9 905 374 | Self-locking collar nut (M8-10 ZNS3) (rounds to 10) | 2 |
| Additional for U25 | | |
| 07 11 9 904 670 | Flange nut (M10-10-ZNS3) | 1 |
| 07 11 9 905 147 | Hex bolt with washer (M10x25-10.9 ZNS3) | 1 |

Sublet – Bulk Supply Materials

| Part Number | Description | Quantity |
|---------------|--|------------------|
| 81 22 0146735 | MINI Brake fluid DOT 4 (DN = 12 oz bottle) | Sublet as needed |
| Or: | | |
| 81 22 0142156 | Brake fluid DOT 4 (DN = 12 oz bottle) | Sublet as needed |
| Or: | | |
| 81 22 0142155 | Brake fluid DOT 4 (DN = 1 Gallon) | Sublet as needed |
| Or: | | |
| 81 22 5B43922 | Brake fluid DOT 4, LV (DN = 1/10-liter billing part number, only in conjunction with dispersing from the 30-liter drum with a separate ordering part number) | Sublet as needed |
| And: | | |
| 83 19 5A53089 | BMW Group Non-Chlorinated Brake Parts Cleaner- 3% VOC - (DN = 15 oz) | Sublet as needed |
| Or | | |
| 83 19 2451315 | BMW Group Non-Chlorinated Brake Parts Cleaner - 45% VOC - (DN = 15 oz) | Sublet as needed |

CLAIM INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the applicable work package information below, the additional work as required, and part numbers listed above that apply.

Important: For vehicle which received the In-Car/In-App Communication message, refer to [SI M34 03 24](#) to claim the Repair Code in conjunction with the work performed in SI M34 01 24, as this will remove the daily In-Car/In-App communications to the customer for this recall.

Copyright ©2025 MINI USA, a division of BMW of North America, LLC. All Rights Reserved

| | |
|-------------------------|--|
| Plusposition (+) | Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop |
| Main work | The vehicle arrives for this Recall, no other Main work will be performed/claimed during this workshop visit |

Only one Main work flat rate labor operation code can be claimed per workshop visit.

| | | |
|---------------------|-------------------|--|
| Repair Code: | 0034870200 | F6x J0x U25 Replace integrated braking system |
|---------------------|-------------------|--|

Below are the special flat rate labor operation code choices for this action.

IB Replacement with Vehicle Programming and Encoding

| Work Package | Labor Operation | Description | Labor Allowance |
|----------------|-----------------|--|-----------------|
| # 1 | 00 77 606 | Replace integrated brake system, program, and encode the vehicle control units, includes Carrying out vehicle test (00 00 556/61 21 528) (Plusposition) | As applicable |
| Or: | | | |
| # 2 | 00 77 072 | Replace integrated brake system, program, and encode the vehicle control units, includes Carrying out vehicle test (00 00 006/61 21 528) (Main work) | As applicable |
| As applicable: | | | |
| Expanded WP A | 00 77 609 | Additional work, brake bleeding procedure (for installation of an "Dry: unfilled IB) | 2 FRU |
| Expanded WP B | N/A | No longer applies | N/A |
| Expanded WP C | 00 77 832 | Additional work mileage check | 1 FRU |
| Expanded WP D | 00 77 641 | Additional work reprogramming | 5 FRU |

Or:

IB Replacement, Vehicle Programming and Encoding is included in another Repair.

| Work Package | Labor Operation | Description | Labor Allowance |
|--------------|-----------------|---|-----------------|
| #3 | 00 77 607 | Replace the integrated brake system (Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair during the same workshop visit) (Plusposition) | As applicable |
| Or: | | | |
| #4 | 00 77 073 | Replace the integrated brake system (Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair during the same workshop visit) (Main work) | As applicable |

| | | | |
|----------------|-----------|--|-------|
| As applicable: | | | |
| Expanded WP A | 00 77 609 | Additional work, brake bleeding procedure (for installation of an “Dry: unfilled IB) | 2 FRU |
| Expanded WP B | N/A | No longer applies | N/A |
| Expanded WP C | 00 77 832 | Additional work mileage check | 1 FRU |
| Expanded WP D | 00 77 641 | Additional work reprogramming | 5 FRU |

Vehicle Programming and Encoding Required after Part Replacement

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

After replacing the integrated brake (IB) system module, select this open Technical Campaign to also perform and submit for updating the vehicle to the required I-level or higher instead when applicable (This includes 00 00 006 or 00 00 556, 61 21 528, and 61 00 730).

Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

Or:

IB Replacement, Vehicle Programming and Encoding is included in another Repair.

| Work Package | Labor Operation | Description | Labor Allowance |
|--------------|-----------------|--|-----------------|
| # 5 | 00 77 610 | The vehicle has already been completed by another repair or technical action (Plusposition) | 1 FRU |
| Or: | | | |
| # 6 | 00 77 074 | The vehicle has already been completed by another repair or technical action (Main work) | 1 FRU |

Claim Repair Comments

Reference the SIB number, the work package (Pkg) number and the Expanded WPs performed in the technician’s RO notes and in the claim comments (For example: M34 01 24 WP1, A, C, D), unless otherwise required by State law.

Also, identify and explain when the “Dry” unit additional work, and what other additional work was required and performed.

Also, explain the additional work that was required and performed.

Sublet – Bulk Supply Materials (RO and Claim Comments Required)

| | | |
|----------------------|--|---------------|
| Sublet Code 4 | Reimbursement for the repair-related bulk supply materials (Do not use the MINI part numbers for claim submission) | Up to \$50.00 |
|----------------------|--|---------------|

Sublet reimbursement calculation for claiming the applicable repair-related bulk supply material (MINI part number) is at the dealer net (DN) price for the full or proportional quantity used plus your dealer’s handling.

BMW Group's AIR Application Resource for Flat Rate Labor Operation Codes

To obtain the corresponding flat rate unit (FRU) allowance information from the BMW Group AIR application resource, start by entering the Chassis Number (last seven (7) characters of the VIN), and click on the "Search" icon. If the "Vehicle Selection" window displays two or more model possible vehicle choices, select the applicable Model, or enter the full VIN (17 characters) instead to proceed. Click on the "Flat Rate Units" button and enter a flat rate labor operation code number "without spaces" in the field to the right, click on the "Search" icon to display the corresponding listing of "Flat rate unit group details" that are available and their corresponding FRU allowances.

Vehicle Programming and Encoding – Additional Work (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Repair Code in this bulletin together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the applicable Repair Code listed in AIR together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

(*) Based on which one applies to your dealer, please refer to **SI M01 01 20** or **M01 04 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your dealer performed, unless otherwise required by State law.

Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)

This Recall repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Repair Code noted above as follows:

Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to [SI M01 01 17](#) for additional information.

Reimbursement of Recall Remedy Comparable Prior Customer-Pay Repairs (TREAD Act)

The Safety Recall remedy repair for this action is to replace the Affected Vehicle's power brake unit (Integrated Brake IB module) together with performing the required follow-up vehicle programming and encoding procedure.

Based on the age of the Affected Vehicles and the type of remedy repair being performed, a reimbursement request for a qualifying prior customer-pay repair is not likely. However, a customer may still request the review of a repair that was performed on their vehicle which they paid for.

A qualifying customer pay repair, performed **prior** to the notification of Recall, must be comparable to the Recall's remedy repair, and it must primarily address the Service Information Bulletin's identified vehicle issue (Situation/Cause) which requires repair (Correction) as noted above. Also, the repair must have been correctly, effectively, and completely performed as required by the applicable BMW Group approved repair process instructions and guidelines (Procedure) including required replacement part usage (Parts Information) for it to be considered and approved for reimbursement.

In the event of the above situation, please contact the Warranty department (include a legible copy of the invoice) through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections. The Warranty department
Copyright ©2025 MINI USA, a division of BMW of North America, LLC. All Rights Reserved

will respond to your inquiry accordingly.

FEEDBACK REGARDING THIS BULLETIN

| | |
|--------------------|---|
| Technical Feedback | To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin |
| Warranty Feedback | To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal |

Supporting Materials

[picture_as_pdf M340124_24V-104-IB-MINI-FAQ-\(09Aug2024\).pdf](#)
[picture_as_pdf M340124 Recall Notice.pdf](#)

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Managers, Parts Managers and Warranty Processors

RE: Recall 24V-104: Integrated Braking System – M34 01 24

BMW AG is conducting a Voluntary Safety Recall (effective August 8, 2024) on certain Model Year 2025 MINI vehicles.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that Centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

Safety Recall
24V-104
Integrated Brake (IB)
Model Year 2025
MINI Hardtop Cooper (2 Door, 4 Door)
MINI Cooper Countryman
Issue Date: 08/09/2024

Q1. Which MINI models in the US are potentially affected by this Safety Recall?

Certain Model Year 2025 MINI Hardtop Cooper (2 Door, 4 Door), and MINI Cooper Countryman models, in the US are potentially affected.

Q2. What is the specific issue?

The Integrated Brake (IB) module may not function according to specifications. If this happens, a warning lamp and message will be displayed in the instrument cluster. There will be a reduction in power assist braking, which could lead to an extended stopping distance and increase the risk of a crash. The Antilock Brake System (ABS) and Dynamic Stability Control (DSC) system may also not function, which could affect vehicle handling and control. Please note that higher pedal force may be required.

However, fully mechanical braking is not affected. If the IB module is not functioning properly, the parking (emergency) brake will be automatically activated to aid in braking performance. Also, the emergency function of the brake force distribution system remains available to help maintain vehicle stability and control.

If you notice any of these conditions, your vehicle may be experiencing this issue. Please drive carefully, and avoid abrupt braking as much as possible. Please contact an authorized MINI dealer as soon as possible to have the vehicle remedied.

If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

Q3. Why are other models / vehicles not included in this Safety Recall?

Other models have an Integrated Brake (IB) system that was produced to specifications by the supplier.

Q4. Can I continue to drive my vehicle?

Yes. However, when you are notified by MINI of this Safety Recall that a remedy is available, please contact an authorized MINI dealer to schedule an appointment as soon as possible. For the latest updates to this Safety Recall, please visit miniusa.com/recall. **If you are not the only driver of this vehicle, please advise all other drivers of this important information.**

Q5. How did MINI become aware of the issue?

MINI became aware of the issue through its quality control procedures.

Q6. How will I be informed of this Safety Recall?

Owners of potentially affected vehicles will be notified via First Class mail advising them of this Safety Recall. When parts become available, they will receive another letter, requesting that they schedule an appointment with an authorized MINI dealer as soon as possible to have this Safety Recall performed. For the latest updates to this Safety Recall, please visit miniusa.com/recall.

To ensure MINI has the most up-to-date contact and vehicle information, owners should register their vehicle at miniusa.com/ol. Registration is free and will give them access to other information specific for their MINI vehicle. Alternatively, owners can visit miniusa.com/recall and click on “**Manage recall notices and contact information**”.

Q7. How will my vehicle be remedied?

When the remedy is available, potentially affected vehicles will have the Integrated Brake (IB) system replaced for free which should take several hours.

Q8. Do I have to wait for MINI to contact me to have the remedy performed?

Yes. We are in the process of implementing this Safety Recall to ensure that the necessary parts, tools, and procedures are available. For the latest updates to this recall, please visit miniusa.com/recall.

2025-02-20

This Service Information Bulletin (Revision 8) replaces SI B34 02 24 **dated November 2024**.

What’s New:

- Correction updated
- Procedure revised
- Parts Information updated
- Claim Information updated
- Attachments for “Wet IB” and “Dry IB” from Revision 7 no longer needed

| | |
|--------------------------|--------------------------------|
| <input type="checkbox"/> | THIS REPAIR IS MOBILE FRIENDLY |
|--------------------------|--------------------------------|

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop if the campaigns have a status of remedy available. Otherwise, please release the vehicle.

MODEL

| E-Series | Model Description |
|----------|--------------------------------|
| F95 | X5 M Sports Activity Vehicle |
| F96 | X6 M Sports Activity Coupe |
| G05 | X5 Sports Activity Vehicle |
| G06 | X6 Sports Activity Coupe |
| G07 | X7 Sports Activity Vehicle |
| G09 | BMW XM Sports Activity Vehicle |
| G60 | 5 Series Sedan & i5 Sedan |
| G70 | 7 Series Sedan & i7 Sedan |
| U10 | X2 Sports Activity Coupe |
| U11 | X1 Sports Activity Vehicle |

AFFECTED VEHICLES

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. As of August 9, 2024, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

Vehicles which previously had the Integrated Brake Module replaced according to B34 04 23 need to have the re-work performed again in accordance with the updated part numbers and procedure in this bulletin.

SITUATION

BMW AG is amending Voluntary Safety Recall (effective August 8, 2024) to add certain Model Year 2023 - 2025 BMW vehicles.

The Integrated Brake (IB) module may not function according to specifications. If this happens, a warning lamp and message will be displayed in the instrument cluster. There will be a reduction in power assist braking, which could lead to an extended stopping distance and increase the risk of a crash. The Antilock Brake System (ABS) and Dynamic Stability Control (DSC) system may also not function, which could affect vehicle handling and control. Please note that higher pedal force may be required.

The Recall Notice and FAQ have been attached for further information.

Important: For vehicles which received the In-Car/In-App Communication message, refer to SI B34 05 24 to claim the Defect Code in conjunction with the work performed in SI B34 02 24. This will remove the daily In-Car/In-App communications to the customer for this recall.

CAUSE

Certain vehicles could experience signal disturbances in the Integrated Brake (IB) module.

CORRECTION

Replace the IB with either a “wet” pre-filled unit or a “dry” unfilled unit.



“Wet” IB pre-filled: Brake fluid reservoir is filled (arrow) and brake fluid line ports are plugged with bolts (circled).

Part numbers:

5B67B85

5B6E463

5B6E467

5B69D65


5B69D61

5B69D63

5B72715

5B72716

5B6F947



“Dry” IB unfilled: Brake fluid reservoir is empty; brake fluid line ports are sealed with labels.

Part numbers:

5B3C874

5B3C857

5B421D0

5B6C7F2

5B6C7F3

5B6C7F5

Note: Additional work is necessary to install these “Dry” units. Refer to the Claim Information section.

PROCEDURE

If you have received a “**wet**” unit, follow the REP34 51 601 Replacing hydraulic unit



If you have received a “**dry**” unit, follow the REP 34 51 602 Replacing the hydraulic unit (not filled).

Important:

Prior to activating the high-voltage or low-voltage electrical system as per the REP instructions, manually fill the brake fluid reservoir to just below the rim of the filler, above the “MAX” mark.

Reinstall the fluid reservoir cap and continue REP procedures

Failure to fill prior to battery connection may result in extended or additional bleeding procedures

Important Warning for Working on the High-Voltage (HV) systems on BMW Group vehicles:

Only properly trained personnel, who passed all applicable HV Technical Training Courses, should perform repairs which require disconnecting, or removal of High Voltage battery components on any Hybrid or Electric Vehicle. Work performed on High Voltage systems by unqualified persons may result in severe injury or damage to the vehicle. Additional safety information is found in Repair Instruction 61 00... “Observe safety instructions when handling electric vehicles”.

Prior to disconnecting, or the removal of any HV component, the HV system needs to be disabled and secured (by means of the HV Service Disconnect Switch and lock out) by a properly trained HV

Copyright ©2025 BMW of North America, Inc.

Course “ST2324 High Voltage Drivetrain Systems” which as of 1/2023* includes ST1824 Alternative Drive Part 1.

*** Note: As of January 2023, the HV component portion of the “ST2205 Generation 5 High-voltage class” (except for the High Voltage Battery) has been merged into “ST2324 High Voltage Drivetrain Systems”.**

Up to Generation 4 Vehicles- Once vehicle’s HV system is disabled (the “Blitz” - lightning bolt icon is displayed in instrument cluster, see below), a technician without HV Certification may remove a HV component (e.g., EH Heater, EKK Compressor, EME Control Unit, et.), except for the High Voltage Battery.

For Generation 5 Vehicles however, the specific vehicle training is required to diagnose, remove and service any HV component and it is NOT allowed for non HV certified technicians to work on the high voltage system.

High Voltage Battery removal and rework can ONLY be performed by a High-voltage Certified Technician with a HV Battery Certification level corresponding to a specific Electric or Hybrid vehicle, for example:

To repair GEN4 HV battery of G05 PHEV a certification from Technical Training Course “ST2006 – SP44 HV Battery” or equivalent ST1825 – Alternative Drive Part 2 is required (or as of 1/2023 the equivalent “ST 2325 for High Voltage Battery Systems”).

And

To repair A GEN5 HV battery the Technical Training Course “ST2205 Generation 5 High-voltage class” is required or as of 1/2023* the equivalent “ST 2325 for High Voltage Battery Systems”.

***Note: As of January 2023, the “ST2205 Generation 5 High-voltage stand-alone class” has been merged into “ST2324 for High Voltage Drivetrain Systems” and “ST2325 for High Voltage Battery Systems”**

PARTS INFORMATION

Use and invoice the applicable part numbers below.

YOCV Campaign Codes for retailed & third party rental vehicles:

Uxx = 3104638921

F9x G0x = 3104662202

G60 = 3104635889

G70 = 3104635890

YOCV Campaign Codes for inventory & loaner vehicles:

Uxx = 3104718965

F9x G0x = 3104718963

G60 = 3104688881

G70 = 3104663630

Refer to the weekly Parts Matrix and the FlowCode for the most up-to-date ordering information.

| Series | Part Numbers | Description | Quantity |
|------------------------------|-------------------------|------------------------------|---|
| U10, U11 | | | |
| | OR | | |
| | 34 50 5B67B85 | Power brake (WET unit) | 1 |
| | OR | | |
| | 34 50 5B3C874 | Power brake (DRY unit) | 1 |
| | 34 50 5A59585 | Brake booster seal | 1 |
| | 07 11 9905374 | Self-locking collar nut | 2 |
| | 07 11 9904670 | Self-locking collar nut | 1 |
| | 07 11 9905147 | Hexagonal screw with disc | 1 |
| | | | |
| F95, F96, G05, G06, G07, G09 | | | |
| | OR | | |
| | 34 50 5B69D63 | Power brake (WET unit) | 1 |
| | OR | | |
| | 34 50 5B6E467 | Power brake (WET unit) | 1 |
| | OR | | |
| | 34 50 5B6F947 | Power brake (WET unit) | 1 |
| | OR | | |
| | 34 50 5B421D0 | Power brake (DRY unit) | 1 |
| | OR | | |
| | 34 50 5B6C7F5 | Power brake (DRY unit) | 1 |
| | 34 51 6893390 | Brake booster seal | 1 |
| 07 14 6890655 | Self-locking collar nut | 2 | |
| | | | |
| G60 | | | |
| | OR | | |
| | 34 50 5B69D61 | Power brake (WET unit) | 1 |
| | OR | | |
| | 34 50 5B3C859 | Power brake (DRY unit) | 1 |
| | OR | | |
| | 34 50 5B6C7F3 | Power brake (DRY unit) | 1 |
| | 34 51 6893390 | Brake booster seal | 1 |
| | 07 11 9904295 | Self-locking collar nut | 2 |
| | 71 24 5A54A84 | Sign (aka label) brake fluid | 1 |
| | 51 71 6966566 | Hexagonal screw with flange | Up to 4 Depending on type of strut brace |
| | 51 64 8076922 | Hexagonal screw with disc | Up to 4 Depending on type of strut brace |
| | | | |
| G70 | | | |
| | OR | | |
| | 34 50 5B69D65 | Power brake (WET unit) | 1 |
| | OR | | |
| | 34 50 5B6E463 | Power brake (WET unit) | 1 |

| | | | |
|--|---------------|------------------------------|---|
| | | OR | |
| | 34 50 5B3C857 | Power brake (DRY unit) | 1 |
| | | OR | |
| | 34 50 5B6C7F2 | Power brake (DRY unit) | 1 |
| | 34 51 6893390 | Brake booster seal | 1 |
| | 07 11 9904295 | Self-locking collar nut | 2 |
| | 71 24 5A54A84 | Sign (aka label) brake fluid | 1 |
| | 51 71 6966566 | Hexagonal screw with flange | Up to 4 depending on type of strut brace |
| | 51 64 8076922 | Hexagonal screw with disc | Up to 4 depending on type of strut brace |

[AM2]

Sublet – Bulk Supply Materials

| Part Number | Description | Quantity |
|---------------|--|------------------|
| 81 22 0142156 | Brake fluid DOT 4 (DN = 12 oz bottle) | Sublet as needed |
| Or: | | |
| 81 22 0142155 | Brake fluid DOT 4 (DN = 1 Gallon) | Sublet as needed |
| And: | | |
| 81 22 5B43922 | Brake fluid DOT 4, LV (DN = 1/10-liter billing part number, only in conjunction with dispersing from the 30-liter drum with a separate ordering part number) | Sublet as needed |
| 83 19 5A53089 | BMW Group Non-Chlorinated Brake Parts Cleaner- 3% VOC - (DN = 15 oz) | Sublet as needed |
| Or: | | |
| 83 19 2451315 | BMW Group Non-Chlorinated Brake Parts Cleaner - 45% VOC - (DN = 15 oz) | Sublet as needed |

CLAIM INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the applicable work package information below, the additional work as required, and part numbers listed above that apply.

Important: For vehicles which received the In-Car/In-App Communication message, refer to SI B34 05 24 to claim the Defect Code in conjunction with the work performed in SI B34 02 24. This will remove the daily In-Car/In-App communications to the customer for this recall.

| | |
|-------------------------|--|
| Plusposition (+) | Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop |
| Main work | The vehicle arrives for this Recall, no other Main work will be performed/claimed during this workshop visit |

Only one Main work flat rate labor operation code can be claimed per workshop visit.

| | | |
|--------------|------------|---|
| Repair Code: | 0034860200 | Fx Gx Ux Replacing integrated braking system |
|--------------|------------|---|

Below are the special flat rate labor operation code choices for this action.

IB Replacement with Vehicle Programming and Encoding

| Work Package | Labor Operation | Description | Labor Allowance |
|----------------|-----------------|--|-----------------|
| # 1 | 00 77 599 | Replace integrated brake system, program, and encode the vehicle control units, includes Carrying out vehicle test (00 00 556/61 21 528) (Plusposition) | As applicable |
| Or: | | | |
| # 2 | 00 77 067 | Replace integrated brake system, program, and encode the vehicle control units, includes Carrying out vehicle test (00 00 006/61 21 528) (Main work) | As applicable |
| As applicable: | | | |
| Expanded WP A | 00 77 604 | Additional work, brake bleeding procedure (for installation of an "Dry" unfilled IB) | 2 FRU |
| Expanded WP B | N/A | No longer applies | N/A |
| Expanded WP C | 00 77 831 | Additional work mileage check | 1 FRU |
| Expanded WP D | 00 77 639 | Additional work reprogramming | 5 FRU |

Or:

IB Replacement, Vehicle Programming and Encoding is included in another Repair.

| Work Package | Labor Operation | Description | Labor Allowance |
|--------------|-----------------|---|-----------------|
| #3 | 00 77 600 | Replace the integrated brake system (Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair during the same workshop visit) (Plusposition) | As applicable |
| Or: | | | |

| | | | |
|----------------|-----------|--|---------------|
| #4 | 00 77 068 | Replace the integrated brake system (Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair during the same workshop visit) (Main work) | As applicable |
| As applicable: | | | |
| Expanded WP A | 00 77 604 | Additional work, brake bleeding procedure (for installation of an “Dry” unfilled IB) | 2 FRU |
| Expanded WP B | N/A | No longer applies | N/A |
| Expanded WP C | 00 77 831 | Additional work mileage check | 1 FRU |
| Expanded WP D | 00 77 639 | Additional work reprogramming | 5 FRU |

Vehicle Programming and Encoding Required after Part Replacement

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

After replacing the integrated brake (IB) system module, select this open Technical Campaign to also perform and submit for updating the vehicle to the required I-level or higher instead when applicable (this includes 00 00 006 or 00 00 556, 61 21 528, and 61 00 730).

Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

Or:

IB Repair Completed by another Repair or Technical Action

| Work Package | Labor Operation | Description | Labor Allowance |
|--------------|-----------------|--|-----------------|
| # 5 | 00 77 605 | The vehicle has already been completed by another repair or technical action (Plusposition) | 1 FRU |
| Or: | | | |
| # 6 | 00 77 071 | The vehicle has already been completed by another repair or technical action (Main work) | 1 FRU |

Claim Repair Comments

Reference the SIB number, the work package (Pkg) number and the Expanded WPs performed in the technician's RO notes and in the claim comments (For example: R34 02 24 WP1 A C D) unless
Copyright ©2025 BMW of North America, Inc.

otherwise required by State law.

Also, identify and explain when the “Dry” unit additional work, and what other additional work was required and performed.

Sublet – Bulk Supply Materials (RO and Claim Comments Required)

| | | |
|----------------------|--|---------------|
| Sublet Code 4 | Reimbursement for the repair-related bulk supply materials (Do not use the BMW part numbers for claim submission) | Up to \$50.00 |
|----------------------|--|---------------|

Sublet reimbursement calculation for claiming the applicable repair-related bulk supply material (BMW part number) is at the dealer net (DN) price for the full or proportional quantity used plus your center’s handling.

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section.

BMW Group’s AIR Application Resource for Flat Rate Labor Operation Codes

To obtain the corresponding flat rate unit (FRU) allowance information from the BMW Group AIR application resource, start by entering the Chassis Number (last seven (7) characters of the VIN), and click on the “Search” icon. If the “Vehicle Selection” window displays two or more model possible vehicle choices, select the applicable Model, or enter the full VIN (17 characters) instead to proceed.

Click on the “Flat Rate Units” button and enter a flat rate labor operation code number “without spaces” in the field to the right, click on the “Search” icon to display the corresponding listing of “Flat rate unit group details” that are available and their corresponding FRU allowances.

Vehicle Programming and Encoding – Additional Work (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Repair Code in this bulletin together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the applicable Repair Code listed in AIR together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

(*) Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)

This Recall repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Repair Code noted above as follows:

Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to [SI B01 29 16](#) for additional information.

Reimbursement of Recall Remedy Comparable Prior Customer-Pay Repairs (TREAD Act)

The Safety Recall remedy repair for this action is to replace the Affected Vehicle’s power brake unit (Integrated Brake IB module) together with performing the required follow-up vehicle programming and encoding procedure.

Based on the age of the Affected Vehicles and the type of remedy repair being performed, a reimbursement request for a qualifying prior customer-pay repair is not likely. However, a customer may still request the review of a repair that was performed on their vehicle which they paid for.

A qualifying customer pay repair, performed **prior** to the notification of Recall, must be comparable to the Recall’s remedy repair, and it must primarily address the Service Information Bulletin’s identified vehicle issue (Situation/Cause) which requires repair (Correction) as noted above. Also, the repair must have been correctly, effectively, and completely performed as required by the applicable BMW Group approved repair process instructions and guidelines (Procedure) including required replacement part usage (Parts Information) for it to be considered and approved for reimbursement.

In the event of the above situation, please contact the Warranty department (include a legible copy of the invoice) through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections. The Warranty department will respond to your inquiry accordingly.

FEEDBACK REGARDING THIS BULLETIN

| | |
|--------------------|---|
| Technical Feedback | To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin |
| Warranty Feedback | To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal |
| Parts Feedback | To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department |

Supporting Materials

[picture_as_pdf B34 02 24_RECALL 24V-104_INTEGRATED BRAKING SYSTEM_SR.pdf](#)
[picture_as_pdf B340224 Recall Notice.pdf](#)

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Managers, Parts Managers and Warranty Processors

RE: Recall 24V-104: Integrated Braking System – B34 02 24

BMW AG is amending Voluntary Safety Recall (effective August 8, 2024) to add certain Model Year 2023 - 2025 BMW vehicles.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that Centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.