

Recall Campaign Bulletin



Mercedes-Benz

Campaign No. 2024050001, May 2024

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model GL-Class, ML-Class, and R-Class (X164, W164 and 251 platform)
Model Year 2006 – 2012**

Inspect Brake Booster – without Pedal Rework

Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2006-2012 ML-Class, GL-Class, and R-Class (164 and 251 platform) vehicles, the function of the brake booster might be affected due to advanced corrosion in the joint area of its housing. After extended time in the field and in conjunction with prolonged water exposure, this corrosion might lead to a vacuum leak at the brake booster. If this were to occur, the brake force support might be reduced, leading to an increase in the brake pedal forces required to decelerate the vehicle, and/or increased stopping distances. Additionally, in rare cases of very severe corrosion, it might be possible for a particularly strong or hard brake application to cause mechanical damage in the brake booster, whereby the connection between brake pedal and brake system would fail. In such a very rare case, it would not be possible to decelerate the vehicle via the brake pedal. The risk of a crash or injury would be increased. The function of the parking brake is not affected by this issue. Before the issue occurs, the driver might notice a change in the brake pedal feel and/or hissing/airflow noises when applying the brake pedal. An authorized Mercedes-Benz dealer will remove the rubber sleeve from the brake booster housing, inspect the brake booster on the affected vehicles and, depending on the result of this inspection, replace as necessary.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 11,993 vehicles are affected.

Order No. P-RC-2024050001

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Inspect Brake Booster – without Pedal Rework

- i** Existing problems that would hinder the inspection procedure or any subsequent repairs must first be rectified and are the responsibility of the customer. Any associated costs are not claimable and should not be included with the campaign claim.
- i** Before starting work, the vehicle must have no fault message present in the instrument cluster for the brake system. If a fault message is present before starting work, it must be rectified and is the responsibility of the customer. Any associated costs are not claimable and should not be included with the campaign claim.
- i** The single rubber **band no longer** needs to be packed and returned. The rubber bands are no longer needed and can be disposed of.
- i** If a vehicle comes in with **no serial code** on the brake booster unit and/or the **brake booster is not the same color** as in the work instruction pictures, open a TIPS case for verification of aftermarket booster and further processing.

Check/Test Procedure A – visual inspection only

1. Open the hood and check the water drains (**Figure 1, 1**) for correct installation and ability to drain.
 - i** Only for model 251
 - i** Clean and correctly install water drains if necessary.



Figure 1

2. Remove the rubber sleeve wrapped around the brake booster (**Figure 2, A**) with a suitable tool (hook and side cutting pliers).
 - i** If the rubber sleeve on the brake booster is missing or **not** present, then continue with **Check/Test Procedure A1**.
 - i** The rubber sleeve should be separated above the barcode label on the brake booster as seen in (**Figure 2, A**).




Figure 2

3. Take a photo of the rubber sleeve with the VIN label of the B-pillar (**Figures 3 and 4, A**) and store to a local HDD/computer storage location with the vehicle service file and attach it to the warranty claim in EVA.
 - i** These pictures serve as documentation of the current condition of the brake booster.



Figure 3




Figure 4

4. Check corrosion of the brake booster using the removed rubber sleeve.

i Use (Figures 5, 6 and 7) to assess corrosion.

i **Brake booster (OK):**

Multiple point-shaped corrosion marks (Figure 5) are permissible.

A maximum of **one point-shaped corrosion mark** with a diameter **greater than 15 mm** (Figures 6 and 7) is permitted.



Figure 5 (OK)




Figure 6 (OK)



Figure 7 (OK)

i **Brake booster (Not OK):**

Widespread corrosion marks spanning the rubber sleeve are not permissible.

More than one corrosion mark with a diameter greater than 15 mm is not permissible.

- Corrosion measurements **Exceeds thresholds - Not OK:** Carry out **Work Procedure**
- Corrosion measurements **Does not exceed threshold - OK** (Figures 5, 6 or 7): **End measure.**

i If the measure is ended, **do not** re-install a rubber sleeve. Apply marking with **white touch-up paint pen** (Figure 10, 1) to the brake booster checked.

i **Under no circumstances should you treat the brake booster with anti-corrosion agent.**

i The **findings** from the **Check/Test Procedure** must be **documented on the Repair Order** and included in the **dealer text in the warranty claim** in EVA.

Check/Test Procedure A1 – visual inspection only if rubber sleeve is *not* present

i Only if the rubber sleeve of the brake booster is missing.

1. Take a photo of the barcode label (**Figure 8, B**) on the brake booster and store to a local HDD/computer storage location with the vehicle service file and attach to the warranty claim in EVA.



Figure 8

2. Check sequence of numbers on the barcode label (**Figure 9, C**).
 - a. If the numeric sequence between the 13th and 17th digits (**Figure 9, C**) are **less than** "15126": Carry out **Work Procedure** below.
 - b. If the numeric sequence between the 13th and 17th digits (**Figure 9, C**) are **greater than or equal to** "15126": **End measure**.



Figure 9

3. Apply marking with **white touch-up paint pen** (**Figure 10, 1**) to the inspected brake booster.
 - i** Under no circumstances should you treat the brake booster with anti-corrosion agent/paint.



Figure 10

Work Procedure

i To prepare for the **Work Procedure**, the **Mercedes-Benz PartScan** app must be installed on an Apple® iPhone® or Android® smartphone.

i A mobile Internet connection is required for installing and transmitting the data.

i Download the app from the Apple® Store for iPhone® or Google® Play for Android® (download is similar to other apps).

After downloading, a one-time login authentication must be performed via an encrypted QR code (follow instructions on screen).

The required QR code (**Figure 11**) can be scanned here from the work instructions.

Ensure that only authorized workshop personnel have access to the QR code!



Figure 11 – QR Code

The use of the **Mercedes-Benz PartScan** app is recommended to simplify redocumentation and avoid input errors.

i If the PartScan app cannot be used, an XSF ticket for the documentation must be created and noted on the workshop order.

i In the case of a redocumentation with the **Mercedes-Benz PartScan** app, no additional documentation must be carried out in VeDoc.

i The new brake booster contains a small parts kit (**Figure 12**).



Figure 12

1. Replace brake booster.

i **Model 164:** For basic data, see **AR43.10-P-0350GZ**.

Model 251: For basic data, see **AR43.10-P-0350RT**.

i The BAS diaphragm travel sensor **must** be reused.

2. Once the old brake booster has been removed from the vehicle, transfer the BAS diaphragm travel sensor to the new brake booster.

i **Model 164:** For basic data, see **AR42.31-P-6002GZ**.

i **Model 251:** For basic data, see **AR42.31-P-6002RT**.

3. Check for correct function of brake lights.

4. Read out serial number (**Figure 13**) using the **Mercedes-Benz PartScan** app.

i The serial number is automatically entered in VeDoc. Verify the VIN reads from the vehicle correctly.



Figure 13

Primary Parts Information

Qty.	Part Name	Part Number
1	Brake booster	A 251 430 00 00
As required	Brake fluid	*

* The replacement parts must be determined according to the equipment variant for the vehicle identification number via the parts process in the Xentry Portal.

i Small parts such as screws/bolts, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Warranty Information

i **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

Damage Code	Operation Number	Description	Labor Time (hrs.)
42 900 17	12-2142	Check/Test Procedure A Check brake unit Includes: Remove rubber sleeve from brake unit and document test result This operation number can be used even if no rubber sleeve is present on the brake unit	0.2
	12-2143	Check/Test Procedure A1 Check barcode on brake unit Only if no rubber sleeve is present on the brake unit	0.1
	12-2144	Replace brake unit (after check) Model 164 Includes: Modify travel sensor for brake unit and bleed brake system	2.0
	12-2144	Replace brake unit (after check) Model 251 Includes: Modify travel sensor for brake unit and bleed brake system	2.4

i **Note:** Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.