	Tesla, Inc. Service Bulletin	Replace Wiper Motor Assembly		V	
SB-24-17-006 July 2, 2024					
Classification		Section/Group	Mobile Service	Configuration	
Recall Bulletin		17 - Electrical	Can Perform (where permitted)	All	
Model	Model Year	Country/Region	Build Location	Build Location	
Cybertruck	2024	United States	Giga Texas		

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

On certain Cybertruck vehicles, the front windshield wiper motor controller may stop functioning due to electrical overstress to the gate driver component.

Correction

Replace the wiper motor assembly with an undamaged part.

E NOTE: If this bulletin is applicable to the vehicle, perform the correction without any need for inspection.

Correction Des	scription	Correction	Time	
Replace Wiper M	otor Assembly		S012417006	0.30
	Part Number	Description		Quantity
Parts Required	1853250-00-B	ASSEMBLY, WIPER MOTOR	R, CYBERTRUCK	1
	This part number was on specified in the Parts C	se the revision listed or later, unless of	therwise	
Special Tools	1853255-97-D 1565836-00-A	WIPER ARM REMOVAL TO HC18 PRESSURE/TEMP SE		

Procedure

- 1. Order a new wiper motor assembly and inspect the Batch Number on the new wiper motor.
 - If digits 4–8 of the Batch Number (Figures 1 and 2) is "24145" or greater, continue to the next step.
 - If digits 4–8 of the Batch Number is "24144" or less, reject and send this wiper motor to the Material Review Board (MRB). Order a new wiper motor with Batch Number 24145 or greater, and then proceed with installation.



Figure 1 – Batch Number




Figure 2 – Digits 4-8 of Batch Number

2. Replace the wiper motor assembly (refer to Service Manual procedure 1750135022).