



HYUNDAI Technical Service Bulletin

GROUP RECALL	NUMBER 24-01-078H
DATE SEPTEMBER 2024	MODEL(S) TUCSON (NX4M)

SUBJECT: SRS WARNING LABEL APPLICATION FOR GLOVE BOX
(RECALL 268)

* IMPORTANT

Vehicle repairs related to safety recalls are critically important and must be performed properly in accordance with TSB procedures. Review this bulletin in its entirety prior to beginning any repair work.

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must also perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

Access the "Vehicle Information" screen via WebDCS to identify open recalls.

Description: Certain 2025MY Tucson (NX4M) vehicles may not have a passenger-side Supplemental Restraint System (SRS) label affixed to the glove compartment box. As such, the affected vehicles fail to comply with the label requirement set forth in Federal Motor Vehicle Safety Standard No. 208, "Occupant Crash Protection". This bulletin provides instructions to apply the SRS warning label to the edge of the glove box, ensuring the label is properly positioned and visible.

Applicable Vehicles (Certain):

- 2025MY Tucson (NX4M) produced from 06/07/2024 – 07/30/2024

Parts Information:

Model	Part Name	Part Number	Figure	Remarks
Tucson (NX4M)	Label-C/Pad (Airbag Warning)	85261-2D700		Qty: 1 Labels were sent to dealers who had affected vehicles in their inventory at the start of this recall.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

Warranty Information:

Model	Op. Code	Operation	Op. Time	Casual Part	Nature Code	Cause Code
Tucson (NX4M)	241M08R0	Glove Box SRS Warning Label Application	0.2 M/H	85261-2D700	B1B	ZZ3

NOTE 1: Submit claim on Claim Entry Screen as “Campaign” type.

NOTE 2: If a part is found in need of replacement while performing this campaign and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

NOTE 3: This TSB includes Repair validation photos. Op times include VIN, Mileage, and Repair validation photo(s) as outlined in the Digital Documentation Policy.


Service Procedure:

STUI




This TSB includes Repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

1. Locate the SRS warning label (A).



2. Remove the tape cover.




3. Apply the label to the center edge of the glove box.

Press firmly to ensure the label properly adheres.



4. Close the glove box.



- 5.

STUI



Using STUI, take a photo of the warning label installed with the last 6 digits of the VIN and the date of repair on a piece of paper.

Upload the photo to STUI.

