

F/CMVSS Noncompliance Recall

N242474600 Missing Certification Label



Release Date: December 2024

Revision: 01

Revision Description: This bulletin is being revised to add the customer letter. Please discard all previous copies of N242474600.

Attention: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

For EV Involved Vehicles: The repairs outlined in this bulletin must only be completed at an authorized EV dealer and repairs must be performed by a technician who has successfully completed the applicable technical training required to perform this repair.

Make	Model	Model Year		RPO	Description
		From	To		
Buick	Envision	2024	2024		

Involved vehicles are marked "Open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	General Motors has decided that certain 2024 model year Buick Envision vehicles fail to conform to S4.3.3 of Federal Motor Vehicle Safety Standard (FMVSS) No. 110 "Tire Selection and Rims." These vehicles are missing the label that provides the tire size and cold tire pressure for the front and rear tires and the gross vehicle weight ratings. Without tire and gross vehicle weight rating information available on the label, there is a risk that customers may overinflate or underinflate their tires or exceed the recommended weight ratings, increasing the risk of a crash. Additionally, the Vehicle Emissions Control Information (VECI) label may not have been installed, as required by EPA regulations.
Correction	Dealers will install the missing labels.

Parts

Quantity	Part Name	Part No.
1	Certification Label	19355584
1	Emissions Label	19354745

Note: Both labels are VIN specific. Order the labels through the EPC and enter the VIN number in the order field. A VIN is needed for BOTH label orders. For ordering issues, email gmcert@duramarkusa.com.

Warranty Information


Labor Operation	Description	Labor Time	Trans. Type	Net Item
9107640	Label Installation	0.3	ZFAT	N/A

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

F/CMVSS Noncompliance Recall

N242474600 Missing Certification Label




6740361

1. Locate the Vehicle Emission Control Information Label location on the underside of the hood, to the left of the hood latch (yellow outline above). Ensure that the label surface and the area surrounding the label is clean and dry. Use a non-oil based cleaner, preferably isopropyl alcohol (rubbing alcohol) to clean the label surface and the area surrounding the label.
2. Remove the backing from the new label.
3. Apply the label in the location shown and smooth the label from the center out.
4. Close the hood.

F/CMVSS Noncompliance Recall

N242474600 Missing Certification Label



6740362

5. Open the driver's side door and locate the Vehicle Certification Label location at the bottom of the B pillar behind the door. Ensure that the label surface and the area surrounding the label is clean and dry. Use a non-oil based cleaner, preferably isopropyl alcohol (rubbing alcohol) to clean the label surface and the area surrounding the label.
6. Apply the label in the location shown and smooth the label from the center out.
7. Close the driver's side door.

Dealer Responsibility – For USA & Export (USA States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

Dealer Responsibility – All

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this recall must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

F/CMVSS Noncompliance Recall

N242474600 Missing Certification Label



Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory you must take the steps necessary to ensure the program correction has been made before selling the vehicle. In addition, for vehicles entering your facility for service, you are required to ensure the customer is aware of the open recall and make every reasonable effort to implement the program correction as set forth in this bulletin prior to releasing the vehicle.

Dealer Reports – For USA & Export

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this recall. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall may be a violation of law in several states.

Courtesy Transportation – For USA & Canada

Courtesy transportation is available for customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual for courtesy transportation program details.

Customer Notification

USA & Canada - General Motors will notify customers of this recall on their vehicle (see copy of sample customer letter included with this bulletin).

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**



IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN: _____

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that certain 2024 model year Buick Envision vehicles fail to conform to Federal Motor Vehicle Safety Standard No. 110 "Tire Selection and Rims." As a result, GM is conducting a recall. We apologize for this inconvenience. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in GM recall N242474600.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

These vehicles are missing the label that provides the tire size and cold tire pressure for the front and rear tires and the gross vehicle weight ratings. Without tire and gross vehicle weight rating information available on the label, there is a risk that customers may overinflate or underinflate their tires or exceed the recommended weight ratings, increasing the risk of a crash.

What will we do?

Your GM dealer will install the missing label. Additionally, the Vehicle Emissions Control Information (VECI) label may not have been installed, as required by EPA regulations. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 30 minutes.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

Do you have questions?

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

For the hearing or speech impaired, please contact our Customer Assistance Center using the Telecommunication Relay Service by dialing 711 then providing the appropriate Customer Assistance Center number for your vehicle.

Division	Number
Buick	1-800-521-7300
Puerto Rico – English	1-866-467-9700
Puerto Rico – Español	1-866-467-9700
Virgin Islands	1-866-467-9700

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.nhtsa.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 24V710.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

F/CMVSS Noncompliance Recall
N242474600 Missing Certification Label



Regina A. Carto
Vice President
Global Product Safety and Systems

GM Recall: N242474600