The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name : Chicco USA, Inc. Submission Date : APR 09, 2025 NHTSA Recall No. : 25C-005 Manufacturer Recall No. : NR

Manufacturer Information :

Manufacturer Name : Chicco USA, Inc. Address : 1826 William Penn Way LANCASTER PA 17601 Company phone : 717-735-6200

Child Restraint Information :

Make 1:	Chicco
Model :	MyFit Zip Air Harness and Booster Child Restraint
Seat Type :	OTHER
Model No. :	See Descr. Info
Platform Name / No. :	NR
Brand Name :	NR
Descriptive Information :	 The recall population was determined using dynamic crash testing results carried out during NHTSA annual conformity testing in MAR 2021 and retested in FEB 2024 at Calspan. Both tested MyFit Zip Air Models were confirmed to have a manufacturing date of SEP 2020. Therefore the recall population will include all MyFit Zip Air Models manufactured from SEP 2020 to AUG 2024 (end of production). The recalled Child Restraint System has a different Lower Anchor and Tether for Children (LATCH) anchors and a different fabric seat pad design than the non-recalled Child Restraint Systems. Models: 07079561970070, 04079561190070 (Total Potential Qty 30,984),
Production Dates :	SEP 01, 2020 - AUG 31, 2024



25C-005

Population :

Number of potentially involved : 30,984 Estimated percentage with defect : 100 %

Part 573 Safety Recall Report

25C-005

Description of Noncompliance :

Description of the	When tested according to the requirements of FMVSS 213 S5.1.2(b) the HIII 3		
Noncompliance :	Year Old Test Dummy can experience a chest resultant acceleration greater		
	than the 60g limit in the cumulative duration of 3 milliseconds when in the		
	following configuration:		
	a) Type I (Lap Belt Only)		
	b) NO Tether (not installed per manufacturer's recommendation)		
	c) Forward Face Harness		
	d) Recline position 3 & 4 (most upright)		
FMVSS 1 :	213 - Child restraint systems		
FMVSS 2 :	NR		
Description of the Safety Risk :	In the event of a crash, a child restrained using Type I (lap belt only) without top tether could be at an increased risk of chest injury. No such injuries or deaths have been reported to Artsana USA, Inc. or to the best of our knowledge reported to the NHTSA for this use mode.		
Description of the Cause :	Possible contributing factors currently being evaluated include: a) Storage location of "Super Cinch" LATCH directly under dummy when installing the CRS without LATCH.		
	b) Dummy placement due to the unique fabric seat pad design of this model.c) Not following user guide instructions "ALWAYS use the top tether strap on this Child Restraint when used in harness mode"		
Identification of Any Warning that can Occur :	There are not any known warnings.		

Involved Components :

Component Name : NR

Component Description : NR

Component Part Number: NR

Supplier Identification :

Component Manufacturer

Name : Artsana USA, Inc.

Address : 1826 William Penn Way Lancaster 17601

Country: NR

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Re	ecall Report	25C-005	Page 3
Chronology : 3/19/2021 - NHTSA Compliance To 2/02/2024 - NHTSA Compliance To	1		2
Description of Remedy :			
Description of Remedy Program	 Artsana USA, Inc. is currently example. a) Notice to retailers and consumption b) Amended Instructions included c) Additional components 		ing:
How Remedy Component Differ from Recalled Component	0 0	between the remedy and recalled u	nits is to
Identify How/When Recall Condition was Corrected in Production		peing manufactured as of August 2	024.
Recall Schedule :			
Description of Recall Schedule			
Planned Dealer Notification Date Planned Owner Notification Date			
Purchaser Information :			
The following manufacturers purch installation in new motor vehicles of	-		
Name : NR			
Address : NR			
NR Country : NR			
Country: NR			

Country : NR Company Phone : NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573