### The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

Manufacturer Name :	Ford Motor Company
Submission Date :	JAN 17, 2025
<b>NHTSA Recall No. :</b>	25V-019
Manufacturer Recall No. :	25S02

### Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

### Vehicle Information :

Vehicle 1:	2021-2023 Ford B	ronco Sport		
Vehicle Type :	LIGHT VEHICLES			
Body Style :	ALL			
Power Train :	NR			
Descriptive Information :	Ford's team reviewed supplier process and maintenance records to determine the population of affected parts. The Ford process is capable of tracing 12V battery production to the vehicle in which the 12V battery is installed. The suspect 12V batteries were introduced into production on February 5, 2020, and removed from production on October 20, 2022. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service			
	Information System			
Production Dates :	FEB 05, 2020 - OC'	T 20, 2022		
Production Dates : VIN Range 1 : F			d: NR	□ Not sequential



Number of potentially involved : 272,817

Estimated percentage with defect : 1%

**Population :** 

## 25V-019

# Part 573 Safety Recall Report

25V-019

	023 Ford Maverick		
Power Train :GASDescriptive Information :Ford's team reviewed supplier process and maintenance records to determine the population of affected parts. The Ford process is capable of tracing 12V battery production to the vehicle in which the 12V battery is installed. The suspect 12V batteries were introduced into production on February 5, 2020, and removed from production on October 20, 2022.These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database			
	·		
: Begin :	NR	End: NR	☐ Not sequential
tha whi acco S 1 : NR	t is unable to restar le coming to a stop	t after an auto stop/ at low speed. Either	′start event or experience a stall c of these conditions may be
	<b>C</b>		
use : The clos ulti due to t det	e supplier's cast-on se to strap walls. The mately battery failu to weld temperatu he target position. I ect certain electrica	strap (COS) process is leads to cracked ( ires. Additionally, w res being too high o Prior software relea I signatures present	positioned battery plate lugs too COSs, open battery cells and eak tombstone welds are occurring r weld position being offset relative sed as part of FSA 24S24 is unable to t on failed batteries and/or failed to
ning Nor	-	, q,	
	<ul> <li>ALL</li> <li>GAS</li> <li>Ford's popular product batteriar product batteriar product batteriar product for this act line (1-specific Inform)</li> <li>FEB 03</li> <li>Begin :</li> <li>FEB 03</li> <li>Begin :</li> <li>FEB 03</li> <li>S 1 : NR</li> <li>S 2 : NR</li> <li>isk : A locut is a close of the close of</li></ul>	<ul> <li>GAS</li> <li>Ford's team reviewed suppopulation of affected part production to the vehicle i batteries were introduced production on October 20. These vehicles are not prothis action to specific vehicline (1-866-436-7332) or specific information regart Information System (OASI : FEB 03, 2021 - OCT 20, 20 : Begin : NR</li> <li>FEB 03, 2021 - OCT 20, 20 : Begin : NR</li> <li>ect : In affected vehicles, the on-strap failures, which driving. If the battery sthat is unable to restart while coming to a stop accompanied by a loss</li> <li>S 1 : NR</li> <li>S 2 : NR</li> <li>isk : A loss of motive power use : The supplier's cast-on close to strap walls. The ultimately battery failed due to weld temperatu to the target position. I detect certain electricat disable stop/start function.</li> </ul>	<ul> <li>ALL</li> <li>GAS</li> <li>Ford's team reviewed supplier process and mapopulation of affected parts. The Ford process production to the vehicle in which the 12V bat batteries were introduced into production on production on October 20, 2022.</li> <li>These vehicles are not produced in VIN order. this action to specific vehicles can best be obtaline (1-866-436-7332) or by contacting a loca specific information regarding the vehicles from Information System (OASIS) database.</li> <li>FEB 03, 2021 - OCT 20, 2022</li> <li>Begin: NR End: NR</li> <li>Fed: NR</li> <li>Altaria and the battery suddenly degrades d that is unable to restart after an auto stop/while coming to a stop at low speed. Either accompanied by a loss of 12-volt accessori S1: NR</li> <li>S2: NR</li> <li>S2: NR</li> <li>S4 loss of motive power can increase the risise: The supplier's cast-on strap (COS) process close to strap walls. This leads to cracked C ultimately battery failures. Additionally, w due to weld temperatures being too high o to the target position. Prior software releated detect certain electrical signatures presented disable stop/start functionality quickly enditionality quickly endit</li></ul>

# Part 573 Safety Recall Report

25V-019

Component Name 1 :12V BatteryComponent Description :Battery AssemblyComponent Part Number :LX6T-10655-f

### **Supplier Identification :**

#### **Component Manufacturer**

Name :Camel BatteryAddress :No. 4 Zhuiri RoadXiang Yang Foreign States 441003Country :China

#### **Chronology** :

On September 24, 2024, Ford received an informal inquiry from the National Highway Traffic Safety Administration (NHTSA) Office of Defect Investigation (ODI) related to 19 Vehicle Owner Questionnaires (VOQs) alleging a Loss Of Motive Power (LOMP) after receiving a remedy for Field Service Action (FSA) 24S24. Ford's Automotive Safety Office (ASO) and Low Voltage Power Supply team reviewed the VOQs and based on the team's findings, this concern was introduced to Ford's Critical Concern Review Group (CCRG) on October 29, 2024.

On November 15, 2024, NHTSA ODI opened Recall Query RQ24-014 into this concern.

From November 2024 through January 2025, the Low Voltage Power Supply team conducted an engineering evaluation of several field returned 12-volt batteries from the suspect population. Vehicles recalled under 24S24 were produced with Enhanced Flooded Batteries (EFB) supplied by two different suppliers: Camel and Clarios. This investigation identified internal manufacturing defects in the Camel EFB batteries, including failures of the battery's Cast On Strap (COS) and internal weld failures, both of which can lead to open circuits. The customer claims and warranty returns related to alleged LOMP failures demonstrate a higher concentration in warmer weather states.

As of October 29, 2024, 234 out of 238 allegations of LOMP post-24S24 were vehicles produced with Camel EFB batteries. Ford has not identified any Clarios EFB batteries with a similar failure mode to what has been observed in the Camel EFB.

As of November 20, 2024, Ford is not aware of any accidents, fires, or injuries attributed to this condition.

On January 10, 2025, Ford's Field Review Committee reviewed the concern and approved a field action.

The information contained in this report was submitted pursuant to 49 CFR §573

### **Description of Remedy :**

Description of Remedy Program :	Owners will be notified by mail and instructed to take their vehicle to a
	Ford or Lincoln dealer to have their vehicle inspected for the presence of a Ford Absorbed Glass Mat (AGM) 12V battery. If there is not a Ford AGM
	battery present, one will be installed. There will be no charge for this service.
	Ford provided the general reimbursement plan for the cost of remedies
	paid for by vehicle
	owners prior to notification of a safety recall in May 2023. Owners who have paid to have these repairs completed at their own expense may be
	eligible for reimbursement, in accordance with the recall reimbursement plan on file with NHTSA.
How Remedy Component Differs	The replacement 12V battery BAGM-48H6-760 is absent the internal
	defects present in the Camel batteries.
Identify How/When Recall Condition was Corrected in Production :	Not required per 49 Part 573.

### **Recall Schedule :**

Description of Recall Schedule :	Notification to dealers is expected to occur on January 21, 2025. Mailing
	of owner notification letters is expected to begin February 3, 2025 and is
	expected to be completed by February 7, 2025.
Planned Dealer Notification Date :	JAN 21, 2025 - JAN 21, 2025
Planned Owner Notification Date :	FEB 03, 2025 - FEB 07, 2025

\* NR - Not Reported