Part 573 Safety Recall Report

Manufacturer Name :Toyota Motor Engineering & ManufacturingSubmission Date :JAN 22, 2025NHTSA Recall No. :25V-028Manufacturer Recall No. :25TA01 / 25LA01



Number of potentially involved : 858

Estimated percentage with defect : 1%

Population :

25V-028

Manufacturer Information :

Manufacturer Name : Toyota Motor Engineering & Manufacturing Address : 6565 Headquarters Drive Plano TX 75024 Company phone : 1-800-331-4331

Vehicle Information :

Vehicle 1:	2018-2018 Toyo	a Camry		
Vehicle Type :				
Body Style :				
Power Train :	NR			
Descriptive Information :	vehicles in this ra This recall applie containing impel These vehicles co density and conta or (2) a pump im periods of time. aforementioned As discussed furt original report [2 the original vehic percentage of vel will lead to a veh such as the speci conditions descri requires an integ	nge were sold s to certain ve- ers produced ntain fuel pun in either (1) a peller that was vehicles with f conditions are her below, all 0V012] as inte le populations nicles to actual icle stall while ic production bed in section er value be ent	in the U.S. hicles with speci- during specific p ps that were pro- pump impeller of sexposed to pro- uel pumps that v not included. vehicles in this re- ended due to data s. Toyota is unab ly contain the de driving at higher condition of fuel 5. However, as t tered, Toyota has	ove production period range, not all ic fuel pumps supplied by Denso, eriods under specific circumstances. duced with impellers of lower of a type with lower surface strength fuction solvent drying for longer were not produced under the port had not been included in the processing errors when identifying e to provide an estimate of the fect. Whether the issue in each case speeds depends on many variables, pump impeller and vehicle operating he NHTSA manufacturer portal entered the value "1" in response to is report, "1" means "unknown".
Production Dates :	-	-		•
VIN Range 1:1		NR	End: NR	☐ Not sequential

Part 573 Safety Recall Report

25V-028

Page 2

Vehicle 2:	2019-2019 Lexus NX300		
Vehicle Type :			
Body Style :			
Power Train :	NR		
Descriptive Information :	vehicles in this range wer This recall applies to cert containing impellers proo These vehicles contain fu density and contain either or (2) a pump impeller the periods of time. Vehicles aforementioned condition As discussed further belo original report [20V012] the original vehicle popul percentage of vehicles to will lead to a vehicle stall such as the specific produ conditions described in s	re sold in the U.S. cain vehicles with specific fue duced during specific period el pumps that were produce er (1) a pump impeller of a ty nat was exposed to productio with fuel pumps that were r ns are not included. ow, all vehicles in this report as intended due to data pro- lations. Toyota is unable to p actually contain the defect. while driving at higher spec- uction condition of fuel pump ection 5. However, as the NI	pe with lower surface strength on solvent drying for longer not produced under the had not been included in the cessing errors when identifying provide an estimate of the Whether the issue in each case eds depends on many variables p impeller and vehicle operatin HTSA manufacturer portal
		l. For the purpose of this re	red the value "1" in response to port. "1" means "unknown".
Production Dates	APR 22, 2019 - APR 22, 2		r,
Production Dates	111 10 22, 2010 111 10 22, 2	010	

Part 573 Safety Recall Report

25V-028

Page 3

Vehicle 3:	2019-2019 Lexus RX350)L	
Vehicle Type :			
Body Style :			
Power Train :	NR		
Descriptive information .	vehicles in this range we This recall applies to cer containing impellers pro These vehicles contain f density and contain eith or (2) a pump impeller t periods of time. Vehicle aforementioned condition As discussed further bell original report [20V012 the original vehicle popu percentage of vehicles to will lead to a vehicle stat such as the specific prod conditions described in requires an integer value	tain vehicles with specific fuel oduced during specific periods uel pumps that were produced er (1) a pump impeller of a typ hat was exposed to production s with fuel pumps that were no	l pumps supplied by Denso, s under specific circumstance d with impellers of lower pe with lower surface strengt n solvent drying for longer ot produced under the nad not been included in the essing errors when identifyin rovide an estimate of the Whether the issue in each cas ds depends on many variable impeller and vehicle operati (TSA manufacturer portal red the value "1" in response
Production Dates .	AUG 02, 2019 - AUG 02,		
VIN Range 1:		End: NR	Not sequentia
escription of Defect :			
Description of the Defe	the fuel tank, that surpumps may include in density. If these imp (2) of a different type periods of time, high excessive fuel absorp deformation. In som sufficient interference	are equipped with a low-press pplies fuel pressure to the fuel mpellers which have been ma ellers are also (1) of a type wi e but were exposed to product er levels of surface cracking m otion may occur, resulting in ir e cases, the impeller may defo re with the fuel pump body to An inoperative fuel pump due	l injection system. These fuel nufactured with lower th lower surface strength or tion solvent drying for longer hay occur. In this condition, ncreased impeller orm to a point that creates cause the fuel pump to

result in illumination of check engine and master warning indicators, rough engine running, engine no start and/or vehicle stall while driving at low speed. However, in rare instances, vehicle stall could occur while driving at higher speeds, increasing the risk of a crash.

- FMVSS 1: NR
- FMVSS 2: NR

Description of the Safety Risk : An inoperative fuel pump due to these conditions could result in illumination

art 573 Safety Recall Report	25V-028	Page
no start and/or vehicle stall while di	indicators, rough engine running, eng riving at low speed. However, in rare while driving at higher speeds, increas	
Description of the Cause : NR		
Identification of Any Warning NR that can Occur :		
Involved Components :		
Component Name 1: Pump Assy, Fuel w/Filter		
Component Description : Fuel Pump Assembly		
Component Part Number : 23220-25020		
Component Name 2 : Pump Assy, Fuel		
Component Description : Fuel Pump Assembly		
Component Part Number : 23221-36030		
Component Name 3: Pump Assy, Fuel		
Component Description : Fuel Pump Assembly		
Component Part Number : 23221-31130		
Supplier Identification : Component Manufacturer		
Name : DENSO CORPORATION		
Address : 1-1, Showa-cho		
Kariya-city Aichi-pref. Foreign States 448-8661		
Country : Japan		
Chronology :		
January 13, 2020		
The information contained in this report was submit	ted pursuant to 49 CFR §573	

25V-028

Page 5

Toyota filed a Part 573 Defect Information Report (20V012) about the above-described condition. Subsequently, amendments were filed.

May 2024 - August 2024

In late May 2024, Toyota began to receive field technical reports from the Japan market indicating that the engine would not start. The dealers inspected the vehicles and found the low-pressure fuel pumps malfunctioned. The fuel pumps were recovered and shipped to the fuel pump supplier for further investigation. The supplier found that these fuel pumps should have been in the scope of the original recall and reported this to Toyota. Toyota then began investigating why these vehicles were not included in the original recall.

September 2024 – January 2025

In September 2024, Toyota found that certain fuel tank assembly part numbers had not been included due to incorrect production history information from the supplier. During the course of this investigation, Toyota discovered additional errors in the identification of the involved vehicles when Toyota processed production records to identify affected vehicles that should have been included in the original recall:

failing to understand that certain affected fuel tanks had been imported into Japan for use in vehicles to be sold in the U.S.; and

the use of an incorrect date to identify certain vehicle production information.

Based on the above findings, Toyota concluded that certain Toyota and Lexus vehicles may not have been included in the original recall.

January 15, 2025 Based on the results of the above investigation, Toyota decided to conduct a voluntary safety recall campaign.

As of January 15, 2025, based on a diligent review of records, Toyota's best engineering judgment is that there are zero Toyota Field Technical Reports and two warranty claims that have been received from U.S. sources that relate or may relate to this condition in the involved vehicles, and which were considered in the decision to submit this report.

Description of Remedy :

Description of Remedy Program :	All known owners of the subject vehicles will be notified to return their vehicles to a Toyota and Lexus dealer. For all involved vehicles, the dealers will replace the fuel pump assembly with an improved one. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan.
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule :	Notifications to owners of the affected vehicles will occur by March 23, 2025. A copy of the draft owner notification will be submitted as soon as it is available. Notifications to distributors/dealers will be sent on January 22, 2025. Copies of dealer communications will be submitted as they are issued.
Planned Dealer Notification Date :	5
Planned Owner Notification Date :	MAR 09, 2025 - MAR 23, 2025

* NR - Not Reported