Part 573 Safety Recall Report

Manufacturer Name :	Ford Motor Company
Submission Date :	FEB 10, 2025
NHTSA Recall No. :	25V-048
Manufacturer Recall No. :	25S05
	20000

Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

Vehicle Information :		
Vehicle 1:	2021-2021 Ford Expedition	
Vehicle Type :	LIGHT VEHICLES	
Body Style :		
Power Train :	NR	
Descriptive Information :	Affected vehicles are equipped with rear view cameras and were produced betwee $01/04/2021$ and $03/31/2021$.	een
	These vehicles are not produced in VIN order. Information as to the applicability this action to specific vehicles can best be obtained by either calling Ford's toll-fre line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can ob specific information regarding the vehicles from the Ford On-line Automotive Ser Information System (OASIS) database. 21,088 Expedition vehicles are affected.	ee otain
	JAN 04, 2021 - MAR 31, 2021	
VIN Range 1: I	Begin :NREnd :NRNot sequent	itial



Number of potentially involved : 91,580

Estimated percentage with defect : 2 %

Population :

25V-048

Part 573 Safety Recall Report

25V- (048
---------------	-----

FMVSS	ct : The real 1 : NR 2 : NR	r-view camera i	nay exhibit an intermittent	or persistent loss of image.
Production Dates : VIN Range 1 :	OCT 01, 202	sair vehicles aro 20 - AUG 31, 20 NR		🗌 Not sequentia
These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtai specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.				
Power Train : Descriptive Information :	Affected ve	hicles are equip 0 and 08/31/2	-	s and were produced betweer
Vehicle Type : Body Style :		ICLES		
C C	0	Lincoln Corsaiı		
Production Dates : VIN Range 1 :		21 - MAY 30, 20 NR	21 End: NR	Not sequentia
	this action t line (1-866 specific info Information 59,365 Sup	to specific vehic -436-7332) or l ormation regard n System (OASI er Duty vehicles	les can best be obtained by by contacting a local Ford or ling the vehicles from the Fo 5) database. 5 are affected.	ation as to the applicability of either calling Ford's toll-free [•] Lincoln dealer who can obta ord On-line Automotive Servi
Descriptive mormation.	02/01/202	1 and $05/30/2$	Ĵ21.	s and were produced betweer
Power Train :		hiolog ono oquir	nod with yoon view comono	and wore produced between
Vehicle Type : Body Style :	LIGHT VEH	ICLES		

Part 573 Safety Recall Report

Description of the Cause :	The specific root cause of the concern has not yet been determined. Based on
	minimal rear-view camera repeat repairs, Ford believes that the main causal
	factor is within this specific camera.
Identification of Any Warning that can Occur :	None
that can o cour .	

Involved Components :

Component Name 1:	CMR RR FAC VEH DTCT
Component Description :	Ford Expedition Rear Analog Camera
Component Part Number :	NL1T-19G490-AB

Component Name 2 :	CMR RR FAC VEH DTCT
Component Description :	Ford Super Duty Rear Analog Camera
Component Part Number :	HC3T-19G490-BC

Component Name 3 :	CMR RR FAC VEH DTCT
Component Description :	Lincoln Corsair Rear Analog Camera
Component Part Number :	LJ7T-19G490-AE

Supplier Identification :

Component Manufacturer

Name : Magna Address : 2050 Auburn Road Auburn Hills Michigan 48326 Country : United States

Chronology:

On October 1, 2024, an issue pertaining to rearview camera systems pertaining to certain 2021 Expedition, 2021-2022 Super Duty, and 2020–2022 Corsair vehicles equipped with Magna Analog cameras was brought to Ford's Critical Concern Review Group (CCRG) for review. This population was identified during a broader CCRG investigation that identified elevated warranty rates during specific production windows for these

The information contained in this report was submitted pursuant to 49 CFR §573

vehicle lines.

From October through December 2024, Ford compared design differences between the suspect vehicle lines and others that utilize similar cameras supplied by Magna, including attachment, wiring, SYNC software, and Accessory Protocol Interface Module (APIM) differences. This review did not identify any contributing factors. Ford obtained and inspected vehicles from the suspect period in an effort to better understand the vehicle's rear view camera performance and did not identify any specific causes. Additionally, Ford conducted statistical analysis to understand differences between the suspect period and the remaining population. This analysis confirmed that there is a statistically significant difference in field performance for the suspect population despite there being an undetermined cause.

As of January 17, 2025, Ford is aware of 6 VOQs related to this concern in the included population.

Ford is not aware of any reports of accidents or injury related to this condition.

On January 24, 2025, Ford's Field Review Committee reviewed the concern and approved a field action.

On February 7, 2025, Ford's Field Review Committee approved an amendment to include certain 2021 – 2022 Super Duty vehicles models (F-250, F-350, F-450, F-550, and F-600 models) equipped with rearview camera and prep kit.

Description of Remedy :

Description of Remedy Program :	The remedy is under development. When the remedy is available, owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have the remedy performed. There will be no charge for this service.
	Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2023. Owners who have paid to have these repairs completed at their own expense may be eligible for reimbursement, in accordance with the recall reimbursement plan on file with NHTSA.
How Remedy Component Differs from Recalled Component :	The remedy is under development.
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule : Notification to dealers is expected to occur on February 17, 2025.

The information contained in this report was submitted pursuant to 49 CFR §573

	Mailing of owner notification letters is expected to begin March 3, 2025
	and is expected to be completed by March 3, 2025.
Planned Dealer Notification Date :	FEB 17, 2025 - FEB 17, 2025
Planned Owner Notification Date :	MAR 03, 2025 ⁻ MAR 03, 2025

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573