



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V058

**Manufacturer Name:** Toyota Motor Engineering & Manufacturing

**Submission Date:** Jul 02, 2025

**NHTSA Recall No.:** 25V058

**Manufacturer Recall No.:** 25TB04 / 25TA04

### Manufacturer Information

### Population

**Manufacturer Name:** Toyota Motor Engineering & Manufacturing

**Address:** 6565 Headquarters Drive  
Plano TX, 75024

**Total number of potentially involved:** 221,846

**Estimated percentage with defect:** 1%

### Vehicle Information

**Vehicle 1:** 2024-2025 Toyota Tacoma

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Dec 14, 2023 - Jan 17, 2025

**Number of potentially involved:** 221,846

**Descriptive Information:**

(1) Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. (2) This recall only applies to the aforementioned Tacoma vehicles equipped with 16-inch brakes. MY2024-2025 Tacoma vehicles equipped with 17-inch brakes are of a different brake system design and are not affected by this issue. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to brake fluid loss while driving depends on vehicle operating conditions described in section 5. However, as the NHTSA manufacturer portal requires an integer value be entered, Toyota has entered the value "1" in response to this question in the portal. For the purpose of this report, "1" means "unknown".

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

The subject vehicles are equipped with 16-inch brake systems where the brake hoses, attached to rear brake calipers, transfer brake fluid under hydraulic pressure to the calipers for braking. These components are positioned inside the rear 17-inch or 18-inch Toyota wheels. The brake calipers and wheels have clearance between the brake hoses and wheels such that, if mud and dirt build up on the interior of the wheels when operating under certain off-road or muddy road conditions, this mud/dirt can contact the brake hoses. Over time, this may damage and wear through the brake hoses, causing a

# Part 573 Safety Recall Report

## 25V058

brake fluid leak. This can lead to a reduction of brake performance and increase in brake stopping distance, which increases the risk of a crash.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

Over time, this may damage and wear through the brake hoses, causing a brake fluid leak. This can lead to a reduction of brake performance and increase in brake stopping distance, which increases the risk of a crash.

**Description of the cause:**

**Identification of any warning that can occur:**

### Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:** HC Queretaro, S.A. de C.V

**Address:** Circuito El Marques Norte 62 y 76  
El Marqués  
Queretaro Foreign States, 76246

**Country:** Mexico

### Involved Components

**Component Name 1:** Hose, Flexible, RH

**Component Description:** Rear Brake Hose

**Component Part Number:** 90947-A2128

**Component Name 2:** Hose, Flexible, LH

**Component Description:** Rear Brake Hose

**Component Part Number:** 90947-A2129

# Part 573 Safety Recall Report

**25V058**

## Chronology

Please see the attached amended Part 573 Defect Information Report for the full chronology.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

All owners of the subject vehicles will be notified to return their vehicles to a Toyota dealer. For all involved vehicles, the dealers will replace both rear brake hoses with improved ones. As the owner notification letters will be mailed out well within the active period of the Toyota New Vehicle Limited Warranty ("Warranty"), all involved vehicle owners for this recall would have been provided a repair at no cost under Toyota's Warranty. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan.

**How remedy component differs from recalled component:**

**Identify how/when recall condition was corrected in production:**

## Reimbursement Plan

**Description of reimbursement program:**

**Period of reimbursement:**

**Costs to be reimbursed:**

**Address for reimbursement claims:**

## Recall Schedule

**Part 573 Safety Recall Report****25V058****Description of recall schedule:**

Notifications to owners of the affected 4-wheel drive vehicles with 16-inch brakes and 17-inch Toyota wheels were sent on March 7, 2025.

Notifications to owners of the affected 4-wheel drive vehicles with 16-inch brakes and 18-inch Toyota wheels and 2-wheel drive vehicles with 16-inch brakes and either 17-inch or 18-inch Toyota wheels will occur by August 31, 2025. A copy of the draft owner notification will be submitted as soon as it is available.

Notifications to distributors/dealers of the affected 4-wheel drive vehicles with 16-inch brakes and 17-inch Toyota wheels were sent on February 6, 2025.

Notifications to distributors/dealers of the affected 4-wheel drive vehicles with 16-inch brakes and 18-inch Toyota wheels and 2-wheel drive vehicles with 16-inch brakes and either 17-inch or 18-inch Toyota wheels will be sent on July 2, 2025. Copies of dealer communications will be submitted as they are issued.

**Planned Dealer Notification Date:** Jul 02, 2025 - Jul 02, 2025

No Dealers

**Planned Interim Owner Notification Date:**

No Owners

**Planned Remedy Owner Notification Date:** Aug 17, 2025 - Aug 31, 2025

Phased Recall

**Date when VIN will be searchable:**